## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVA	ATION DIVISION		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-24665	
<u>DISTRICT II</u>	,		5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X
<u>DISTRICT III</u>			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410	TOTAL TOTAL ON THE CONTROL ON THE CO	T 6	7. Lease Name or Unit Agreement	Nama
SUNDRY NOTICES AND REPORTS ON WELLS				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			NORTH HOBBS (G/SA) UNIT	
1. Type of Well:			8. Well No. 341	
Oil Well X Gas Well Other				
2. Name of Operator			9. OGRID No. 157984	
Occidental Permian Ltd.  3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, NI	M 88240 505/397-82	200		110225 (0/511)
4. Well Location				
Unit Letter O : 990	Feet From The SOUTH	1650 Fee	et From The EAST	Line
Section 30	Township 18-S	Range 38-	E NMPM	LEA County
	11. Elevation (Show whether DF, RKB, 3646 GL	RT GR, etc.)		
	3040 GL			
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AÑD ABANDON	REMEDIAL WORK	ALTERING (	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPN	S. PLUG & AB	ANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMENT	I JOB	
OTHER: Add perfs and acidize		OTHER:		
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)				
SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
-			general and the second	are ex
1. Pull equipment.			,	•
<ul><li>2. Perforate and acid stimulate.</li><li>3. Run production equipment.</li></ul>				
5. Tun production equipment			20	~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~
			60	
			· · · · · · · · · · · · · · · · · · ·	1.
			0	
				* <b>4</b>
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or				
closed according to NMOCD guide lines	, a general permit	or an (attached) alternative	e OCD-approved plan	· ·
SIGNATURE		TITLE Engineering Ad	visor DATE	3-17-05
TYPE OR PRINT NAME David Nelson	E-mail address:		TELEPHONE NO.	505-397-8200
For State Use Only	1.1.			
APPROVED BY  CONDITIONS OF APPROVAL IF ANY:  OC FIELD REPRESENTATIVE II/STAFF MANAGER				
CONDITIONS OF APPROVAL IF ANY:	<b>-</b>			MAR 2 3 2005