## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	N TRIPLICATE OIL CONSERVATION DIVISION				
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO. 30-025-29063		
DISTRICT II	Sainte 1 c, 1011 07303		5. Indicate Type of Lease		
1301 W. Grand Ave, Artesia, NM 88210			STATE	FEE X	
DISTRICT III			6. State Oil & Gas Lease No.		
1000 Rio Brazos Rd, Aztec, NM 87410					
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)			NORTH HOBBS (G/SA) UNIT		
Type of Well:     Oil Well	Oil Well Gas Well Other Wtr Injector			8. Well No. 112	
Name of Operator     Occidental Permian Ltd.			9. OGRID No. 157984		
3. Address of Operator			10. Pool name or Wildcat	HOBBS (G/SA)	
1017 W. Stanolind Rd., HOBBS	s, NM 88240 505/397-82	200			
4. Well Location					
Unit Letter D : 200	Feet From The NORTH		et From The WEST	Line	
Section 30	Township 18-S	Range 38-I	E NMPM	LEA County	
	11. Elevation (Show whether DF, RKB, and 3657 GL	RT GR, etc.)			
Pit or Below-grade Tank Application	or Closure				
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water					
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material					
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING (	CASING	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OPNS	S. PLUG & AB	ANDONMENT	
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMENT	JOB		
OTHER: Squeeze and stimulate		OTHER:			
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
1. Pull equipment and squeeze 4117-29.					
2. 3. Acid stimulate. 4. Run CO2 injection equipment.					
4. Kun CO2 injection equipment.					
Establish injector as produced gas injector under section 18, page 12 of Division Order R-6199-B.					
			0,	*	
I harshy cartify that the information shows is	true and complete to the best of my knowledge on	d haliaf I fouther contifue that any mit	t or helow grade tout has been/will be	constructed on	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guilelines , a general permit or an (attached) alternative OCD-approved plan					
SIGNATURE	11 The	TITLE Engineering Adv	visor DATE	3-14-05	
TYPE OR PRINT NAME David No	elson E-mail address:		TELEPHONE NO.	505-397-8200	
APPROVED BY  CONDITIONS OF APPROVAL IF ANY:  OC FIELD REPRESENTATIVE WSTAFF MANAGER  MAR 2 3 2005					
CONDITIONS OF APPROVAL IF ANY					
U	A OC LIPHE		MAR 2 3 2005		