

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB No. 1004-0137  
Expires: March 31, 2007

**SUNDRY NOTICES AND REPORTS ON WELLS**

*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

**SUBMIT IN TRIPLICATE- Other instructions on reverse side.**

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
Arch Petroleum Inc.

3a. Address  
P.O. Box 10340, Midland, TX 79702

3b. Phone No. (include area code)  
432-685-8100

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

560' FNL & 510' FWL, Section 27, T23S, R37E

5. Lease Serial No.

NMLC-030187

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No

C. E. Lamunyon #24

9. API Well No.

30-025-22415

10. Field and Pool, or Exploratory Area

Langlie Mattix 7 Rvrs Q Grbg

11. County or Parish, State

Lea County, NM

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input checked="" type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Arch Petroleum Inc. request permission to plug back the above captioned well from the Blinbry to the Langlie Mattix based on the following procedure:

1. Dump 50' cmt on CIBP @ 5350'.
2. Load & test csg to 2000#.
3. Perf Langlie Mattix 3350'-3600'.
4. Acidize.
5. Frac as directed
6. Put well on production for evaluation.

**DENIED**

RECEIVED  
Hobbs  
OCD

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Cathy Wright

Title Sr Eng Tech

Signature

*Cathy Wright*

Date 03/17/05

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

**DENIED**

(ORIG. SGD.) DAVID R. GLAD

**PETROLEUM ENGINEER**

MAR 22 2005

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

**Denied! Well Has Not Produced Since 05/1998 And Has Been SI/TA Without Approval Since 08/22/2002. A Notice Of Intent To Plug And Abandon Well Was Approved 02/28/2005. You Must Plug This Well By 05/28/2005!**

for any person knowingly and willfully to make to any department or agency of the United States any matter within its jurisdiction.

GWW