

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator

BURLINGTON

RESOURCES OIL & GAS COMPANY LP

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M

1060' FSL, 1702' FEL, Sec. 28, T-29-N, R-11-W, NMPM

5. Lease Number
NMNM-020982

6. If Indian, All. or
Tribe Name

7. Unit Agreement Name

Well Name & Number
Mangum #4E

8. API Well No.
30-045-24128

9. Field and Pool
Basin Fruitland Coal/
Otero Cha/Basin DK

10. County and State
San Juan Co, NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment

Type of Action

☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☒ Other - Temporarily abandon
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut off
☐ Conversion to Injection

13. Describe Proposed or Completed Operations

2-17-05 MIRU. SDON.
2-18-05 ND WH. NU BOP. Release Model "R" pkr. TOOH w/2 3/8" tbg & pkr. TIH, tag up @ 6230'. Blow well & CO to 6250'. TOOH. SD for weekend.
2-21-05 TIH, tag up @ 6252'. Attempt to clean fill. TOOH. TIH w/4 3/4" bit to 6252'. Establish circ. CO to PBTD @ 6267'. Circ hole clean. Pump 500 gal 15% HCl. Blow well & CO. SDON.
2-22-05 Blow well & CO. TOOH w/bit. TIH w/standing valve & tbg. PT tbg to 1000 psi, for 15 min, OK. Retrieve standing valve. Blow well & CO. TIH w/200 jts 2 3/8" 4.7# J-55 EUE tbg, landed @ 6219'. (SN @ 6218'). Set pkr @ 2796'. ND BOP. NU WH. Blow well & CO. SDON.
2-23-05 Blow well & CO. SDON.
2-24-05 (Verbal approval from Matt Halbert, BLM to temporarily abandon wellbore & wait for recompletion of Fruitland Coal according to approved sundry dated 6-28-04). Blow well & CO. ND WH. NU BOP. TIH w/gauge ring to 6250'. TOOH. TIH w/CIBP, set @ 6225'. TOOH. TIH w/pkr, set @ 6090'. Blow well & CO. SDON.
2-25-05 Blow well & CO. Release pkr, TOOH. TIH w/CIBP, set @ 6072'. TOOH. TIH, load tbg w/wtr. Plug #1: pump 17 sx Type III cmt inside csg above CIBP @ 5890-6072' to plug Dakota. TOOH to 3000'. SD for weekend.

Continued on back

14. I hereby certify that the foregoing is true and correct.

Signed Nancy Oltmanns Title Senior Staff Specialist Date 3/7/05

(This space for Federal or State Office use)

APPROVED BY _____ Title _____ Date _____

CONDITION OF APPROVAL, if any:

ACCEPTED FOR RECORD

MAR 15 2005

NMOCB

FARMINGTON FIELD OFFICE
BY Shm

- 2-28-05 TIH, tag TOC @ 5970'. TOOH. TIH, perf 2 sqz holes @ 5282'. TOOH. TIH w/cmt retainer, set @ 5232'. Establish injection. Plug #2: pump 51 sx Type III cmt below cmt retainer inside & outside csg. Pump 9 sx Type III cmt above cmt retainer inside csg to plug Gallup. Displace w/18 bbl wtr. TOOH. WOC. TIH, tag TOC @ 5096'. TOOH. TIH, perf 2 sqz holes @ 3252'. TOOH. SDON.
- 3-1-05 TIH w/cmt retainer, set @ 3202'. Establish injection. Plug #3: pump 51 sx Type III cmt below cmt retainer inside & outside csg. Pump 9 sx Type III cmt above cmt retainer inside csg to plug Mesaverde. Displace w/10.5 bbl wtr. TOOH. WOC. TIH, tag TOC @ 3115'. TOOH. TIH w/cmt retainer, set @ 2592'. Establish circ. Plug #4: pump 93 sx Type III cmt below cmt retainer inside csg. Pump 9 sx Type III cmt above cmt retainer inside csg to plug Chacra. Displace w/8 bbl wtr. TOOH. SDON.
- 3-2-05 PT csg to 820 psi/30 min, OK. (Verbal approval from Charlie Perrin, OCD). TOOH. TIH w/5 1/2" CIBP, set @ 1800'. TOOH. ND BOP. NU WH. RD. Rig released.

Please consider this well to be temporarily abandoned pending recompletion of the Fruitland Coal formation.