

State of New Mexico  
Energy, Minerals and Natural Resources

**HOBBES OGD**  
**OIL CONSERVATION DIVISION**  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**JUN 15 2011**

WELL API NO. <b>30-025-05616</b>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <b>AO-1543</b>
7. Lease Name or Unit Agreement Name <b>North Monument Grayburg/SA Unit Blk. 3</b>
8. Well Number <b>15</b>
9. OGRID Number <b>873</b>
10. Pool name or Wildcat <b>Eunice Monument G/SA</b>

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

**Apache Corporation**

3. Address of Operator

**303 Veterans Airpark Lane, Ste. 3000, Midland, TX 79705**

4. Well Location

Unit Letter **O** : **660** feet from the **South** line and **1980** feet from the **East** line

Section **17** Township **19S** Range **37E** NMPM County **Lea**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

**3670' GL**

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type \_\_\_\_\_ Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water **N/A**

Pit Liner Thickness: \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

**12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ P AND A ☒

CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6/2/11-----MIRU plugging equipment. Set 5 1/2" CIBP @ 3750'.

6/3/11-----Tag 5 1/2 CIBP @ 3750' mix mud laden fluid circ 87 bbls,  
Spot 50 sx cmt woc tag cmt plug @ 3340'. **3346'**  
Spot 40 sx cmt from 2810' woc.

6/6/11-----Tag cmt plug @ 2459'.  
(Per OCD) perf @ 1500' sqz 60 sx cmt woc.  
Tag cmt plug @ 1250'.

Perf 6 holes @ 331' est circ down 5 1/2 x 7 5/8 csg. Could not pump into 10 3/4 csg.

Circ 30 sx cmt from 331' down 5 1/2 x 7 5/8 to Surf.

Cut off well head & anchors - clean location.

Install dry hole marker. MO plugging equipment.

Approved for plugging of well bore only.  
Liability under bond is retained pending receipt  
of C-103 (Subsequent Report of Well Plugging)  
which may be found at OCD Web Page under  
Forms, [www.emnrd.state.nm.us/oed](http://www.emnrd.state.nm.us/oed).

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE [Signature] TITLE \_\_\_\_\_ (Basic Energy Services) DATE **6-18-11**

Type or print name:

E-mail address:

Telephone No. 432-563-3355

**For State Use Only**

APPROVED BY: [Signature] TITLE **Staff NGR** DATE **6/16/2011**

Conditions of Approval (if any):

**DOT**