Submit 3 Copies To Appropriate District Office	State of New Me		Form C-103
District I	Energy, Minerals and Natu	ral Resources WELL AP	June 19, 2008
1625 N. French Dr., Hobbs, NM 88240 District II HOBBS OC	BIL CONSERVATION	30-025-342	
	OIL CONSERVATION	D	e Type of Lease
District III 1000 Rio Brazos Rd , Aztec, NM 84401 3 20	1220 South St. Fran	517	ATE FEE X
District IV 1220 S. St. Francis Dr., Santa Fe, NM	IISanta Fe, NM 87	6. State O	il & Ga's Lease No.
87505	AND DEDODTS ON WELLS		Name or Unit Agreement Name
SUNDR RECEIVED AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			-
DIFFERENT RESERVOIR. USE "APPLICATIO PROPOSALS.)	N FOR PERMIT" (FORM C-101) FO		
	Well 🔲 Other:	8. Well N	umber 001
2. Name of Operator Apache Corporation		9. OGRIE 873) Number
3. Address of Operator			ame or Wildcat
303 Veterans Airpark Lane, Suite 3000 M	lidland, TX 79705	Blinebry O&	&G(Oil)6660/House;Tubb(78760)
4. Well Location			
Unit Letter : 1980	feet from the South		feet from the East line
Section 14		ange 38E NMPM	County Lea
	Elevation (Show whether DR 03' KB	, RKB, RT, GR, etc.)	
<u>(</u>)			
12 Chaok Anna	onriate Roy to Indicate N	ature of Notice, Report or	Other Data
12. Check Apple	opriate DOX to mulcate N		
NOTICE OF INTEN	_	-	T REPORT OF:
		REMEDIAL WORK	
		COMMENCE DRILLING OPN	
PULL OR ALTER CASING DOWNHOLE COMMINGLE		CASING/CEMENT JOB	
OTHER:		OTHER: Recomplete Tubb	X
13. Describe proposed or completed	operations. (Clearly state all	pertinent details, and give pertin	ent dates, including estimated date
13. Describe proposed or completed of starting any proposed work).	operations. (Clearly state all	pertinent details, and give pertin	
13. Describe proposed or completed	operations. (Clearly state all	pertinent details, and give pertin	ent dates, including estimated date
13. Describe proposed or completed of starting any proposed work).	operations. (Clearly state all SEE RULE 1103. For Multip	pertinent details, and give pertin	ent dates, including estimated date
13. Describe proposed or completed of starting any proposed work). or recompletion.Apache re-completed this well, as follows	operations. (Clearly state all SEE RULE 1103. For Multip ws:	pertinent details, and give pertin le Completions: Attach wellbor	ent dates, including estimated date e diagram of proposed completion
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 	operations. (Clearly state all) SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P	pertinent details, and give pertin le Completions: Attach wellbor	ent dates, including estimated date e diagram of proposed completion
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 	operations. (Clearly state all) SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid.	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67	ent dates, including estimated date e diagram of proposed completion
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 1/09/2008 Wash sand; RIH w/tbg. 	operations. (Clearly state all) SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid.	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67	ent dates, including estimated date e diagram of proposed completion
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 	operations. (Clearly state all) SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid.	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67	ent dates, including estimated date e diagram of proposed completion
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 1/09/2008 Wash sand; RIH w/tbg. 	operations. (Clearly state all) SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid.	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67	ent dates, including estimated date e diagram of proposed completion
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 1/09/2008 Wash sand; RIH w/tbg. 	operations. (Clearly state all) SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid.	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67	ent dates, including estimated date e diagram of proposed completion
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 1/09/2008 Wash sand; RIH w/tbg. 	operations. (Clearly state all) SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid.	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67	ent dates, including estimated date e diagram of proposed completion
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 1/09/2008 Wash sand; RIH w/tbg. 	operations. (Clearly state all) SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid.	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67	ent dates, including estimated date e diagram of proposed completion
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 1/09/2008 Wash sand; RIH w/tbg. 	operations. (Clearly state all) SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid.	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67 n w/1848 gal linear gel.	ent dates, including estimated date e diagram of proposed completion
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 1/09/2008 Wash sand; RIH w/tbg. 1/10/2008 RIH w/rods & pump. RTP. 	operations. (Clearly state all) SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid. 5-25; 82,000# 20/40 SLC, flush	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67 n w/1848 gal linear gel.	ent dates, including estimated date e diagram of proposed completion 06-10', 48-52' w/2 SPF, 36 holes.
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 1/09/2008 Wash sand; RIH w/tbg. 1/10/2008 RIH w/rods & pump. RTP. pud Date: 02/05/1998 	operations. (Clearly state all j SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid. S-25; 82,000# 20/40 SLC, flush Rig Release Da	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67 n w/1848 gal linear gel. ate: 02/22/1998	ent dates, including estimated date e diagram of proposed completion
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 1/09/2008 Wash sand; RIH w/tbg. 1/10/2008 RIH w/rods & pump. RTP. 	operations. (Clearly state all j SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid. S-25; 82,000# 20/40 SLC, flush Rig Release Da	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67 n w/1848 gal linear gel. ate: 02/22/1998	ent dates, including estimated date e diagram of proposed completion 06-10', 48-52' w/2 SPF, 36 holes.
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 1/09/2008 Wash sand; RIH w/tbg. 1/10/2008 RIH w/rods & pump. RTP. pud Date: 02/05/1998 	operations. (Clearly state all j SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid. S-25; 82,000# 20/40 SLC, flush Rig Release Da	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67 n w/1848 gal linear gel. ate: 02/22/1998	ent dates, including estimated date e diagram of proposed completion 06-10', 48-52' w/2 SPF, 36 holes.
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 1/09/2008 Wash sand; RIH w/tbg. 1/10/2008 RIH w/rods & pump. RTP. pud Date: 02/05/1998 	operations. (Clearly state all j SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid. S-25; 82,000# 20/40 SLC, flush Rig Release Da	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67 n w/1848 gal linear gel. ate: 02/22/1998 DHC-HOB- 4 est of my knowledge and belief.	ent dates, including estimated date e diagram of proposed completion 06-10', 48-52' w/2 SPF, 36 holes.
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 1/09/2008 Wash sand; RIH w/tbg. 1/10/2008 RIH w/rods & pump. RTP. pud Date: 02/05/1998 hereby certify that the information above bIGNATURE RUSA 	operations. (Clearly state all j SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid. 3-25; 82,000# 20/40 SLC, flush Rig Release Da e is true and complete to the bo	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67 n w/1848 gal linear gel. n w/1848 gal linear gel. <u>DHC-HOB- 4</u> est of my knowledge and belief.	ent dates, including estimated date e diagram of proposed completion 06-10', 48-52' w/2 SPF, 36 holes.
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 1/09/2008 Wash sand; RIH w/tbg. 1/10/2008 RIH w/rods & pump. RTP. pud Date: 02/05/1998 	operations. (Clearly state all j SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid. 5-25; 82,000# 20/40 SLC, flush Rig Release Da e is true and complete to the be with the back of the	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67 n w/1848 gal linear gel. ate: 02/22/1998 <u>DHC-HOB- 4</u> est of my knowledge and belief. ngr Tech S: <u>Reesa.Holland@apachecorp.com</u>	ent dates, including estimated date e diagram of proposed completion 06-10', 48-52' w/2 SPF, 36 holes.
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 1/09/2008 Wash sand; RIH w/tbg. 1/10/2008 RIH w/rods & pump. RTP. Pud Date: 02/05/1998 hereby certify that the information above bigNATURE Reesa Holland For State Use Only 	operations. (Clearly state all j SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid. 3-25; 82,000# 20/40 SLC, flush Rig Release Da e is true and complete to the be cond	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67 n w/1848 gal linear gel. ate: 02/22/1998 <u>DHC-HOB- 4</u> est of my knowledge and belief. ngr Tech S: <u>Reesa.Holland@apachecorp.com</u>	ent dates, including estimated date e diagram of proposed completion 06-10', 48-52' w/2 SPF, 36 holes.
 13. Describe proposed or completed of starting any proposed work). or recompletion. Apache re-completed this well, as follo 1/04/2008 MIRUSU. RIH & set CIBP 1/07/2008 Acidize Tubb w/2000 gal 15 1/08/2008 Frac Tubb w/39,774 gal SS 1/09/2008 Wash sand; RIH w/tbg. 1/10/2008 RIH w/rods & pump. RTP. Pud Date: 02/05/1998 hereby certify that the information above bIGNATURE	operations. (Clearly state all j SEE RULE 1103. For Multip ws: @ 7350' w/2 sx cmt on top. P 5% HCL DXBX acid. 5-25; 82,000# 20/40 SLC, flush Rig Release Da e is true and complete to the be with the back of the	pertinent details, and give pertin le Completions: Attach wellbor erf Tubb @ 6623-27', 40-44', 67 n w/1848 gal linear gel. n w/1848 gal linear gel. <u>DHC-HOB- 4</u> est of my knowledge and belief.	ent dates, including estimated date e diagram of proposed completion 06-10', 48-52' w/2 SPF, 36 holes.