Form 3160-5 (August 1999)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO 1004-0135

Expires. November 30, 2000

## 5. Lease Serial No

LC-061869

ᆫ	00100	<u></u>		
6	If Indian	Allottee	or Trit	se Mame

SUNDRY	NOTICES	AND	REPORTS	ON	WELLS	JUN	28	2011
Do not use t							•	,

abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well X Oil Well Gas Well X Other Drilled Not Completed 8. Well Name and No. Cotton Draw Unit 98 2 Name of Operator OXY USA Inc. 16696 9. API Well No. . 3a. Address 3b. Phone No. (include area code) 30-025-37586 P.O. Box 50250, Midland, TX 79710-0250 432-685-5717 10. Field and Pool, or Exploratory Area 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Paduca Delaware 2480 FNL 1250 FWL SWNW(E) Sec 21 T25S R32E 11 County or Parish, State NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Fracture Treat Alter Casing Reclamation Well Integrity Subsequent Report Casing Repair New Construction Other Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

TD-4900'

PBTD-4862'

Perfs 4585-4855'

9-5/8" 36# csg @ 820' w/ 450sx, 12-1/4" hole, TOC-Surf-Circ 7" 23# csg @ 4900' DVT @ 3893' w/ 1000sx. 8-3/4" hole. TOC-Surf-Circ

- 1. M&P 85sx cmt @ 4862-4500' WOC-Tag
- M&P 35sx cmt @ 3943-3803' WOC-Tag
- M&P 30sx cmt @ 902-770' WOC-Tag
- M&P 25sx cmt @ Surface

10# MLF between plugs

## SEE ATTACHED FOR CONDITIONS OF APPROVAL

RECLAMATION PROCEDURE **ATTACHED** 

I hereby certify that the foregoing is true and correct Name (Printed/Typed)	Title	***				
David Stewart	Regulatory Advisor					
In State	Date 6(5(1)					
THIS SPACE FO	OR FEDERAL OR STATE OFFICE USE					
Approved by famo a. Long	Title SEAS	Date 6-76-11				
Conditions of approval, if any, are attached. Approval of this notice do certify that the applicant holds legal or equitable title to those rights in which would epitite the applicant to conduct operations here to be applicant to conduct operations here to be applicant to conduct operations here to be applicant to conduct operations there are the applicant to conduct operations there are the applicant to conduct operations there are the applicant to conduct operations.	oes not warrant or Office The subject lease					

Title 18USC Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

OXY USA Inc. - Proposed Cotton Draw Unit #98 API No. 30-025-37586

25sx @ Surface

30sx @ 902-770' WOC-Tag

35sx @ 3943-3803' WOC-Tag

85sx @ 4862-4500' WOC-Tag

TD-4900'


12-1/4" hole @ 820' 9-5/8" csg @ 820' w/ 450sx-TOC-Surf-Circ

8-3/4" hole @ 4900' 7" csg @ 4900' DVT @ 3893' 1st w/ 300sx-TOC-3888'-Circ 2nd w/ 700sx-TOC-Surf-Circ

Perfs @ 4585-4855'

PB-4862'

OXY USA Inc. - Current Cotton Draw Unit #98 API No. 30-025-37586



12-1/4" hole @ 820' 9-5/8" csg @ 820' w/ 450sx-TOC-Surf-Circ

8-3/4" hole @ 4900' 7" csg @ 4900' DVT @ 3893' 1st w/ 300sx-TOC-3888'-Circ 2nd w/ 700sx-TOC-Surf-Circ

Perfs @ 4585-4855'

PB-4862'