Submit 3 Copies To Appropriate District  State of New Mexico	Form C-103
Office District I  Energy, Minerals and Natural Resource	ces March 4, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II	30 025 08455
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISIO	5. Indicate Type of Lease
District III 1220 South St. Francis Dr.	STATE X FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM	B-2317
87505	D 2317
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO	A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	State 35 No. 31
PROPOSALS.)	8. Well Number
1. Type of Well:	31
Oil Well X Gas Well Other	
2. Name of Operator	9. OGRID Number
McGowan Working Partners, Inc.	220397
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 55809, Jackson MS 39296-5809	Vacuum – Greyburg/San Andres
4. Well Location	
1. Wen boomen	
Unit Letter N : 660 feet from the South line a	and 1980 feet from the West line
One Letter 14 . 000 rect from the mile t	and 1700 feet from the West fine
Section 35 Township 17S Range	34E NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, C	
	on, etc.)
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be	a attached)
Pit Location: UL Sect Twp Rng Pit type Depth to Groun	dwaterDistance from nearest fresh water well
Distance from nearest surface water Below-grade Tank Location ULSect	TwpRng;
feet from theline andfeet from theline	
	232425
	Jotice Report or Other Data
12. Check Appropriate Box to Indicate Nature of N	Notice, Report or Other Data,
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF: Name of the state of t
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIA	SUBSEQUENT REPORT OF: Name of the state of t
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIA	SUBSEQUENT REPORT OF: Name of the state of t
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMEN	SUBSEQUENT REPORT OF: Name of the state of t
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING MULTIPLE CASING	SUBSEQUENT REPORT OF:  AL WORK  ALTERING CASING  ALTERING
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMEN	SUBSEQUENT REPORT OF:  AL WORK  ALTERING CASING  ALTERING
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING MULTIPLE COMPLETION CEMENT	SUBSEQUENT REPORT OF:  AL WORK  ALTERING CASING  ALTERING
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING MULTIPLE CASING CEMENT OTHER: OTHER:	SUBSEQUENT REPORT OF:  ALTERING CASING
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL  TEMPORARILY ABANDON CHANGE PLANS COMMEN  PULL OR ALTER CASING MULTIPLE CASING CEMENT  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent details)	SUBSEQUENT REPORT OF:  ALTERING CASING
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING MULTIPLE CASING CEMENT OTHER: OTHER:	SUBSEQUENT REPORT OF:  ALTERING CASING
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMENDULL OR ALTER CASING MULTIPLE CASING CEMENT OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed.)	SUBSEQUENT REPORT OF:  ALTERING CASING
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING MULTIPLE CASING CEMENT OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertin SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed.)  1. Pull production string.	SUBSEQUENT REPORT OF:  ALTERING CASING
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING MULTIPLE CASING CEMENT OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertin SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet  1. Pull production string. 2. Drill out CIBP @ 4570'	SUBSEQUENT REPORT OF:  ALTERING CASING
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING MULTIPLE CASING CEMENT OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertin SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet  1. Pull production string. 2. Drill out CIBP @ 4570' 3. Clean out to TD of 4765".	SUBSEQUENT REPORT OF:  ALTERING CASING
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL  TEMPORARILY ABANDON CHANGE PLANS COMMENT  PULL OR ALTER CASING MULTIPLE CASING CEMENT  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed.  1. Pull production string. 2. Drill out CIBP @ 4570' 3. Clean out to TD of 4765".	SUBSEQUENT REPORT OF:  ALTERING CASING
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK X PLUG AND ABANDON  TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE CASING CEMENT  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed.  Pull production string.  Pull production string.  Drill out CIBP @ 4570'  Clean out to TD of 4765''.  Perf. @ 4718-65' w/4" casing gun, 2 spf 180 phase  Test & return to service.	SUBSEQUENT REPORT OF:  ALTERING CASING
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK X PLUG AND ABANDON  TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE CASING CEMENT  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertin SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet  1. Pull production string. 2. Drill out CIBP @ 4570' 3. Clean out to TD of 4765''. 4. Perf. @ 4718-65' w/4" casing gun, 2 spf 180 phase 5. Test & return to service.  I hereby certify that the information above is true and complete to the best of my known and complete to the best of my	SUBSEQUENT REPORT OF:  ALTERING CASING  ALTERING CASING  PLUCAND  ABANDONMENT  OCO  Ment dates, including estimated date of starting any proposed work).  Tended to be a starting and proposed work.  The starting and proposed work and the starting and proposed work.
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK X PLUG AND ABANDON  TEMPORARILY ABANDON CHANGE PLANS  PULL OR ALTER CASING MULTIPLE CASING CEMENT  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed.  Pull production string.  Pull production string.  Drill out CIBP @ 4570'  Clean out to TD of 4765''.  Perf. @ 4718-65' w/4" casing gun, 2 spf 180 phase  Test & return to service.	SUBSEQUENT REPORT OF:  ALTERING CASING  ALTERING CASING  PLUCAND  ABANDONMENT  OCO  Ment dates, including estimated date of starting any proposed work).  Tended to be a starting and proposed work.  The starting and proposed work and the starting and proposed work.
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIA  TEMPORARILY ABANDON CHANGE PLANS COMMEN  PULL OR ALTER CASING MULTIPLE CASING CEMENT  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertin SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet  1. Pull production string. 2. Drill out CIBP @ 4570' 3. Clean out to TD of 4765''. 4. Perf. @ 4718-65' w/4" casing gun, 2 spf 180 phase 5. Test & return to service.  I hereby certify that the information above is true and complete to the best of my kr grade tank has been/will be constructed or closed according to NMOCD guidelines, a general per	SUBSEQUENT REPORT OF:  ALTERING CASING  ALTERING CASING  PLUCTAND  ABANDONMENT  OCD  Test and  Job  Ment dates, including estimated date of starting any proposed work).  tion or recompletion.  Towledge and belief. I further certify that any pit or belowmit or an (attached) alternative OCD-approved plan.
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIA  TEMPORARILY ABANDON CHANGE PLANS COMMEN  PULL OR ALTER CASING MULTIPLE CASING CEMENT  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertin SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet  1. Pull production string. 2. Drill out CIBP @ 4570' 3. Clean out to TD of 4765''. 4. Perf. @ 4718-65' w/4" casing gun, 2 spf 180 phase 5. Test & return to service.  I hereby certify that the information above is true and complete to the best of my kr grade tank has been/will be constructed or closed according to NMOCD guidelines, a general per	SUBSEQUENT REPORT OF:  ALTERING CASING  ALTERING CASING  PLUCAND  ABANDONMENT  OCO  Ment dates, including estimated date of starting any proposed work).  Tended to be a starting and proposed work.  The starting and proposed work and the starting and proposed work.
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK X PLUG AND ABANDON  TEMPORARILY ABANDON CHANGE PLANS COMMEN  PULL OR ALTER CASING MULTIPLE CASING  COMPLETION CEMENT  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed.  Pull production string.  Drill out CIBP @ 4570'  Clean out to TD of 4765''.  Perf. @ 4718-65' w/4" casing gun, 2 spf 180 phase  Test & return to service.  I hereby certify that the information above is true and complete to the best of my known grade tank has been/will be constructed or closed according to NMOCD guidelines, a general pertinent details, and give pertine	SUBSEQUENT REPORT OF:  ALTERING CASING  ALTERING CASING  ALTERING CASING  PLUCTAND  ABANDONMENT  OCD  Test and Job  Inent dates, including estimated date of starting any proposed work).  Intent dates, including estimated date of starting any proposed work).  In owledge and belief. I further certify that any pit or belowmit or an (attached) alternative OCD-approved plan.  Industry Officer  DATE 25 Feb 05
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIA  TEMPORARILY ABANDON CHANGE PLANS COMMEN  PULL OR ALTER CASING MULTIPLE CASING CEMENT  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertin SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet  1. Pull production string. 2. Drill out CIBP @ 4570' 3. Clean out to TD of 4765''. 4. Perf. @ 4718-65' w/4" casing gun, 2 spf 180 phase 5. Test & return to service.  I hereby certify that the information above is true and complete to the best of my kr grade tank has been/will be constructed or closed according to NMOCD guidelines, a general per	SUBSEQUENT REPORT OF:  ALTERING CASING  ALTERING CASING  ALTERING CASING  PLUCTAND  ABANDONMENT  OCD  Test and Job  Inent dates, including estimated date of starting any proposed work).  Intent dates, including estimated date of starting any proposed work).  In owledge and belief. I further certify that any pit or belowmit or an (attached) alternative OCD-approved plan.  Industry Officer  DATE 25 Feb 05
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING MULTIPLE CASING CEMENT OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give perting SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed to Drill out CIBP @ 4570' 3. Clean out to TD of 4765''. 4. Perf. @ 4718-65' w/4" casing gun, 2 spf 180 phase 5. Test & return to service.  I hereby certify that the information above is true and complete to the best of my kr grade tank has been/will be constructed or closed according to NMOCD guidelines, a general perroper SIGNATURE Glenn Hepner E-mail address: glenn@mcgowa	SUBSEQUENT REPORT OF:  ALTERING CASING  ALTERING CASING  ALTERING CASING  PLUCTAND  ABANDONMENT  OCD  Test and Job  Inent dates, including estimated date of starting any proposed work).  Intent dates, including estimated date of starting any proposed work).  In owledge and belief. I further certify that any pit or belowmit or an (attached) alternative OCD-approved plan.  Industry Officer  DATE 25 Feb 05
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON  TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING MULTIPLE CASING CEMENT  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertin SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed complet  1. Pull production string. 2. Drill out CIBP @ 4570' 3. Clean out to TD of 4765''. 4. Perf. @ 4718-65' w/4" casing gun, 2 spf 180 phase 5. Test & return to service.  I hereby certify that the information above is true and complete to the best of my kr grade tank has been/will be constructed or closed according to NMOCD guidelines, a general perr	SUBSEQUENT REPORT OF:  ALTERING CASING  ALTERING CASING  ALTERING CASING  PLUCTAND  ABANDONMENT  OCD  Test and Job  Inent dates, including estimated date of starting any proposed work).  Intent dates, including estimated date of starting any proposed work).  In owledge and belief. I further certify that any pit or belowmit or an (attached) alternative OCD-approved plan.  Industry Officer  DATE 25 Feb 05
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING MULTIPLE CASING CEMENT OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed operations. (Clearly state all pertinent details, and give pertinent SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed operations. (Clearly state all pertinent details, and give pertinent SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed operations. (Clearly state all pertinent details, and give pertinent SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed operations. (Clearly state all pertinent details, and give pertinent SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed operations. Attach wellbore diagram of proposed completed operations. (Clearly state all pertinent details, and give pert	SUBSEQUENT REPORT OF: ALTERING CASING ALTERING
12. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL TEMPORARILY ABANDON CHANGE PLANS COMMEN PULL OR ALTER CASING MULTIPLE CASING CEMENT OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, and give perting SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completed.  1. Pull production string. 2. Drill out CIBP @ 4570' 3. Clean out to TD of 4765''. 4. Perf. @ 4718-65' w/4" casing gun, 2 spf 180 phase 5. Test & return to service.  I hereby certify that the information above is true and complete to the best of my kr grade tank has been/will be constructed or closed according to NMOCD guidelines, a general perronal string.  SIGNATURE Glenn Hepner E-mail address: glenn@mcgowa	SUBSEQUENT REPORT OF:  ALTERING CASING  ALTERING CASING  ALTERING CASING  PLUCTAND  ABANDONMENT  OCD  Test and Job  Inent dates, including estimated date of starting any proposed work).  Intent dates, including estimated date of starting any proposed work).  In owledge and belief. I further certify that any pit or belowmit or an (attached) alternative OCD-approved plan.  Industry Officer  DATE 25 Feb 05