

RECEIVED

## New Mexico Oil Conservation Division, District 1

Form 3160-5  
(February 2005)

UNITED STATES

1625 N. French Drive

Hobbs, NM 88240

DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB No 1004-0137  
Expires: March 31, 2007OCT 08 2010  
HOBBSD

## SUNDRY NOTICES AND REPORTS ON WELLS

**Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.**5. Lease Serial No.  
NMNM 65342

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well

☐ Oil Well☒ Gas Well☐ Other2. Name of Operator  
Wespac Energy LLC3a. Address  
8620 N New Braunfels, Suite 603  
San Antonio, Texas 781273b. Phone No. (include area code)  
210-310-31354. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
Township 10 South, Range 30 East, NMPM

3-10S - 30E

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.  
Middlebrook 3-19. API Well No.  
30-005-2106210. Field and Pool or Exploratory Area  
Oasis; ABO 8182011. Country or Parish, State  
Chaves, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

## TYPE OF SUBMISSION

## TYPE OF ACTION

☐ Notice of Intent☐ Acidize☐ Deepen☐ Production (Start/Resume)☐ Water Shut-Off☒ Subsequent Report☐ Alter Casing☐ Fracture Treat☐ Reclamation☐ Well Integrity☐ Casing Repair☐ New Construction☐ Recomplete☒ Other Change of Operator☐ Final Abandonment Notice☐ Change Plans☐ Plug and Abandon☐ Temporarily Abandon☐ Convert to Injection☐ Plug Back☐ Water Disposal

13. Describe Proposed or Completed Operation. Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

The undersigned accepts all applicable terms, conditions, stipulations, and restrictions concerning operations conducted on the leased land or portion thereof, as described below:

Township 10 South, Range 30 East, NMPM

Section 3: SW/4 limited as to all depths from the surface of the earth down to the base of the deepest producing formation or 100 feet below the total depth drilled as of August 9, 1990, whichever is the shallower.

Bond Coverage: Oil & Gas ~~Individual~~ Bond  
BLM Bond File No.: NMB000549

Effective 01-01-2010

Wespac Energy LLC Accepts All Applicable Terms,  
Conditions, Stipulations, And Restrictions  
Concerning Operations Conducted On The Leased  
Land Or Portion Thereof Under Their \$25,000.00  
Statewide BLM Bond Number NMB000549 Effective  
01-01-2010.

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Don Ford

Title Manager

Date 07/13/2010

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

/S/ DAVID R. GLASS

PETROLEUM ENGINEER

Title

Date

SEP 16 2010

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

ROSWELL FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)