

## New Mexico Oil Conservation Division, District 1

1625 N. French Drive  
Hobbs, NM 88240Form 3160-5  
(August 2007)UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

JUL 20 2011

FORM APPROVED  
OMB No. 1004-0137  
Expires: July 31, 2010**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

RECEIVED

SUBMIT IN TRIPLICATE - Other instructions on page 2.

## 1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other

## 2. Name of Operator

Celero Energy II, LP

## 3a. Address

400 W. Illinois, Ste. 1601 Midland TX 79701

## 3b. Phone No. (include area code)

(432)686-1883

## 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1980' FSL & 1980' FEL  
Sec 34, T13S, R31E (J)

## 5. Lease Serial No.

NM-120355

## 6. If Indian, Allottee or Tribe Name

## 7. If Unit of CA/Agreement, Name and/or No.

## 8. Well Name and No.

Drickey Queen Sand Unit #903

## 9. API Well No.

30-005-00912

## 10. Field and Pool or Exploratory Area

Caprock; Queen

## 11. Country or Parish, State

Chaves, NM

## 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Attempt to
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	return to
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	injection

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

3/21 - 3/25/11 RU. TIH w/ 4 3/4" bit, bumper sub, 6- 3 1/2" DC's & 74 jts of 2 7/8" WS to 2539'. Tag up. TOH & PU 4 1/2" impression block & TIH. Tag fish @ 2539'. Set impression block & TOH. TIH w/ screw in sub & 80 jts of 2 7/8" tbg WS to 2539'. Tag & screw into fish. Pulled 20K over & pipe came free. Gained 2K string wt. TOH & recovered 12 jts of 2 3/8" IPC tbg (342'). Top of fish @ 2881'. TIH w/ 4 11/16" overshot, bumper sub, jars, 6- 3 1/2" DC's, x-over, 81 jts of 2 7/8" WS. Tag @ 2785'. TOH. Change BHA to screw in sub, 2 jts 2 7/8" WS, bumper sub, jars, 6- 3 1/2" DC's, x-over, 82 jts 2 7/8" WS. Tag @ 12' in on jt #82 @ 2786'. TOH. TIH w/ 4 3/4" bit, BS & 88 jts 2 7/8" WS. Tag @ 2786'. TOH w/ bit. TOH w/ 4 1/2" impression block & 88 jts of 2 7/8" WS @ 2786'. Set impression block & TOH. Csg appears to be parted. TIH w/ csg scraper & 87 jts of 2 7/8" WS to 2756'. TOH & PU 5 1/2" RBP & TIH w/ 87 jts of WS & set RBP @ 2756'. TOH. Run CIL from 2756' to surface. TIH & move RBP up to 2610'. Filled hole w/ 28 bbls PW. Get off plug & TOH. Test csg to 500# psi. Tested okay. Set RBP @ 2610'. Run CBL. TIH w/ on/off tool & 83 jts 2 7/8" WS & retrieve RBP. TIH open ended tagged @ 2786'. Worked pipe through down to 2815'. Could not work through. TOH, LD tbg, install 1 jt 2 3/8" tbg WH w/ valve. Prepare to send sundry to P&A. □

MSB- OGD 7/20/2011

## 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Lisa Hunt

Title Regulatory Analyst

Signature

Lisa Hunt

Date 06/28/2011

## ACCEPTED FOR RECORDS SPACE FOR FEDERAL OR STATE OFFICE USE

## Approved by

/S/ DAVID R. GLASS

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1012 makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or reports to any matter within its jurisdiction.

(Instructions on page 2)