

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr, Hobbs, NM 87240
District II
1301 W Grand Ave, Artesia, NM 88210
District III
1000 Rio Brazos Rd, Aztec, NM 87410
District IV
1220 S St Francis Dr, Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

June 19, 2008

HOBBS OCD

JUL 18 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-12509
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: North Hobbs G/SA Unit
8. Well Number 311
9. OGRID Number 157984
10. Pool name or Wildcat Hobbs; Grayburg-San Andres
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3641' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	2. Name of Operator Occidental Permian Ltd.	3. Address of Operator P.O. Box 4294, Houston, TX 77210-4294
4. Well Location Unit Letter <u>B</u> : <u>1022</u> feet from the <u>North</u> line and <u>2310</u> feet from the <u>East</u> line Section <u>34</u> Township <u>18-S</u> Range <u>38-E</u> NMPM County <u>Lea</u>		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3641' GR		

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attached

Approved for plugging of well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms, www.emnrd.state.nm.us/oed.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Stephens TITLE Regulatory Compliance Analyst DATE 7/12/11

Mark_Stephens@oxy.com

Type or print name Mark Stephens E-mail address: Mark_Stephens@oxy.com PHONE (713) 366-5158

For State Use Only

APPROVED BY Maley Brown TITLE Compliance Officer DATE 7/25/2011

Conditions of Approval (if any):

JUL 25 2011

North Hobbs G/SA Unit Well No. 311
API No. 30-025-12509

Plug and abandon the subject well as follows -

6/27/11 - 6/29/11:

MI x RU plugging unit. ND WH x NU BOP. RIH with perf sub on 128 jts. production tubing. RU pump truck x circulate well with 75 bbls 10 ppg mud-laden fluid. Tag existing CIBP at 4060'. Spot 30 sx. cement on tag x flush with 22 bbls 10 ppg mud. Pull uphole x spot 30 sx. cement at 2918'. POOH with tubing x RIH with 7" AD-1 packer x set at 1505'. RIH with wireline x tag at 2685'. Pull uphole x perforate at 1820'. Establish injection rate into perfs - 2 bbls per minute @ 1400 psi with full returns. Mix and pump 100 sx. Cl. C x flush with 13 bbls 10 ppg mud. Release packer and reset at 30'. RIH with wireline x tag plug at 1580'. Pull uphole x perforate at 400'. ND BOP x NU WH. Circulate 120 sx. cement from 400' to surface. RD plugging unit x clean location.