

Submit 1 Copy To Appropriate District

Office

District I - (575) 393-6161

1625 N. French Dr., Hobbs, NM 88240

District II - (575) 748-1283

811 S. First St., Artesia, NM 88210

District III - (505) 334-6178

1000 Rio Brazos Rd., Aztec, NM 87410

District IV - (505) 476-3460

1220 S. St. Francis Dr., Santa Fe, NM

87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

WELL API NO. /

30-005-20532

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

NM - 146153A

7. Lease Name or Unit Agreement Name

HAHN FEDERAL

8. Well Number #5

Grid # 261198 ✓

10. Pool name or Wildcat
TOM TOM; SAN ANDRESSUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Doral Energy Inc.

3. Address of Operator

22610 US HWY NORTH, SUITE 281 SAN ANTONIO, TX 78258

4. Well Location

Unit Letter NK 1980 feet from the WEST line and 1980 feet from the SOUTH lineSection 27 Township 7S Range 31E NMPM County HAVE

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL. ☐
DOWNHOLE COMMINGLE ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐OTHER: Temporary Abandonment ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Doral Energy Corp., respectfully request Temporary Abandonment status of this well.

We will set CIBP as soon as we are granted permission to abandon.

Condition of Approval: Notify OCD Hobbs
office 24 hours prior to running MIT Test & Chart

Rule 19.15.25.14

Set CIBP, RBP or Packer within 100 feet of uppermost
perfs or open hole Pressure test to 500 psi for 30 minutes w/
a pressure drop of not greater than 10% over a
30 minute period

Rig Release Date

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Larry RisleyTITLE PresidentDATE 7-22-2011

Type or print name

Larry RisleyE-mail address: larryr@xbres.comPHONE: 210-261-6700

For State Use Only

APPROVED BY:

[Signature]

TITLE

STAFF MGRDATE 7-26-2011

Conditions of Approval (if any):