



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

Susana Martinez
Governor

John H. Bemis
Cabinet Secretary

Jami Bailey
Division Director
Oil Conservation Division

Field Inspection Program
"Preserving the Integrity of Our Environment"

11-Aug-11

HOBBS OCD

AUG 11 2011

RECEIVED

CIMAREX ENERGY CO. OF COLORADO
600 N. MARIENFELD ST. SUITE 600
MIDLAND TX 79701

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

CITIES THOMAS No.003				H-19-24S-37E	30-025-25608-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
08/11/2011	Routine/Periodic	Mark Whitaker	Yes	No	9/7/2011	iMAW1122348772
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection:		Well sign not legible (Rule 19.15.16.8). Rules require that sign be legible at a distance of 50 feet THIS IS THE SECOND NOTICE. NEED TO REPLACE WELL SIGN				

CITIES THOMAS No.004				G-19-24S-37E	30-025-25756-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
08/11/2011	Routine/Periodic	Mark Whitaker	Yes	No	9/7/2011	iMAW1122349149
Comments on Inspection:		Well sign not legible (Rule 19.15.16.8). Rules require that sign be legible at a distance of 50 feet. THIS IS THE SECOND NOTICE. NEED TO REPLACE WELL SIGN.				

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By." date shown
above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order
summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently
plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.


Sincerely,


COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data
Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER	015H14150977	US POSTAGE
	\$0.44	
	08/11/11	
	Mailed From 88240	

CIMAREX ENERGY CO. OF COLORADO
600 N. MARIENFIELD ST
SUITE 600
MIDLAND, TX 79701