REC'D 10/8/2020 - NMOCD

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Operator

FORM APPROVED

Expires: January 31, 2018 rial No.

6. If Indian, Allottee or Tribe Name

5. Lease Serial No.

NMNM14218

not use this form for prop	osals to drill or to re-enter an
	60-3 (APD) for such proposals.

SUNDRY NOTICES AND REPORTS ON WELLS Do aban

SUBMIT IN TRIPLICATE - Other instructions on page 2		7. If Unit or CA/Agreement, Name and/or No.
Type of Well ☐ Gas Well ☐ Other		8. Well Name and No. CC FRISTOE B FED NCT-2 29
	ontact: HOWIE LUCAS owie.lucas@chevron.com	9. API Well No. 30-025-35984-00-S1
3a. Address 6301 DEAUVILLE BLVD MIDLAND, TX 79706	3b. Phone No. (include area code) Ph: 832-588-4044	10. Field and Pool or Exploratory Area LANGLIE MATTIX-7RVRS-QN-GB
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State
Sec 35 T24S R37E NENW 660FNL 1980FWL		LEA COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION				
□ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	■ Water Shut-Off	
Notice of Intent	☐ Alter Casing	☐ Hydraulic Fracturing	□ Reclamation	Well Integrity	
Subsequent Report ■	□ Casing Repair	■ New Construction	☐ Recomplete	Other	
☐ Final Abandonment Notice	Change Plans	☑ Plug and Abandon	☐ Temporarily Abandon		
	☐ Convert to Injection	Plug Back	☐ Water Disposal		

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

06/05/2020 Move in P&A equipment. Pressure test tubing. L/D rods. 06/08/2020 N/U and test BOPE. TOH w/ tubing. <u>Set CIBP at 3,400</u>?. TIH and tag <u>CIBP</u>. Pressure test

casing to 500 psi for 15 minutes successfully. Spot 33 bls of MLF. Spot 25 sx class C cmt: 3,400?-3,154?

Spot 65 sx

06/09/2020 Tag TOC at 2,092?. Spot 25 sx class C cmt: 2,092?-1,844?. Spot 130 sx class C cmt:

1,1102-surface.

Verified cmt at surface. RDMO. P&A complete.

RECLAMATION PROCEDURE **ATTACHED**

RECLAMATION DUE 12-9-20'

10/13/2020 - PM NMOCD

						_
14. I hereby certify the	tat the foregoing is true and correct. Electronic Submission #520011 verifie For CHEVRON USA INCORP Committed to AFMSS for processing by DEB Med) HOWIE LUCAS	POATE	D. cont to the Hobb			
- 1 (17 micar 1)p		1000	. w E. TOITTEET	7710	ARE LEID EALL VEGOVO	-
Signature	(Electronic Submission)	Date	06/23/2020		IIII 2 4 2020	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE				JUN 2 4 2089		
Approved By		Title		В	UREAU OF LAND MANAGEMENT	
Conditions of approval, certify that the applican	if any, are attached. Approval of this notice does not warrant or tholds legal or equitable title to those rights in the subject lease applicant to conduct operations thereon.	Offic	2		CARLSBAD FIELD OFFICE	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Save Form 3160-5 (June 2015) UNITED STATES

DEPARTMENT OF THE INTERIOR

Print

FORM APPRO	OVED
OMB No. 1004	-0137
Expires: January .	31, 2018

5. Lease Serial No.

BUREAU OF LAND MANAGEMEN	NM-14218			
SUNDRY NOTICES AND REPORTS ON	6. If Indian, Allottee or Tribe Name			
Do not use this form for proposals to drill or	o. Il maian, Another o	The Name		
abandoned well. Use Form 3160-3 (APD) for s				
SUBMIT IN TRIPLICATE - Other instructions on p	7. If Unit of CA/Agree	ement, Name and/or No.		
1. Type of Well	age 2	1		
Oil Well Gas Well Other		8. Well Name and No.		
2. Name of Operator Contact: Howie Lucas	··	CC Fristoe "B" NCT 2-29 9. API Well No.		
Chevron USA Incorporated E-Mail: howie.lucas@chev		30-025-35984		
	o. (include area code)	10. Field and Pool or I	Exploratory Area	
6301 Deauville Blvd., Midland, TX 79706 Ph: 832-5	88-4044	Langlie Mattix, 7 Rivers, Queen, Grayburg 11. Country or Parish, State		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)			State	
Section 35, 24S, 37E, 660' FNL, 1980' FWL		Lea County, NM		
12 CHECK THE APPROPRIATE BOX(ES) TO I	NDICATE NATURE OF NOTI	CE, REPORT OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF AC	TION		
Notice of Intent Acidize De	eepen Proc	luction (Start/Resume)	Water Shut-Off	
Alter Casing Hy	draulic Fracturing Rec	amation	Well Integrity	
A Subsequent Report		omplete	Other	
		porarily Abandon		
Final Abandonment Notice Convert to Injection Plants. Describe Proposed or Completed Operation: Clearly state all pertinent details.		er Disposal		
completion of the involved operations. If the operation results in a multiple of completed. Final Abandonment Notices must be filed only after all requirements ready for final inspection.) 06/05/2020 Move in P&A equipment. Pressure test tubing. L. 06/08/2020 N/U and test BOPE. TOH w/ tubing. Set CIBP at 500 psi for 15 minutes successfully. Spot 33 bls of MLF. Spot class C cmt: 2,668'-2,025'. 06/09/2020 Tag TOC at 2,092'. Spot 25 sx class C cmt: 2,09 Verified cmt at surface. RDMO. P&A complete.	ents, including reclamation, have /D rods. 3,400'. TIH and tag Clust 25 sx class C cmt: 3,	BP. Pressure tes	t casing to	
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)				
Howie Lucas E-mail address: howie.lucas@chevron.com	Title Well Abandonme	ent Engineer, Attorney	/ in Fact	
Signature	Date 06/23/20			
THE SPACE FOR FE	DERAL OR STATE OF	FICE USE		
Approved by		I		
	Title	l _r	Date	
Conditions of approval, if any, are attached. Approval of this notice does not ward certify that the applicant holds legal or equitable title to those rights in the subject which would entitle the applicant to conduct operations thereon.	ant or			
Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any false fictitious or fraudulent statements or representations as to any matter with		lfully to make to any de	partment or agency of the United States	

Clear



BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/mn



In Reply Refer To: 1310

Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1 The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3 The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD If you

314

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Melissa Horn Environmental Protection Specialist 575-234-5951

Kelsey Wade Environmental Protection Specialist 575-234-2220

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612

WORLD ST.

西京門 THE YES

BUREAU OF LAND MANAGEMENT DEPARTMENT OF THE INTERIOR

UNITED STATES

CARLSBAD FIELD OFFICE 620 EAST GREENE STREET PENALTY FOR PRIVATE USE \$300

OFFICIAL USE

CARLSBAD, NEW MEXICO 88220

US POSTAGE \$000.50º 06/26/2020 Hasler

FIRST-CLASS MAIL

ZIP 88220 011E11520047

CHEVERON USA INCORPAORATED 6301 DEAUVILLE BLVD MIDLAND, TX 79706