

Submit 1 Copy To Appropriate District Office

District I – (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II – (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III – (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV – (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised July 18, 2013

WELL API NO. 30-025-22561
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Opal
8. Well Number 1
9. OGRID Number 247692
10. Pool name or Wildcat N. Bagley L. Penn

<p><b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)</p>	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator Jay Management Company, LLC	
3. Address of Operator 1001 West Loop South, Suite 750 Houston, TX 77027	
4. Well Location Unit Letter <u>D</u> : <u>660</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>West</u> line Section <u>20</u> Township <u>11 S</u> Range <u>33 E</u> NMPM County <u>Lea</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4317 KB	

## 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐  
CLOSED-LOOP SYSTEM ☐  
OTHER: ☐

## SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐  
OTHER: ☐

PNR

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

05-20-20 Attempt to set CIBP @ 8,475'. Fail. RIH with bit and scraper can't pass 6,565'. POOH with bit and scraper.

05-21-20 RIH open ended tubing. Tag hard @ 6,565'. Call OCD for instruction. Spot a balance plug @ 6,565' w/ 20 sx class "C" cmt (Per Kerry w/ OCD). WOC.

Tag TOC @ 6,260. Circulate MLF. Pressure test casing to 500 psi. Pass. Perf @ 6,000' (Per Kerry w/ OCD). Attempt to Sqz. Fail. Call OCD for instruction.

05-22-20 Attempt to POOH w/ tubing. Fail. Work on tubing. Can't POOH but can RIH. Call OCD for instruction.

05-26-20 RIH w/ tubing to 6,260'. Cut tubing @ 6,035'. Spot a balance plug @ 6,030' w/ 25 sx class "C" cmt (Per Kerry w/ OCD). WOC. Tag TOC @ 5,780'.

Perf @ 3,785'. Attempt to Sqz. Fail. Call OCD for instruction. Spot a balance plug @ 3,835' w/ 25 sx cmt (Per Kerry w/ OCD). WOC.

05-27-20 Attempt to Tag. No Tag. Spot a balance plug @ 3,835' w/ 40 sx cmt (Per Kerry w/ OCD). WOC. Attempt to Tag. No Tag. Spot balance plug @ 3,835' w/ 25 sx cmt (Per Kerry w/ OCD). WOC.

05-28-20 Tag TOC @ 3,433' Perf @ 2,400'. Sqz w/ 65 sx cmt. WOC. Tag TOC @ 2,167'. Perf @ 1,720'. Sqz w/ 65 sx cmt. WOC.

05-29-20 Tag TOC @ 1,476'. Perf @ 395'. Circulate cement to surface.

Cut off wellhead 3' below ground level. Verify cement to surface. Install dry hole marker.

Spud Date:

05/19/2020

Rig Release Date:

05/29/2020

11/20/2020 - PM NMOCD

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

Production Analyst

DATE

11/19/2020

Type or print name

Nhi Le

E-mail address:

nle@jaymgt.com

PHONE:

713-621-6785

For State Use Only

APPROVED BY:

Kerry Fortner

TITLE

Compliance Officer A

DATE

11/18/20

Conditions of Approval (if any):