

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-34091
5. Indicate Type of Lease STATE [X] FEE [ ]
6. State Oil & Gas Lease No. B-2148
7. Lease Name or Unit Agreement Name Shahara State
8. Well Number 010
9. OGRID Number 328733
10. Pool name or Wildcat [43329] MALJAMAR,GRAYBURG-SAN ANDRES

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)
1. Type of Well: Oil Well [X] Gas Well [ ] Other [ ]
2. Name of Operator Flint Oak Energy, LLC
3. Address of Operator 1703 Westfield Loop Rd Houston, Tx. 77073
4. Well Location Unit Letter F : 2625 feet from the North line and 1335 feet from the West line
Section 16 Township 17S Range 33E NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4191 GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK [X] PLUG AND ABANDON [ ]
TEMPORARILY ABANDON [ ] CHANGE PLANS [ ]
PULL OR ALTER CASING [ ] MULTIPLE COMPL [ ]
DOWNHOLE COMMINGLE [ ]
CLOSED-LOOP SYSTEM [ ]
OTHER: [ ]
SUBSEQUENT REPORT OF:
REMEDIAL WORK [ ] ALTERING CASING [ ]
COMMENCE DRILLING OPNS [ ] P AND A [ ]
CASING/CEMENT JOB [ ]
OTHER: [ ]

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1. Move in and rig up well servicing equipment.
2. Pull all downhole production equipment
3. Clean out fill from production casing as necessary.
4. Replace all failed production equipment as necessary.
5. Release well servicing equipment.
6. Place well on production to common facility.

Anticipated start date - 01/15/2021

Spud Date: [ ]

Rig Release Date: [ ]

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Operations Manager DATE 12-23-2020

Type or print name Jeff Stevenson E-mail address: jeff@oaknrg.com PHONE: 832-262-9521

For State Use Only

APPROVED BY: [Signature] TITLE Compliance Officer A DATE 1/29/21
Conditions of Approval (if any)