

Submit 1 Copy To Appropriate District Office
 District I – (575) 393-6161
 1625 N. French Dr., Hobbs, NM 88240
 District II – (575) 748-1283
 811 S. First St., Artesia, NM 88210
 District III – (505) 334-6178
 1000 Rio Brazos Rd., Aztec, NM 87410
 District IV – (505) 476-3460
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Form C-103
 Revised July 18, 2013

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-34179
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator Flint Oak Energy, LLC		6. State Oil & Gas Lease No. B-2148
3. Address of Operator 1703 Westfield Loop Rd Houston, Tx. 77073		7. Lease Name or Unit Agreement Name Shahara State
4. Well Location Unit Letter K : 2630 feet from the South line and 2307 feet from the West line Section 16 Township 17S Range 33E NMPM County Lea		8. Well Number 014
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4185' GR		9. OGRID Number 10. Pool name or Wildcat [43329] MALJAMAR;GRAYBURG-SAN ANDRES

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☒	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
DOWNHOLE COMMINGLE ☐	P AND A ☐
CLOSED-LOOP SYSTEM ☐	CASING/CEMENT JOB ☐
OTHER: ☐	OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.


1. Move in and rig up well servicing equipment.
2. Pull all downhole production equipment.
3. Clean out fill from production casing as necessary.
4. Replace all failed production equipment as necessary.
5. Release well servicing equipment.
6. Place well on production to common facility.

Anticipated start date - 01/15/2021

Spud Date:


Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE Operations Manager DATE 12-23-2020

Type or print name Jeff Stevenson E-mail address: jeff@oaknrg.com PHONE: 832-262-9521

For State Use Only

APPROVED BY:  TITLE Compliance Officer A DATE 1/29/21

Conditions of Approval (if any)