	UNITED	STATES	OCD-HO	NRRS	1	FORM APPROVED		
orm 3160- 5HOBBS OCD UNITED STATES OCD-HOBBS					OMB No 1004- 0137			
AUG 2 9 2011	BUREAU OF LANI	D MANAGEME	NT			Expires July 31, 2010		
SUNDRY NOTICES AND REPORTS ON WELLS					5 Lease Serial No NMNM118720			
RECEIVED Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6 If Indian, All	ottee, or Tribe Name		
	TRIPLICATE - Other In:			s.	7 If Unit or CA	A Agreement Name and/or No		
Type of Well			JC 2.	· · · · ·	-			
X Oil Well Gas Well Other					8 Well Name a			
2 Name of Operator					9 API Well No	erson B-52 Federal #4	H	
3a Address	COG Operating LLC 3b Phone No. (include area code)				-			
2208 W. Main Street	2208 W. Main Street			575-748-6946		30-025-39289		
Artesia, NM 88210 4 Location of Well (Footage, Sec., T., R., A	M, or Survey Description)	Lat.				ool, or Exploratory Area k; Bone Spring, Nort	h l	
2310' FSL & 660' FWL Unit L (NWSW)					11 County or F			
Sec 5-T19S-R32E		Long			Le	a NN	1	
2. CHECK APPROPRIATE BOX	(S) TO INDICATE NATU	RE OF NOTICE,	REPORT,	OR OTHER I	DATA			
TYPE OF SUBMISSION			TYPE	OF ACTION		.		
Notice of Intent	Acidize	Deepen	[Production (S	itart/ Resume)	Water Shut-off		
	Altering Casing	Fracture Trea	ıt [Reclamation		Well Integrity		
X Subsequent Report	Casing Repair	New Constru	ction	Recomplete		X Other		
	Change Plans	Plug and abar	ndon [Temporarily A	bandon	Completion Ope	rations	
			L					
If the proposal is to deepen direc Attach the Bond under which the v following completion of the involved	tionally or recomplete horizont work will performed or provide d operations If the operation	ally, give subsurface the Bond No on results in a multiple	locations an file with the completion of	nd measured and BLM/ BIA Re or recompletion	any proposed w l true vertical de quired subsequent in a new interva	epths or pertinent markers reports shall be filed with I, a Form 3160-4 shall be	and sand in 30 day filed ond	
 Describe Proposed or Completed O If the proposal is to deepen direc Attach the Bond under which the v following completion of the involved testing has been completed. Final determined that the site is ready for final 6/13/11 to 6/15/11 MIRU V 	Deperation (clearly state all perti- tionally or recomplete horizont work will performed or provide d operations If the operation Abandonment Notice shall be inspection)	ment details includin ally, give subsurface the Bond No on results in a multiple filed only after all	locations an file with the completion of requirements	starting date of ad measured and BLM/ BIA Re or recompletion s, including recl	any proposed w l true vertical de quired subsequent in a new interva amantion, have b	epths or pertunent markers reports shall be filed with I, a Form 3160-4 shall be een completed, and the c	and sand in 30 day filed ond	
 13. Describe Proposed or Completed O If the proposal is to deepen direct Attach the Bond under which the v following completion of the involved testing has been completed. Final determined that the site is ready for final 6/13/11 to 6/15/11 MIRU V Tag PBTD @ 11050'. 	Dependion (clearly state all perti- tionally or recomplete horizont work will performed or provide d operations If the operation Abandonment Notice shall be inspection)	unent details includin ally, give subsurface the Bond No on results in a multiple filed only after all 2'. Test csg to 30	locations an file with the completion of requirements 0000#. Dril	starting date of ind measured and BLM/ BIA Re for recompletion s, including recl	any proposed w I true vertical de quired subsequent in a new interva amantion, have b	epths or pertunent markers reports shall be filed with I, a Form 3160-4 shall be seen completed, and the o	and sands in 30 day filed onc	
 13. Describe Proposed or Completed O If the proposal is to deepen direct Attach the Bond under which the v following completion of the involved testing has been completed. Final determined that the site is ready for final 6/13/11 to 6/15/11 MIRU V Tag PBTD @ 11050'. 6/16/11 to 7/15/11 Perfora 1011918 gal fluid. 	Departion (clearly state all pertitionally or recomplete horizont work will performed or provide d operations If the operation Abandonment Notice shall be inspection) WSU. Tag DVT @ 8672 te Bone Spring 9500-11	2'. Test csg to 3(030'. Acdz w/90	locations an file with the completion of requirements 0000#. Dril	starting date of ind measured and BLM/ BIA Re for recompletion s, including recl	any proposed w I true vertical de quired subsequent in a new interva amantion, have b	epths or pertunent markers reports shall be filed with I, a Form 3160-4 shall be seen completed, and the o	and sands in 30 day filed onc	
 13. Describe Proposed or Completed O If the proposal is to deepen direct Attach the Bond under which the v following completion of the involved testing has been completed. Final determined that the site is ready for final 6/13/11 to 6/15/11 MIRU V Tag PBTD @ 11050'. 6/16/11 to 7/15/11 Perforat 1011918 gal fluid. 8/1/11 to 8/2/11 MIRU CT 	Departion (clearly state all perti- tionally or recomplete horizont work will performed or provide d operations If the operation Abandonment Notice shall be inspection) WSU. Tag DVT @ 8672 te Bone Spring 9500-11 U & drill out all frac plu	2'. Test csg to 30 030'. Acdz w/90 gs.	locations an file with the completion of requirements 0000#. Dril 006 gal 7 1	starting date of id measured and BLM/ BIA Re for recompletion s, including recl lled out DVT	any proposed w I true vertical de quired subsequent in a new interval amantion, have b C. Circulate c rac w/129776	epths or pertinent markers reports shall be filed with l, a Form 3160-4 shall be eeen completed, and the o lean. 7# sand &	and sand in 30 day filed onc perator ha	
 13. Describe Proposed or Completed O If the proposal is to deepen direct Attach the Bond under which the v following completion of the involved testing has been completed. Final determined that the site is ready for final 6/13/11 to 6/15/11 MIRU V Tag PBTD @ 11050'. 6/16/11 to 7/15/11 Perfora 1011918 gal fluid. 	Departion (clearly state all perti- tionally or recomplete horizont work will performed or provide d operations If the operation Abandonment Notice shall be inspection) WSU. Tag DVT @ 8672 te Bone Spring 9500-11 U & drill out all frac plu	2'. Test csg to 30 030'. Acdz w/90 gs.	locations an file with the completion of requirements 0000#. Dril 006 gal 7 1	starting date of id measured and BLM/ BIA Re for recompletion s, including recl lled out DVT	any proposed w I true vertical de quired subsequent in a new interval amantion, have b C. Circulate c rac w/129776	epths or pertunent markers reports shall be filed with I, a Form 3160-4 shall be seen completed, and the o	and sand in 30 day filed onc perator ha	
 13. Describe Proposed or Completed O If the proposal is to deepen direct Attach the Bond under which the v following completion of the involved testing has been completed. Final determined that the site is ready for final 6/13/11 to 6/15/11 MIRU V Tag PBTD @ 11050'. 6/16/11 to 7/15/11 Perforat 1011918 gal fluid. 8/1/11 to 8/2/11 MIRU CT 	Departion (clearly state all perti- tionally or recomplete horizont work will performed or provide d operations If the operation Abandonment Notice shall be inspection) WSU. Tag DVT @ 8672 te Bone Spring 9500-11 U & drill out all frac plu	2'. Test csg to 30 030'. Acdz w/90 gs.	locations an file with the completion of requirements 0000#. Dril 006 gal 7 1	starting date of id measured and BLM/ BIA Re for recompletion s, including recl lled out DVT	any proposed w I true vertical de quired subsequent in a new interval amantion, have b C. Circulate c rac w/129776	epths or pertinent markers reports shall be filed with 1, a Form 3160-4 shall be seen completed, and the of lean. 7# sand & D FOR RECO	and sand in 30 day filed onc perator ha	
 13. Describe Proposed or Completed O If the proposal is to deepen direct Attach the Bond under which the v following completion of the involved testing has been completed. Final determined that the site is ready for final 6/13/11 to 6/15/11 MIRU V Tag PBTD @ 11050'. 6/16/11 to 7/15/11 Perforat 1011918 gal fluid. 8/1/11 to 8/2/11 MIRU CT 	Departion (clearly state all perti- tionally or recomplete horizont work will performed or provide d operations If the operation Abandonment Notice shall be inspection) WSU. Tag DVT @ 8672 te Bone Spring 9500-11 U & drill out all frac plu	2'. Test csg to 30 030'. Acdz w/90 gs.	locations an file with the completion of requirements 0000#. Dril 006 gal 7 1	starting date of id measured and BLM/ BIA Re for recompletion s, including recl lled out DVT	any proposed w I true vertical de quired subsequent in a new interval amantion, have b C. Circulate c rac w/129776	epths or pertinent markers reports shall be filed with l, a Form 3160-4 shall be eeen completed, and the o lean. 7# sand &	and sand in 30 day filed onc perator ha	
 13. Describe Proposed or Completed O If the proposal is to deepen direct Attach the Bond under which the v following completion of the involved testing has been completed. Final determined that the site is ready for final 6/13/11 to 6/15/11 MIRU V Tag PBTD @ 11050'. 6/16/11 to 7/15/11 Perforat 1011918 gal fluid. 8/1/11 to 8/2/11 MIRU CT 	Dependion (clearly state all pert tionally or recomplete horizont work will performed or provide d operations If the operation Abandonment Notice shall be inspection) WSU. Tag DVT @ 8672 te Bone Spring 9500-11 U & drill out all frac plu 6.5# L-80 tbg @ 8903'.	2'. Test csg to 30 030'. Acdz w/90 gs.	locations an file with the completion of requirements 0000#. Dril 006 gal 7 1	starting date of id measured and BLM/ BIA Re for recompletion s, including recl lled out DVT	any proposed w I true vertical de quired subsequent in a new interval amantion, have b C. Circulate cl rac w/129776 CCEPTE	epths or pertinent markers reports shall be filed with 1, a Form 3160-4 shall be been completed, and the of lean. 7# sand & D FOR RECO 16 2 5 2011 Report Report	and sand in 30 day filed onc perator ha	
 13. Describe Proposed or Completed O If the proposal is to deepen direct Attach the Bond under which the v following completion of the involved testing has been completed. Final determined that the site is ready for final 6/13/11 to 6/15/11 MIRU V Tag PBTD @ 11050'. 6/16/11 to 7/15/11 Perforat 1011918 gal fluid. 8/1/11 to 8/2/11 MIRU CT 	Departion (clearly state all perti- tionally or recomplete horizont work will performed or provide d operations If the operation Abandonment Notice shall be inspection) WSU. Tag DVT @ 8672 te Bone Spring 9500-11 U & drill out all frac plu	2'. Test csg to 30 030'. Acdz w/90 gs.	locations an file with the completion of requirements 0000#. Dril 006 gal 7 1	starting date of id measured and BLM/ BIA Re for recompletion s, including recl lled out DVT	any proposed w I true vertical de quired subsequent in a new interval amantion, have b C. Circulate cl rac w/129776 CCEPTE	epths or pertinent markers reports shall be filed with 1, a Form 3160-4 shall be been completed, and the of lean. 7# sand & D FOR RECO JG 2 5 2011 DF LAND MANAGEME	and sand in 30 day filed onc perator ha	
 13. Describe Proposed or Completed O If the proposal is to deepen direct Attach the Bond under which the v following completion of the involved testing has been completed. Final determined that the site is ready for final 6/13/11 to 6/15/11 MIRU V Tag PBTD @ 11050'. 6/16/11 to 7/15/11 Perfora 1011918 gal fluid. 8/1/11 to 8/2/11 MIRU CTI 8/3/11 to 8/4/11 Set 2 7/8" 	Departion (clearly state all pert tionally or recomplete horizont work will performed or provide d operations if the operation Abandonment Notice shall be inspection) WSU. Tag DVT @ 8672 te Bone Spring 9500-11 U & drill out all frac plu 6.5# L-80 tbg @ 8903'.	2'. Test csg to 30 030'. Acdz w/90 gs.	locations an file with the completion of requirements 0000#. Dril 006 gal 7 1	starting date of id measured and BLM/ BIA Re for recompletion s, including recl lled out DVT	any proposed w I true vertical de quired subsequent in a new interval amantion, have b C. Circulate cl rac w/129776 CCEPTE	epths or pertinent markers reports shall be filed with 1, a Form 3160-4 shall be been completed, and the of lean. 7# sand & D FOR RECO 16 2 5 2011 Report Report	and sand in 30 day filed onc perator ha	
 13. Describe Proposed or Completed O If the proposal is to deepen direct Attach the Bond under which the v following completion of the involved testing has been completed. Final determined that the site is ready for final 6/13/11 to 6/15/11 MIRU V Tag PBTD @ 11050'. 6/16/11 to 7/15/11 Perforat 1011918 gal fluid. 8/1/11 to 8/2/11 MIRU CT 	Departion (clearly state all pert tionally or recomplete horizont work will performed or provide d operations if the operation Abandonment Notice shall be inspection) WSU. Tag DVT @ 8672 te Bone Spring 9500-11 U & drill out all frac plu 6.5# L-80 tbg @ 8903'.	2'. Test csg to 30 030'. Acdz w/90 gs.	locations an file with the completion of requirements 0000#. Dril 006 gal 7 1	starting date of id measured and BLM/ BIA Re for recompletion s, including recl lled out DVT	any proposed w I true vertical de quired subsequent in a new interval amantion, have b C. Circulate cl rac w/129776 CCEPTE	epths or pertinent markers reports shall be filed with 1, a Form 3160-4 shall be been completed, and the of lean. 7# sand & D FOR RECO JG 2 5 2011 DF LAND MANAGEME	and sand in 30 day filed onc perator ha	
 13. Describe Proposed or Completed O If the proposal is to deepen direct Attach the Bond under which the v following completion of the involved testing has been completed. Final determined that the site is ready for final determined that the foregoing is true than (<i>Printed/Typed</i>) 	Departion (clearly state all pert tionally or recomplete horizont work will performed or provide d operations if the operation Abandonment Notice shall be inspection) WSU. Tag DVT @ 8672 te Bone Spring 9500-11 U & drill out all frac plu 6.5# L-80 tbg @ 8903'.	2'. Test csg to 30 030'. Acdz w/90 gs.	locations an file with the completion of requirements 0000#. Dril 006 gal 7 1 ump.	starting date of id measured and BLM/ BIA Re for recompletion s, including recl	any proposed w I true vertical de quired subsequent in a new interval amantion, have b C. Circulate cl rac w/129776 CCEPTE	epths or pertinent markers reports shall be filed with 1, a Form 3160-4 shall be been completed, and the of lean. 7# sand & D FOR RECO JG 2 5 2011 DF LAND MANAGEME	and sand in 30 day filed onc perator ha	
 13. Describe Proposed or Completed O If the proposal is to deepen direct Attach the Bond under which the v following completion of the involved testing has been completed. Final determined that the site is ready for final 6/13/11 to 6/15/11 MIRU V Tag PBTD @ 11050'. 6/16/11 to 7/15/11 Perfora 1011918 gal fluid. 8/1/11 to 8/2/11 MIRU CTI 8/3/11 to 8/4/11 Set 2 7/8" 	Departion (clearly state all pert tionally or recomplete horizont work will performed or provide d operations if the operation Abandonment Notice shall be inspection) WSU. Tag DVT @ 8672 te Bone Spring 9500-11 U & drill out all frac plu 6.5# L-80 tbg @ 8903'.	2'. Test csg to 3(030'. Acdz w/9(gs. Place well on pt	locations an file with the completion of requirements 0000#. Dril 006 gal 7 1 ump.	starting date of id measured and BLM/ BIA Re for recompletion s, including recl lled out DVT	any proposed w I true vertical de quired subsequent in a new interval amantion, have b C. Circulate cl rac w/129776 CCEPTE	epths or pertinent markers reports shall be filed with 1, a Form 3160-4 shall be been completed, and the of lean. 7# sand & D FOR RECO JG 2 5 2011 DF LAND MANAGEME	and sands in 30 day filed one perator ha	
 13. Describe Proposed or Completed O If the proposal is to deepen direct Attach the Bond under which the v following completion of the involved testing has been completed. Final determined that the site is ready for final determined for the site is ready for final determined for the site is ready for final determined that the site is ready for final determined for the site is ready for final determined for the site is ready for final determined that the site is ready for final determined for the site is ready for the site is ready for final determined for the site is ready for the site is	Apperation (clearly state all pert tionally or recomplete horizont work will performed or provide d operations If the operation Abandonment Notice shall be inspection) WSU. Tag DVT @ 8672 te Bone Spring 9500-11 U & drill out all frac plu 6.5# L-80 tbg @ 8903'.	unent details mcludm ally, give subsurface is the Bond No on results in a multiple filed only after all 2'. Test csg to 30 030'. Acdz w/90 gs. Place well on pu	locations an file with the completion of requirements 000 #. Dril 006 gal 7 1 ump. Regulato 8/18/11	starting date of id measured and BLM/ BIA Re for recompletion s, including recl //2% acid. F	any proposed w true vertical de quired subsequent in a new interval amantion, have b C. Circulate cl rac w/129776 CCEPTE AL BOREAU C CARLS	epths or pertinent markers reports shall be filed with 1, a Form 3160-4 shall be been completed, and the of lean. 7# sand & D FOR RECO JG 2 5 2011 DF LAND MANAGEME	and sand in 30 day filed onc perator ha	

Conditions of approval, if any are attached Approval of this notice does not warrant o							
certify that the applicant holds legal or equitable title to those rights in the subject lease	Office						
which would entitle the applicant to conduct operations thereon							
Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, make it a crime for	r any person knowingly and willfully to make any department or agency of the United						
States any false, fictitiousor fraudulent statements or representations as to any matter within its jurisdiction							

.