

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
HOBBS OGD
OIL CONSERVATION DIVISION
SEP 01 2011
1220 S. St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEPLEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-00398
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator State of NM (formerly Xeric Oil & Gas)		6. State Oil & Gas Lease No.
3. Address of Operator 1625 N. French Drive Hobbs, NM 88240		7. Lease Name or Unit Agreement Name Mesa Queen Unit
4. Well Location Unit Letter G 1980 feet from the North line and 1980 feet from the East line Section 16 Township 16S Range 32E NMPM County Lea		8. Well Number #008
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 25482
		10. Pool name or Wildcat Mesa Queen

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 19.15.7.14 NMAC. For Multiple Completions. Attach wellbore diagram of proposed completion or recompletion.

See attached Plugging Procedure

The Oil Conservation Division Must be notified
24 hours prior to the beginning of plugging operations.

Spud Date

Rig Release Date

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Maxey G. Brown TITLE Compliance Officer DATE 9/1/2011
Type or print name Maxey G. Brown E-mail address _____ PHONE: 575-393-6161
For State Use Only

APPROVED BY [Signature] TITLE STATE MGR DATE 9-1-2011
Conditions of Approval (if any) _____

SEP 01 2011

State of New Mexico formerly Xeric Oil & Gas Corp
Mesa Queen Unit No. 8

Set CIBP at 3350' and cap w/ 25 sx cmt.
Circulate hole w/ 9.5 ppg brine w/ 25 sx salt gel per 100 bbls.
Perforate at 2500'.
Squeeze w/ 25 sx cmt. WOC and Tag.
Perforate at 1260'.
Squeeze w/ 25 sx cmt. WOC and Tag.
Perforate at 417'.
Circulate cmt to surface.
Cut off wellhead and install dry hole marker.

PLUGGING & ABANDONMENT WORKSHEET

(3 STRING CSNG)

OPERATOR State of NM formerly XERIC OIL & GAS
LEASENAME MESA QUEEN UNIT

WELL # 8
SECT 16 TWN 16S RNG 32E
FROM 1980 (N)SL 1980 (E)WL
TD: 3460 FORMATION @ TD
PBD: 3449 FORMATION @ PBD

13 3/8
@ 367'
TOC Surface
(100 SX)

8 5/8
@ 1265'
TOC PULLED

4 1/2
@ 3460'
TOC
(200 SX)

PBD 3449'
TD 3460'

	SIZE	SET @	TOC	TOC DETERMINED BY	
SURFACE	13 3/8	367'	Surf.	Circ.	
INTMED 1	8 5/8	1265'	?	PULLED	
INTMED 2	4 1/2	3460'	?		
PROD					
	SIZE	TOP	BOT	TOC	DETERMINED BY
LINER 1					
LINER 2					
CUT & PULL @			TOP - BOTTOM		
INTMED 1			PERFS	3402 - 3406	
INTMED 2			OPENHOLE	-	
PROD					

* REQUIRED PLUGS DISTRICT I

RUSTLER (AREA)	1260'	*
YATES BSALT	2500'	
QUEEN		
GRAYBURG		
SAN ANDRES		
CAPTAIN REEF		*
DELAWARE		
BELL CANYON		
CHERRY CANYON		
BERRY CANYON		
BONE SPRING		
OLONIETA		*
BLINERY		
TUBS		
DRINKARD		
ABO		
WC		
PERCH		
STRAWN		
ATOKA		
LABOREW		
ACNE		
ORFORDIAN		

PLUG	TYPE	SACKS	DEPTH
PLUG	PLUG	CMNT	
EXAMPLES			
PLUG #1	OH	25 SXS	9850'
PLUG #2	SHOE	50 SXS	8700'-8800'
PLUG #3	CIBP/35'		5300'
PLUG #4	CIBP	25 SXS	5300'
PLUG #5	STUB	50 SXS	4600'-4700'
PLUG #6	RETR SQZ	200 SXS	400'
PLUG #7	SURF	10 SXS	0-10'
PLUG #8			
PLUG #9			
PLUG #10			
PLUG #11			
PLUG #12			
PLUG #13			
PLUG #14			
PLUG #15			
PLUG #16			
PLUG #17			
PLUG #18			
PLUG #19			
PLUG #20			
PLUG #21			
PLUG #22			
PLUG #23			
PLUG #24			
PLUG #25			