Submit 1 Copy To Appropriate District	State of New Me	xico		Form C-103
Office         Energy, Minerals and Natural Resources		ral Resources		October 13, 2009
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO.	01062
1301 W. Grand Ave., Artesia, NM 88210 OIL CO	ONSERVATION		30-005 5. Indicate Type of Lease	
District III 1000 Rio Brazos Rd., Aztec, NM 87410	20 South St. Fran	icis Dr.	STATE FEE X	
District IV	Santa Fe, NM 87	505	6. State Oil & Gas Lease	
1220 S. St. Francis Dr., Santa Fe, NM SEP 1920 87505	m			
SUNDRY NOTLINES-AND, RE	PORTS ON WELLS		7. Lease Name or Unit A	greement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL) DIFFERENT RESERVOIR. USE "APPLICATION FOR PEI			Drickey Queen Sand Unit	. /
PROPOSALS.)		·	8. Well Number	/
1. Type of Well: Oil Well     Gas Well       2. Name of Operator	Other Injection		9. OGRID Number	
Celero Energy II, LP	,			/128
3. Address of Operator 400 W. Illinois, Ste. 1601			10. Pool name or Wildca	t
Wildland, 1X /9/01			Caprock; Queen	
4. Well Location		11 1 660		
	t from the <u>N</u> wnship 14S Ra	line and <u>660</u>	feet from the <u></u> NMPM Count	
	n (Show whether DR,	<u> </u>		cyChaves 4
12. Check Appropriate I	Box to Indicate N	ature of Notice, R	eport or Other Data	
NOTICE OF INTENTION			EQUENT REPORT	
PERFORM REMEDIAL WORK PLUG AND	·	REMEDIAL WORK	· · · · · · · · · · · · · · · · · · ·	
		COMMENCE DRILL		
		CASING/CEMENT		
THER:	X	OTHER:		П
<ol> <li>Describe proposed or completed operation of starting any proposed work). SEE RUL</li> </ol>	s. (Clearly state all p	pertinent details, and	give pertinent dates, inclu bletions: Attach wellbore	ding estimated date diagram of
proposed completion or recompletion.				C C
1)□Washover 2-3/8" tubing and POOH with wa	shpipe.			
2) Freepoint 2-3/8" tubing and cut at 2804'. PC	OOH with 2-3/8	" tubing.		
3)□RIH with 1" tubing and spot 25 sx Class C a	it 2840'. PU 1000', V	WOC a total of 4 hour	s, RIH and tag TOC at/ab	ove 2704'.
Circulate minimum 9.5 ppg salt mud to 1960'. I 4) Derf (4) at 1960'. RIH with packer and sque	OOH w/1" tubing. I	POOH w/2-3/8" tubin	g. A hours BBIU and tag '	TOC at/above
1850'. Circulate minimum 9.5 ppg salt mud to 1	308'. POOH.		n 4 nouis, KDIri anu tag	
5) Perf (4) at 1308'. RIH with packer and sque	eze 60 sx Class C. F	OOH, WOC a total o	of 4 hours, RBIH and tag '	roc at/above
1180'. Circulate minimum 9.5 ppg salt mud to 2	25'. POOH.			
6)□Perf (4) at 225'. Fill 5-1/2" casing and casin 7)□Set P&A marker and clean location.	ig annulus to surface	with 100 sx Class C.		
Minimum 9.5 ppg salt mud between plugs. All	plugs are Class C cer	nent with 2% CaCl2.		
·····		f		
bud Date:	Rig Release Da	te:		
nereby certify that the information above is true ar	nd complete to the be	st of my knowledge a	and belief.	
n . 1				
GNATURE LIDA HUNT	TITLE Regulat	orv Analyst	DATE 09/	16/2011
			DATE_09/	10/2011
ype or print name Lisa Hunt	E-mail address	: <u>lhunt@celeroenerg</u>	y.com PHONE: (	(432)686-1883
or State Use Only				
PPROVED BY:	TITLE 5	AP MGZ	- DATE 9.	-19-2011
onditions of Approval (if any):				0 2011

SEP 1 9 2011

.



FIELD: LEASE/UNIT: COUNTY:	Caprock Drickey Queen Sand Unit Chaves	DATE: Jun. 10, 2011 BY: MWM WELL: 44 STATE: New Mexico	/:
SPUD: 6/53 COM	S: Work in progress	g well Sundry Notices stated that d in offset wells, and permission was pipe and cement around the 5-1/2"	
	TD @ 4139'. Recovered 8-5/8" cs TOC calc'd @ 2421' w/enlargemen	rotection string. Drld out w/ cable tools og and ran 5-1/2" production csg. nt = 15%; yld = 1.26 ft3/sk tubing (91 jts); tubing cleaned out to 28 (6-53)	
PBTD - 2900 TD - 4139	;		