,	Submit 3 Copies To Appropriate District State of New Mexico	Form C-103	
	District I Energy, Minerals and Natural Resources	May 27, 2004	
	1625 N. French Dr., Hobbs, NM 88240	WELL API NO.	
	District II District II 1301 W Grand Ave, Artesia, NM 88210 District III District District Distr	30-025-25314 5. Indicate Type of Lease	
	District III 1000 Pro Brown Rd Arter NM 87410 and 2011 1220 South St. Francis Dr.	STATE STATE	
	1000 Rio Brazos Rd., Aztec, NM 87410 P 2 2 2011 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.	
	1220 S. St. Francis Dr., Santa Fe, NM	V-3211	
87505 SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name of Omr Agreement Name	
	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Scratchy Ranch State Unit	
	PROPOSALS.) 1. Type of Well: Oil Well 🔯 Gas Well 🗌 Other	8. Well Number 1	
ł	2. Name of Operator	9. OGRID Number	
	EnerVeast Operating	143199 -	
ĺ	3. Address of Operator	10. Pool name or Wildcat Feather	
	1001 Fannin Ste. 800 Houston TX. 77002	Wild-Cat Upper Penn; East	
	4. Well Location		
	Unit Letter J : 2030 feet from the South line and 1980 feet from the East line		
	Section 14 Township 15 S Range 32 E NMPM County Lea		
	11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
	Pit or Below-grade Tank Application _ or Closure _		
	Pit typeDepth to GroundwaterDistance from nearest fresh water well Distance from nearest surface waterN/A		
Pit Liner Thickness: mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
	PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK ALTERING CASING		
		RILLING OPNS. \square P AND A \square	
	PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN		
	OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
	of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
	or recompletion.		
1. POOH. TBG. Laying down RIH. WL. Set CIBP at 10,436'			
2. RIH. TBG. to 10,436' Circulate Hole Mud Laden Fluid Cap with 25sx. Cmt.			
	3. PUH. to 7,500 Spot 25 sx. Cmt. 4. PERF. At 5,000' SQZ. 40 sx Cmt.		
5. PERF at 4230'SQZ. 55 sx. Cmt. WOC & Tag.			
6. PERF. At 450' SQZ. 75 sx. Cmt. WOC & Tag.			
	7. PERF. At 60' Circulate 75 sx. CMT. To Surface. The Oil Conservation Division Must be notified		
	24 hours prior to the beginning of plugging operations.		
		'	
_			
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-			
grade tank has been/will be constructed or closed according to NMOCD guidelines 🛛, a general permit 📋 or an (attached) alternative OCD-approved plan 🗌.			
SIGNATURE MADE TITLE (Basic Energy Services) DATE 9-201			
	Type or print name: E-mail address:	Telephone No. 432-563-3355	
l	For State Use Only		
APPROVED BY DATE 9-26-20			
	Conditions of Approval (if any):	ZE DATE / OF ON	
	-		

÷.

, ,



