

Submit 3 Copies To Appropriate District
Office
District I
1625 N French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

HOBBS OCD

OIL CONSERVATION DIVISION

SEP 28 2011

1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

Apache Corporation

3. Address of Operator

303 Veterans Airpark Lane, Ste. 3000, Midland, TX 79705

4. Well Location

Unit Letter N : 990' feet from the S line and 2300' feet from the W line

Section 2 Township 21S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3467' GL

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ N/A _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
OTHER: drill out & add Plugs ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/12/11 MIRU

9/13/11 Tag existing cmt on CIBP @ 5630'. Circulate hole w/mlf. Tbg @ 5377' - Spot 55 sxs, disp ^{TOC} to 4834' & tag @ 4876'.

9/14/11 Tbg @ 4117 - Spot 25 sxs disp ^{TOC} to 3870'. Perf @ 3200'. Pkr @ 2358' unable to set rate pressure Holding 1000#. Tbg @ 3250'. Spot 50 sxs disp ^{TOC} to 2757' & tag @ 2785'. ^{Sqz.} Called ocd + OK'd to Spot.

9/15/11 Perf @ 2054' unable to sqz pressure holding 1000#. Tbg @ 2103' - Spot 25 sxs & tag @ 1875'. Perf @ 333' unable to sqz pressure holding 700#. Perf @ 60'. Well circ out b/h valve. Tbg @ 383' - Spot 30 sxs. POOH. Flange up wellhead circ 15 sxs cmt to surface.

9/16/11 RDMO. Cut off wellhead and anchors. Install DH marker. ^{Clean location.}

Approved for plugging of well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms for the completion of any pit or below-

I hereby certify that the information above is true and complete to the best of my knowledge and belief, and that the well or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Greg Bryant TITLE P & A Tech (Basic Energy Services) DATE 9-21-11

Type or print name: Greg Bryant

E-mail address:

Telephone No. 432-563-3355

For State Use Only

APPROVED BY: Staff Member TITLE Staff Member DATE 9-29-2011

Conditions of Approval (if any).

SEP 29 2011