Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

HÖBBS	OCD
3.5-	00

Hobbs

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

SEP 29 20.1

Lease Serial No.
 NMD© 0321613

6. If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an inventory.

abandoned well. Use Form 3160-3 (APD) for such proposals 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. X Oil Well Gas Well Other Jack B 26 #8 2. Name of Operator 9. API Well No. ConocoPhillips Company 30-025-37430 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 3a. Address Justis;Blinebry&Tubb-Drinkard 3300 N "A" St, Bldg 6 Midland TX 79705 (432)688-6913 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) F,24S, 37E,26 11. Country or Parish, State Lea <u>1650 FNL 2310 FW</u> 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Well Integrity Reclamation Alter Casing Fracture Treat X Other Add Pay New Construction Casing Repair Recomplete Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Plug Back Water Disposal Convert to Injection Final Abandonment Notice 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) 09/24/10 MIRU 09/28/10 TIH w/retrieving head bailer tbg tag @5700' 42 its 2-7/8" tbg, TOOH w/tbg and bailer 09/29/10 TIH w/retrieving tool, tag @ 5700', clean out 5907', circ clean 09/30/10 Finish TOOH w/tbg and RBP, TIH w/bit tag @6440', clean out to 6500' circ clean, start TOOH w/tbg 10/01/10 Finish TOOH w/tbg and bit, RU hydrostatic, TIH testing production tbg, RD testers 10/04/10 TIH w/pump 6 1-1/2" k-bars w/5-2" flex bars 130 3/4, pick up rods 113 7/8, seat pump load and test to 500 psi, **RDPUMO** ACCEPTED FOR RECORD SEP 2 4 2011 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) BUREAU OF LAND MANAGEMENT Title Regulatory SpecialistARLSBAD FIELD OFFICE Brian D Maiorino Signature Date 09/07/2011 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

(Instructions on page 2)

entitle the applicant to conduct operations thereon.

that the applicant holds legal or equitable title to those rights in the subject lease which would

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.