							C	6 CD- A	
Form 3160-5 (August 2007)			ED STATES OF THE INTERIO	R 1	HOBBS OCD		FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010		
			AND MANAGEMENT				ase Serial No.		
	SUNDR	Y NOTICES A	ND REPORTS O	N WELL	₹P 2 9 2011		NMNM62667		
	abandoned	well. Use Form	oposals to drill or 3160-3 (APD) for si	to re-enter uch propos	an Sals.	6. If I	ndian, Allottee or Tribe Name		
	SUBMIT IN	TRIPLICATE -	Other instruction	s on page	2KECEIVED	7. If U	Jnit or CA/Agreement, Name and	/or No.	
1. Type of Well		,						,	
Oil Well Gas Well Other 2. Name of Operator							8. Well Name and No.		
•	~						Eumont "21" Fed	#1 /	
Mewbourne Oil 3a. Address	Company	···	12h Die . N. C. I I			9. API	I Well No.		
30. I note the factore area code						<u> </u>	30-025-33170-S1		
PO Box 5270, Hobbs, NM 88240 575-393-8905 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)						10. Fie	10. Field and Pool, or Exploratory Area		
	/	, m., or survey Descrip	mon)				Eumont		
660' FSL, 1880' J Sec. 21, T-20-S, 1						111. Co	ounty or Parish, State		
		DDODDIATE DO	V(EC) TO TIME	77.37.4			Lea Co. NM		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, F							OR OTHER DATA		
TYPE OF SUBN	MISSION			TY	PE OF ACTION	1			
_		Acidize	Deepen		Production (Start/Re	sume)	Water Shut-Off		
Notice of Intent		Alter Casing	Fracture Treat	t 🔲	Reclamantion		Well Integrity		
Subsequent Report		Casing Repair	New Construc	ction 🔲	Recomplete	П	Other		
Final Abandanasa	** .*	Change Plans	Plug and Abar	ndon 🔲	Temporarily Abando	n —			
Final Abandonment	Notice	Convert to Injection			Water Disposal				
Attach the Bond ur following completion testing has been condetermined that the sign of th	onder which the in of the involvempleted. Final lite is ready for fir plugging ect cellar. RI sx cement it. Rigged din welder a	work will be perform the operations. If the Abandonment Notices and inspection.) quipment. H w/ 4 1/2 CICI 2911'. POH to down. Cleaned lead to backhoe. Du	nonzontary, give subsur- ned or provide the Bond operation results in a mis shall be filed only aft R. Set @ 2911'. Pr to 2000', spot 70 s oc. moved off,	is No. on file sultiple completer all requirer ressured u	and measured and with BLM/BIA. Reson or recompletion ments, including recompleted pto 1000 psi. POH to 1000	true vertical quired subset in a new in a new in clamantion, h	ded work and approximate durated with depths of all pertinent marker quent reports shall be filed with interval, a Form 3160-4 shall be have been completed, and the stoff retainer. POH. RITHE 10 of retainer to surface to surface to marker. backfilled of the stoff warker. backfilled of the stoff warker.	s and zones. thin 30 days be filed once operator has H open face.	
						1	CEDTED FOR	DECOL	
						AL	CCEPTED FOR	REUUF	
Accepted as to particular Accepted Surface restorat	oona is reta	ined until	RECLA DUE_a		-		SEP 1 8 20 L. Common Survey of Land Mark Carlsbad Field (T: NAGEMENT	
4. I hereby certify that the		ue and correct.)							
Name (Printed/Typed)	•			p.	od Super				
ignature Wi	Muz			Title Ti	1814				
				Date	70 / U				

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereas.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)