Submit 3 Copies To Appropriate District	State of New Mexic	co	Form C-103
Office District 1	Energy, Minerals and Natural	Resources _	May 27, 2004
1625 N French Dr., Hobbs, NM 88240			WELL API NO.
District II 1301 W Grand Ave , Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410	OIL CONSERVATION D	IVISION –	30-025-05799 / 5. Indicate Type of Lease
District III UCT 0 4	2011 1220 South St. Francis	s Dr.	STATE FEE
		5	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM RECEIV			
	AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		TICH L	North Monument G/SA Unit Blk 17/
PROPOSALS)	NTORTERWIT (TORW C-101)TORS		8. Well Number
	/ell Other	,	14
2. Name of Operator		!	9. OGRID Number
Apache Corporation			873 10. Pool name or Wildcat
3. Address of Operator 303 Veterans Airpark Lane, Ste.	3000 Midland TY 79705		Eunice Monument; G/SA
4. Well Location			Eunice Monument, G/SA
	fact from the C	line and 221	Or fact from the W line
	feet from the S		
Section 33 Township 11.	19S Range 37E	NMPM	County Lea
	3557' GR	ND, K1, GK, elc.)	
Pit or Below-grade Tank Application or Clos			
Pit typeDepth to Groundwater	Distance from nearest fresh water	well Distance f	rom nearest surface waterN/A
Pit Liner Thickness: mil Belo	w-Grade Tank: Volume	bbls; Construct	tion Material
12. Check Appro	opriate Box to Indicate Natu	ire of Notice, R	eport or Other Data
NOTICE OF INTE	UTION TO	OUD	
NOTICE OF INTE			SEQUENT REPORT OF:
	_	REMEDIAL WORK	
-	1	COMMENCE DRII	
-		CASING/CEMENT	JOB
OTHER: drill out & add Plugs		OTHER:	
OTHER: drill out & add Plugs 13. Describe proposed or completed	operations. (Clearly state all pert	OTHER: inent details, and p	give pertinent dates, including estimated date
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work).	operations. (Clearly state all pert	OTHER: inent details, and p	
OTHER: drill out & add Plugs 13. Describe proposed or completed	operations. (Clearly state all pert	OTHER: inent details, and p	give pertinent dates, including estimated date
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work).	operations. (Clearly state all pert SEE RULE 1103. For Multiple C	OTHER: inent details, and p	give pertinent dates, including estimated date
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC	operations. (Clearly state all pert SEE RULE 1103. For Multiple C	OTHER: inent details, and g Completions: Atta	give pertinent dates, including estimated date ch wellbore diagram of proposed completion Approved for plugging of well bore only.
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion.	operations. (Clearly state all pert SEE RULE 1103. For Multiple C	OTHER: inent details, and g Completions: Atta	give pertinent dates, including estimated date ch wellbore diagram of proposed completion Approved for plugging of well bore only. Liability under bond is retained pending receipt
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100°	operations. (Clearly state all pert SEE RULE 1103. For Multiple C	OTHER: cinent details, and good and completions: Attained and completions.	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging)
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC	operations. (Clearly state all pert SEE RULE 1103. For Multiple C	OTHER: cinent details, and good and completions: Attained and completions.	give pertinent dates, including estimated date ch wellbore diagram of proposed completion Approved for plugging of well bore only. Liability under bond is retained pending receipt
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/	operations. (Clearly state all pert SEE RULE 1103. For Multiple C	OTHER: cinent details, and good and completions: Attained and completions.	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2,100° to 2,180° – Run bit to 3,410°. Ci. MLF. Cap BP @ 3,410° w/ 2553	OTHER: cinent details, and good and completions: Attained and completions.	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607°	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2,100° to 2,180° – Run bit to 3,410°. Ci. MLF. Cap BP @ 3,410° w/ 2553	OTHER: cinent details, and good and completions: Attained and completions.	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386 Perf @ 1,430° – Sqz 60sx cm	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2 @ 2,100° to 2,180° – Run bit to 3,410°. Ci. MLF. Cap BP @ 3,410° w/ 25sy	OTHER: cinent details, and general details. Completions: Attact cre hole clean. cre mt.	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386 Perf @ 1,430° – Sqz 60sx cmt 9/21/11Perf @ 211° – Sqz 120sx cmt	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2,100° to 2,180° – Run bit to 3,410°. Ci. MLF. Cap BP @ 3,410° w/ 2553° t – Tag @ 1,263°	OTHER: cinent details, and good proposed to the completions: Attack of the completions of the completion of the completi	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386 Perf @ 1,430° – Sqz 60sx cmt 9/21/11Perf @ 211° – Sqz 120sx cmt	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2,100° to 2,180° – Run bit to 3,410°. Ci. MLF. Cap BP @ 3,410° w/ 2553° t – Tag @ 1,263°	OTHER: cinent details, and good proposed to the completions: Attack of the completions of the completion of the completi	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386 Perf @ 1,430° – Sqz 60sx cmt 9/21/11Perf @ 211° – Sqz 120sx cmt	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2 @ 2,100° to 2,180° – Run bit to 3,410°. Ci. MLF. Cap BP @ 3,410° w/ 25sy	OTHER: cinent details, and good proposed to the completions: Attack of the completions of the completion of the completi	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386 Perf @ 1,430° – Sqz 60sx cmt 9/21/11Perf @ 211° – Sqz 120sx cmt	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2,100° to 2,180° – Run bit to 3,410°. Ci. MLF. Cap BP @ 3,410° w/ 2553° t – Tag @ 1,263°	OTHER: cinent details, and good proposed to the completions: Attack of the completions of the completion of the completi	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386 Perf @ 1,430° – Sqz 60sx cmt Perf @ 60° – Circ 35sx cmt to RDMO. Cut off wellhead an	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2,100° to 2,180° – Run bit to 3,410°. Ci. MLF. Cap BP @ 3,410° w/ 2553° t – Tag @ 1,263° t – Tag @ 1,263° t in 65%x12½ & Sqz 30sx cmt in 6 o surface d anchors. Clean location. Insta	OTHER: cinent details, and general details, and general details, and general details, and general details. The completions: Attack of the clean. The completions of the clean.	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. 4'Hole
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386 Perf @ 1,430° – Sqz 60sx cmt Perf @ 60° – Circ 35sx cmt t RDMO. Cut off wellhead an	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2,100° to 2,180° – Run bit to 3,410°. Ci. MLF. Cap BP @ 3,410° w/ 2550° t – Tag @ 1,263° in 65%x12½ & Sqz 30sx cmt in 60° o surface d anchors. Clean location. Instate is true and complete to the best of the service of the s	OTHER: cinent details, and general details, and general details, and general details, and general details. The completions: Attack of the clean. The completions of the clean details and general details.	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386 Perf @ 1,430° – Sqz 60sx cmt Perf @ 60° – Circ 35sx cmt to RDMO. Cut off wellhead and I hereby certify that the information above grade tank has been/will be constructed or closed	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2,100° to 2,180° – Run bit to 3,410°. Ci. MLF. Cap BP @ 3,410° w/ 2550° t – Tag @ 1,263° t – Tag @ 1,263° t in 6%x12½ & Sqz 30sx cmt in 60 surface d anchors. Clean location. Instate is true and complete to the best of according to NMOCD guidelines \(\tilde{\text{\text{\text{MOCD}}}\) guidelines \(\text{\tex{\tex	OTHER: cinent details, and general permit completions: Attact Attact Tree hole clean. Tag @ 7 Tag @ 7	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. 47 Hole and belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386 Perf @ 1,430° – Sqz 60sx cmt Perf @ 60° – Circ 35sx cmt t RDMO. Cut off wellhead an	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2,100° to 2,180° – Run bit to 3,410°. Ci. MLF. Cap BP @ 3,410° w/ 2550° t – Tag @ 1,263° in 65%x12½ & Sqz 30sx cmt in 60° o surface d anchors. Clean location. Instate is true and complete to the best of the service of the s	OTHER: cinent details, and general permit completions: Attact Attact Tree hole clean. Tag @ 7 Tag @ 7	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386 Perf @ 1,430° – Sqz 60sx cmt Perf @ 60° – Circ 35sx cmt transport RDMO. Cut off wellhead and I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2,100° to 2,180° – Run bit to 3,410°. Ci. MLF. Cap BP @ 3,410° w/ 2550° t – Tag @ 1,263° t in 6%x12¼ & Sqz 30sx cmt in 60 surface d anchors. Clean location. Instate is true and complete to the best caccording to NMOCD guidelines \(\times \), a	OTHER: cinent details, and general permit completions: Attact Attact	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. 47 Hole and belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan (Basic Energy Services) DATE 9/26/11
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386 Perf @ 1,430° – Sqz 60sx cmt Perf @ 60° – Circ 35sx cmt to RDMO. Cut off wellhead and I hereby certify that the information above grade tank has been/will be constructed or closed	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2,100° to 2,180° – Run bit to 3,410°. Ci. MLF. Cap BP @ 3,410° w/ 2550° t – Tag @ 1,263° t – Tag @ 1,263° t in 6%x12½ & Sqz 30sx cmt in 60 surface d anchors. Clean location. Instate is true and complete to the best of according to NMOCD guidelines \(\tilde{\text{\text{\text{MOCD}}}\) guidelines \(\text{\tex{\tex	OTHER: cinent details, and general permit completions: Attact Attact	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. 47 Hole and belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386 Perf @ 1,430° – Sqz 60sx cmt Perf @ 60° – Circ 35sx cmt tRDMO. Cut off wellhead an I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE Type or print name: Greg Bryant For State Use Only	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2,100° to 2,180° – Run bit to 3,410°. Cin MLF. Cap BP @ 3,410° w/ 2550° t – Tag @ 1,263° t in 65%x12½ & Sqz 30sx cmt in 60 o surface d anchors. Clean location. Instance is true and complete to the best of according to NMOCD guidelines \(\infty\), a TITLE P&A Tec	OTHER: cinent details, and general permit completions: Attact Attact	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. 4'Hole and belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan . (Basic Energy Services) DATE 9/26/11 Telephone No. 432-563-3355
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386 Perf @ 1,430° – Sqz 60sx cmt Perf @ 60° – Circ 35sx cmt tRDMO. Cut off wellhead an I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE Type or print name: Greg Bryant For State Use Only APPROVED BY:	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2,100° to 2,180° – Run bit to 3,410°. Ci. MLF. Cap BP @ 3,410° w/ 2550° t – Tag @ 1,263° t in 6%x12¼ & Sqz 30sx cmt in 60 surface d anchors. Clean location. Instate is true and complete to the best caccording to NMOCD guidelines \(\times \), a	OTHER: cinent details, and general permit completions: Attact Attact	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. 47 Hole and belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan (Basic Energy Services) DATE 9/26/11
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386 Perf @ 1,430° – Sqz 60sx cmt Perf @ 60° – Circ 35sx cmt tRDMO. Cut off wellhead an I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE Type or print name: Greg Bryant For State Use Only	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2,100° to 2,180° – Run bit to 3,410°. Cin MLF. Cap BP @ 3,410° w/ 2550° t – Tag @ 1,263° t in 65%x12½ & Sqz 30sx cmt in 60 o surface d anchors. Clean location. Instance is true and complete to the best of according to NMOCD guidelines \(\infty\), a TITLE P&A Tec	OTHER: cinent details, and general permit completions: Attact Attact	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. 4'Hole and belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan . (Basic Energy Services) DATE 9/26/11 Telephone No. 432-563-3355
OTHER: drill out & add Plugs 13. Describe proposed or completed of starting any proposed work). or recompletion. 9/15/11MIRU. RIH Tbg – Tag TOC 9/16/11Drill out cmt plug @ 2,100° 9/19/11Tbg @ 3,410° – Circ hole w/Perf @ 2,607° 9/20/11Sqz 60sx cmt – Tag @ 2,386 Perf @ 1,430° – Sqz 60sx cmt Perf @ 60° – Circ 35sx cmt tRDMO. Cut off wellhead an I hereby certify that the information above grade tank has been/will be constructed or closed SIGNATURE Type or print name: Greg Bryant For State Use Only APPROVED BY:	operations. (Clearly state all pert SEE RULE 1103. For Multiple Co. 2,100° to 2,180° – Run bit to 3,410°. Cin MLF. Cap BP @ 3,410° w/ 2550° t – Tag @ 1,263° t in 65%x12½ & Sqz 30sx cmt in 60 o surface d anchors. Clean location. Instance is true and complete to the best of according to NMOCD guidelines \(\infty\), a TITLE P&A Tec	OTHER: cinent details, and general permit completions: Attact Attact	Approved for plugging of well bore only. Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd. 4'Hole and belief. I further certify that any pit or belowan (attached) alternative OCD-approved plan . (Basic Energy Services) DATE 9/26/11 Telephone No. 432-563-3355