Office Energy	State of New Mexico	Form C-103
<u>District I</u> Ellergy,	Minerals and Natural Resource	ces March 4, 2004
1625 N French Dr , Hobbs, NM 88240 District II	•	WELL API NO. 30-025-03879
1301 W Grand Ave , Artesia, NM 88210 OIL CO	ONSERVATI <b>HOEBSYJOH</b>	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd , Aztec, NM 87410	220 South St. Francis Dr.	STATE FEE
District IV	Santa Fe, Not \$7506 2011	6. State Oil & Gas Lease No.
1220 S St Francis Dr, Santa Fe, NM 87505	,	<del>4</del>
SUNDRY NOTICES AND RE	PORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL	OR TO DEEPEN OR YEVE BASED TO:	<b>4</b>
DIFFERENT RESERVOIR USE "APPLICATION FOR PER PROPOSALS)	RMIT" (FORM C-101) FOR SUCH	West Lovington Unit
1. Type of Well:		8. Well Number
Oil Well ☐ Gas Well ☑ Other < →	ATO DY	10
Name of Operator     Chevron Mid Continent L.P	. /	9. OGRID Number 241333
3. Address of Operator 15 Smith Rd, Midland, Tx 79705		10. Pool name or Wildcat West Lovington (San Andres)
4. Well Location		
Unit Letter G : -660 fee	t from the South N line a	and 660 980 feet from the West E line
Section 5 To	wnship 17-S Range 36-E	NMPM Lea County
	1 (Show whether DR, RKB, RT, C	
Pit or Below-grade Tank Application (For pit or below-gra		
		dwaterDistance from nearest fresh water well_over 1000'
Distance from nearest surface water Below-grader		Twp;
feet from the South line and 660 feet from	the West line	
		0.1 5
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND A	TO: ABANDON □ REMEDIA	otice, Report or Other Data  SUBSEQUENT REPORT OF: L WORK
NOTICE OF INTENTION OF PERFORM REMEDIAL WORK PLUG AND A	TO: ABANDON	SUBSEQUENT REPORT OF: L WORK ALTERING CASING CE DRILLING OPNS. PLUG AND ABANDONMENT EST AND
NOTICE OF INTENTION OF PERFORM REMEDIAL WORK PLUG AND A TEMPORARILY ABANDON CHANGE PLUG AND A CHANGE PLUG OTHER:	TO: ABANDON	SUBSEQUENT REPORT OF: L WORK
NOTICE OF INTENTION OF PERFORM REMEDIAL WORK PLUG AND A TEMPORARILY ABANDON CHANGE PLUG AND A PULL OR ALTER CASING MULTIPLE COMPLETION OTHER:  13. Describe proposed or completed operation.	TO: ABANDON	SUBSEQUENT REPORT OF: L WORK ALTERING CASING  CE DRILLING OPNS. PLUG AND ABANDONMENT  EST AND JOB  ails, and give pertinent dates, including estimated date
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND A TEMPORARILY ABANDON CHANGE PL PULL OR ALTER CASING MULTIPLE COMPLETION OTHER:  13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  1. Notified E.L. Gonzalez w/ NM OCD on 9/26/11 2. Tag CIBP @ 4651' Circ hole w/110 bls MLF	TO: ABANDON	SUBSEQUENT REPORT OF:  L WORK ALTERING CASING  CE DRILLING OPNS. PLUG AND ABANDONMENT  EST AND  JOB  ails, and give pertinent dates, including estimated date ons. Aftacht wellagendiagram box proposed completion  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND A TEMPORARILY ABANDON CHANGE PL PULL OR ALTER CASING MULTIPLE COMPLETION OTHER:  13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  1. Notified E.L. Gonzalez w/ NM OCD on 9/26/11 2. Tag CIBP @ 4651' Circ hole w/110 bls MLF 3. Spot 25 sx "c" cmt from 4651'-4404' 4. Perf @ 3000' sqz 55 sx "c" cmt from 3000'-2800	ABANDON	SUBSEQUENT REPORT OF:  L WORK ALTERING CASING  CE DRILLING OPNS. PLUG AND ABANDONMENT  EST AND  JOB  ails, and give pertinent dates, including estimated date  ons: AAttackt we linguading ratio of proposed completion  Liability under bond is retained pending receipt  of C-103 (Subsequent Report of Well Plugging)  which may be found at OCD Web Page under  Forms, www.cmnrd.state.nm.us/ocd.
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND A  TEMPORARILY ABANDON CHANGE PL  PULL OR ALTER CASING MULTIPLE COMPLETIO  OTHER:  13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  1. Notified E.L. Gonzalez w/ NM OCD on 9/26/11 2. Tag CIBP 4651' Circ hole w/110 bls MLF 3. Spot 25 sx "c" cmt from 4651'-4404' 4. Perf 3000' sqz 55 sx "c" cmt from 3000'-2800 5. Perf 2280' sqz 100 sx "c" cmt from 2280'-1927	ABANDON	SUBSEQUENT REPORT OF:  L WORK ALTERING CASING  CE DRILLING OPNS. PLUG AND ABANDONMENT  EST AND  JOB  ails, and give pertinent dates, including estimated date ons: AAttacht we linguading remote proposed completion  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND A TEMPORARILY ABANDON CHANGE PL PULL OR ALTER CASING MULTIPLE COMPLETION OTHER:  13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  1. Notified E.L. Gonzalez w/ NM OCD on 9/26/11 2. Tag CIBP @ 4651' Circ hole w/110 bls MLF 3. Spot 25 sx "c" cmt from 4651'-4404' 4. Perf @ 3000' sqz 55 sx "c" cmt from 3000'-2800	ABANDON	SUBSEQUENT REPORT OF:  L WORK ALTERING CASING  CE DRILLING OPNS. PLUG AND ABANDONMENT  EST AND  JOB  ails, and give pertinent dates, including estimated date ons: AAttacht we linguading remote proposed completion  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
NOTICE OF INTENTION  PERFORM REMEDIAL WORK PLUG AND A  TEMPORARILY ABANDON CHANGE PL  PULL OR ALTER CASING MULTIPLE COMPLETIC  OTHER:  13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  1. Notified E.L. Gonzalez w/ NM OCD on 9/26/11 2. Tag CIBP 4651' Circ hole w/110 bls MLF 3. Spot 25 sx "c" cmt from 4651'-4404' 4. Perf 3000' sqz 55 sx "c" cmt from 3000'-2800 5. Perf 2280' sqz 100 sx "c" cmt from 2280'-1927 6. Perf 410' circ 255 sx "c"cmt down 5 1/2" up th 7. Install Dry Hole Marker P&A complete 9/30/11  I hereby certify that the information above is true ar	REMEDIAL ABANDON COMMENT CASING T CEMENT ON CASING T CEMENT OTHER: s. (Clearly state all pertinent deta E 1103. For Multiple Completion (1 (B.Salt est.)woc tag @ 2784' (7 (T. Salt est./Shoe) woc tag @ 1913 rough 8 5/8" & 13 3/8" Annullus csg to	SUBSEQUENT REPORT OF:  L WORK ALTERING CASING  CE DRILLING OPNS. PLUG AND ABANDONMENT  EST AND  JOB  ails, and give pertinent dates, including estimated date ons: AAttacht we linguading remote proposed completion  Liability under bond is retained pending receipt of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under Forms, www.cmnrd.state.nm.us/ocd.
NOTICE OF INTENTION  PERFORM REMEDIAL WORK PLUG AND A  TEMPORARILY ABANDON CHANGE PL  PULL OR ALTER CASING MULTIPLE COMPLETION  OTHER:  13. Describe proposed or completed operation of starting any proposed work). SEE RULT or recompletion.  1. Notified E.L. Gonzalez w/ NM OCD on 9/26/11 2. Tag CIBP 4651' Circ hole w/110 bls MLF 3. Spot 25 sx "c" cmt from 4651'-4404' 4. Perf 3000' sqz 55 sx "c" cmt from 3000'-2800 5. Perf 2280' sqz 100 sx "c" cmt from 2280'-192' 6. Perf 410' circ 255 sx "c"cmt down 5 1/2" up th 7. Install Dry Hole Marker P&A complete 9/30/11  I hereby certify that the information above is true ar grade tank has been/will be constructed or closed according to the constructed or closed according to	REMEDIAL ABANDON COMMENT CASING T CEMENT ON CASING T CEMENT OTHER: s. (Clearly state all pertinent deta E 1103. For Multiple Completion (1 (B.Salt est.)woc tag @ 2784' (7 (T. Salt est./Shoe) woc tag @ 1913 rough 8 5/8" & 13 3/8" Annullus csg to	SUBSEQUENT REPORT OF:  L WORK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND A TEMPORARILY ABANDON CHANGE PL PULL OR ALTER CASING MULTIPLE COMPLETION OTHER:  13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  1. Notified E.L. Gonzalez w/ NM OCD on 9/26/11 2. Tag CIBP @ 4651' Circ hole w/110 bls MLF 3. Spot 25 sx "c" cmt from 4651'-4404' 4. Perf @ 3000' sqz 55 sx "c" cmt from 3000'-2800 5. Perf @ 2280' sqz 100 sx "c" cmt from 2280'-1927 6. Perf @ 410' circ 255 sx "c"cmt down 5 1/2" up th 7. Install Dry Hole Marker P&A complete 9/30/11 I hereby certify that the information above is true ar grade tank has been/will be constructed or closed according to	REMEDIAL ABANDON	SUBSEQUENT REPORT OF:  L WORK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND A TEMPORARILY ABANDON CHANGE PL PULL OR ALTER CASING MULTIPLE COMPLETIC  OTHER:  13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  1. Notified E.L. Gonzalez w/ NM OCD on 9/26/11 2. Tag CIBP @ 4651' Circ hole w/110 bls MLF 3. Spot 25 sx "c" cmt from 4651'-4404' 4. Perf @ 3000' sqz 55 sx "c" cmt from 3000'-2800 5. Perf @ 2280' sqz 100 sx "c" cmt from 2280'-1927 6. Perf @ 410' circ 255 sx "c" cmt from 2280'-1927 6. Perf @ 410' circ 255 sx "c" cmt down 5 1/2" up th 7. Install Dry Hole Marker P&A complete 9/30/11  I hereby certify that the information above is true ar grade tank has been/will be constructed or closed according to	REMEDIAL ANS COMMENT CASING T CEMENT ON CHER:  s. (Clearly state all pertinent deta E 1103. For Multiple Completion (T. Salt est.)woc tag @ 2784' (T. Salt est./Shoe) woc tag @ 1913 rough 8 5/8" & 13 3/8" Annullus csg to the NMOCD guidelines \( \), a general pertinent deta  TITLE Manage	SUBSEQUENT REPORT OF:  L WORK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND A TEMPORARILY ABANDON CHANGE PL PULL OR ALTER CASING MULTIPLE COMPLETION OTHER:  13. Describe proposed or completed operation of starting any proposed work). SEE RULTOR or recompletion.  1. Notified E.L. Gonzalez w/ NM OCD on 9/26/11 2. Tag CIBP 4651' Circ hole w/110 bis MLF 3. Spot 25 sx "c" cmt from 4651'-4404' 4. Perf 3000' sqz 55 sx "c" cmt from 3000'-2800 5. Perf 2280' sqz 100 sx "c" cmt from 2280'-1927 6. Perf 410' circ 255 sx "c"cmt down 5 1/2" up th 7. Install Dry Hole Marker P&A complete 9/30/11 I hereby certify that the information above is true ar grade tank has been/will be constructed or closed according to SIGNATURE  Type or print name  APPPROVED BY  APPPROVED BY	REMEDIAL ANS COMMENT CASING T CEMENT ON CHER:  s. (Clearly state all pertinent deta E 1103. For Multiple Completion (T. Salt est.)woc tag @ 2784' (T. Salt est./Shoe) woc tag @ 1913 rough 8 5/8" & 13 3/8" Annullus csg to the NMOCD guidelines \( \), a general pertinent deta  TITLE Manage	SUBSEQUENT REPORT OF:  L WORK
NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND A TEMPORARILY ABANDON CHANGE PL PULL OR ALTER CASING MULTIPLE COMPLETION OTHER:  13. Describe proposed or completed operation of starting any proposed work). SEE RUL or recompletion.  1. Notified E.L. Gonzalez w/ NM OCD on 9/26/11 2. Tag CIBP 4651' Circ hole w/110 bis MLF 3. Spot 25 sx "c" cmt from 4651'-4404' 4. Perf 3000' sqz 55 sx "c" cmt from 3000'-2800 5. Perf 2280' sqz 100 sx "c" cmt from 2280'-1927 6. Perf 410' circ 255 sx "c"cmt down 5 1/2" up th 7. Install Dry Hole Marker P&A complete 9/30/11 I hereby certify that the information above is true ar grade tank has been/will be constructed or closed according to SIGNATURE  Type or print name  (This space for State use)	ABANDON	SUBSEQUENT REPORT OF:  L WORK