

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88211
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

HOBBBS OCT 03 2011

OCT 03 2011

RECEIVED

HOBBBS OCT 03 2011

OCT 03 2011

HOBBBS OCT 03 2011

OCT 03 2011

HOBBBS OCT 03 2011

OCT 03 2011

HOBBBS OCT 03 2011

OCT 03 2011

HOBBBS OCT 03 2011

OCT 03 2011

HOBBBS OCT 03 2011

OCT 03 2011

HOBBBS OCT 03 2011

OCT 03 2011

HOBBBS OCT 03 2011

OCT 03 2011

HOBBBS OCT 03 2011

OCT 03 2011

HOBBBS OCT 03 2011

OCT 03 2011

HOBBBS OCT 03 2011

WELL API NO. 30-025-26785	
7. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
7. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name State GR	
8. Well Number 001	
9. OGRID Number 190595	
10. Pool name or Wildcat Salado Draw; Wolfcamp (Gas)	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☒
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/1/2011-9/29/2011

Ran 5 1/2" 20# P110 Tie back liner from 11911 to surface x Cemented with 250sx Cmt x TOC estimated at 8500ft

Stage 1 - Perforated 13530-13843ft X Frac Job X CIBP set at 13510ft

Stage 2 - Perforated 13294-13472ft X Frac Job X CIBP set at 13250ft

Stage 3 - Perforated 13075-13224ft X Frac Job

CIBP stuck in well at 12050ft preparing to perforated Stage 4

Bit x DC and tubing currently stuck in the well at 12050ft x FCP 5900psi

Filed C104 Request for test allowable to bleed casing pressure low enough to kill well and continue completion operations

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Billy E. Prichard

TITLE **Agent for Endeavor Energy**

DATE

9/29/2011

Type or print name **Billy E. Prichard**

E-mail address: **billy@pwlle.net**

PHONE: 4329347680

For State Use Only

APPROVED BY:

[Signature]

TITLE

PETROLEUM ENGINEER

DATE

OCT 11 2011

Conditions of Approval (if any):

OCT 11 2011