Submit I Copy To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resources	Form C-103 October 13, 2009
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 COLL CONSERVATION DIVISION District III 1000 Ris Burger Bd. Artes. NM 87410	30-005-01129 5. Indicate Type of Lease
	STATE FEE X
$\frac{District IV}{1220 \text{ S. St. Francis Dr., Santa Fe, NM}} \text{OCT 112011} \\ \text{Santa Fe, NM} \text{OCT 112011} \\ \text{OCT 112011} $	6. State Oil & Gas Lease No.
87505	
SUNDRY NOT OF SASEAREPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Drickey Queen Sand Unit
PROPOSALS.) 1. Type of Well: Oil Well 🔀 Gas Well 🗌 Other	8. Well Number 49
2. Name of Operator Celero Energy II, LP	9. OGRID Number 247128
3. Address of Operator 400 W. Illinois, Ste. 1601	10. Pool name or Wildcat
Midland, TX 79701	Caprock; Queen
4. Well Location	
Unit Letter B : 660 feet from the N line and 1980 feet from the E line	
Section 22 Township 14S Range 31E	NMPM CountyChaves
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
TEMPORARILY ABANDON 🖾 CHANGE PLANS 🗌 COMMENCE DRI	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	ГЈОВ 🗌 .
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
_of starting any proposed work). SEE-RULE 19.15.7.14 NMAC. For Multiple-Completions:-Attach-wellbore-diagram-of	
"Request 3 year temporary abandoned status. Recently tested production casing & put well on production test. Test was	
unsuccessful; however the well has potential utility in the event a CO2 pilot project on the Rock Queen Unit to the North is successful	
& the project is expanded field wide."	
Procedure:	
Procedure: 1. POOH w/ production equipment. 3000 2. RIH w/ CIBP on tbg & set @ roughly 2950.	
3. Circulate hole w/ packer fluid_& perfrom_pressure_testPOOH_w/_tubing & shut well in.	
Rule 19.15.25.14 Set CIBP, RBP or Packer within 100 feet of uppermost	
perfs or open hole Pressure test to 500 psi for 30 minutes with Cond	Ition of Approval Notify OCD Hobbs
a pressure drop of <u>not greater</u> than 10% over a office 30 minute period	24 hours prior of running MIT Test & Chart
SI - case Date.	
The Oil Conservation Division Must be notified	
24 hours prior to the beginning of	
I to the best of my knowledge and belief.	
SIGNATURE THAT TITLE Regulatory Analyst	DATE 10/11/2011
Type or print name Lisa Hunt E-mail address: lhunt@celeroene	rgy.com PHONE: (432)686-1883
For State Use Only	
APPROVED BY TITLE STAFF MAR DATE /0-11-2011	
Conditions of Approval (if any);	······································
	OCT 1 3 2011

