This form is <u>not</u> to be used for reporting packer leakage tests in Southeast New Mexico

NEW MEXICO OIL CONSERVATION DIVISION

NORTHWEST NEW MEXICO PACKER LEAKAGE TE

Well

Operator Williams Exploration and Production Lease

Name Rosa Unit

No. <u>80</u>

ed June 10, 2003

Location Of Well: Unit Letter K

Sec <u>8</u>

Twp 31N Range 05W

API # 30-0300392253700

	Name of Reservoir or Pool	Type of Prod. (Oil or Gas)	Method of Prod. (Flow or Art. Lift)	Prod. Medium (Tbg. Or Csg.)
Upper Completion	Mesa Verde	Gas	Flow	TBG
Lower Completion	Dakota	Gas	Flow	TBG

Pre-Flow Shut-In Pressure Data

Upper	Hour, Date, Shut-In	Length of Time Shut-In	SI Press. Psig	Stabilized? (Yes or No)
Completion	15:00 3-3-05	120 hu	183	
Lower	Hour, Date, Shut-In	Length of Time Shut-In	SI Press. Psig	Stabilized? (Yes or No)
Completion	15:00 3-3-05	120 hrs	398	

Flow Test No. 1

			FIUW I	C91 14	U. 1	
Commenced at (hour, date)* /4:30 3-8-05				Zone producing (Upper or Lower): Lower		
Time	Lapsed Time	Pre	essure		Prod. Zone	Remarks
(Hour, Date)	Since*	Upper Compl.	Lower Comp	ol.	Temp.	
14:35 3-9-05	24 his	182	/33		83	
310-05	48 hrs	183	131		84	THE WINTE
		_				MAR 2005
						of comply.
	·	,	•			Coming of
						CASISI SI
Production rate	during toot					91 SI VI SILVE

Production rate during test

Oil:	BOPD	based on	_Bbls. In	Hrs	Grav.	GOR
Gas:	60	MCFPD; Test thru (Orifice or Meter):	meter		

Mid-Test Shut-In Pressure Data

Upper	Hour, Date, Shut-In	Length of Time Shut-In	SI Press. Psig	Stabilized? (Yes or No)
Completion				
Lower	Hour, Date, Shut-In	Length of Time Shut-In	SI Press. Psig	Stabilized? (Yes or No)
Completion				

(Continue on reverse side)

Flow Test No. 2

	at (hour, date)**			Zone producing (U	Jpper or Lower):	
Time (Hour, Date)	Lapsed Time Since**		essure Lower Compl.	1	Remarks	
				,	1	111
	a da		:			
			1		1.50 B	
	1		3			
						-
		, tr c .		F		· Ī
i1:	during testBOPD basedMCFPD	on(Orifi	Bbls. In	Hrs.	Grav GOR _	
emarks:	WICHTE), rest unu (Ollin	ce of weter).		in the second se	* 12.
proved	+	· ·	ed is true and co	mplete to the best of Operator	of my knowledge. / When Production	Elplo
w Mexico Oil	Conservation Div	vision			bad Durula	
le <u>SU</u>	PERVISOR DISTE	RICT#3		E-mail Addres	s	
		•		7.	1. A5	1 1

Northwest New Mexico Packer Leakage Test Instructions

- 1. A packer leakage test shall be commenced on each multiply completed well within seven days after actual completion of the well, and annually thereafter as prescribed by the order authorizing the multiple completion. Such tests shall also be commenced on all multiple completions within seven days following recompletion and/or chemical or fracture treatment, and whenever remedial work has been done on a well during which the packer or the tubing have been disturbed. Tests shall also be taken at any time that communication is suspected or when requested by the Division.
- 2. At least 72 hours prior to the commencement of any packer leakage est, the operator shall notify the Division in writing of the exact time the est is to be commenced. Offset operators shall also be so notified.
- The packer leakage test shall commence when both zones of the dual ompletion are shut-in for pressure stabilization. Both zones shall remain hut-in until the well-head pressure in each has stabilized, provided owever, that they need not remain shut-in more than seven days.

For Flow Test No. 1, one zone of the dual completion shall be roduced at the normal rate of production while the other zone remains nut-in. Such test shall be continued for seven days in case of a gas well at 24 hours in the case of an oil well. Note: if, on an initial packer akage test, a gas well is being flowed to the atmosphere due to the lack f a pipeline connection the flow period shall be three hours.

Following completion of Flow Test No. 1, the well shall again be ut-in, in accordance with Paragraph 3 above.

- 6. Flow Test No. 2 shall be conducted even though no leak was indicated during Flow Test No. 1. Procedure for Flow Test No. 2 is to be the same as for Flow Test No. 1 except that the previously produced zone shall remain shut-in while the zone which was previously shut-in is produced.
- 7. Pressures for gas-zone tests must be measured on each zone with a deadweight-pressure gauge at time intervals as follows: 3 hour tests: immediately prior to the beginning of each flow-period, at fifteen-minute intervals during the first hour thereof, and at hourly intervals thereafter, including one pressure measurement immediately prior to the beginning of each flow period, at least one time during each flow period (at approximately the midway point) and immediately prior to the conclusion-of each flow period. Other pressures may be taken as desired, or may be requested on wells which have previously shown questionable test data.

24-hour oil zone tests: all pressures, throughout the entire test, shall be continuously measured and recorded with recording pressure gauges the accuracy of which must be checked at least twice, once at the beginning and once at the end of each test, with a deadweight pressure gauge. If a well is a gas-oil or an oil-gas dual completion, the recording gauge shall be required on the oil zone only, with deadweight pressures as required above being taken on the gas zone.

8. The results of the above-described tests shall be filed in triplicate within 15 days after completion of the test. Tests shall be filed with the Aztec District Office of the New Mexico Oil Conservation Division on Northwest New Mexico Packer Leakage Test Form Revised 11-16-98, with all deadweight pressures indicated thereon as well as the flowing temperatures (gas zones only) and gravity and GOR (oil zones only).