

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO.  
30-025-23991

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

HESS STATE

8. Well Number 1

9. OGRID Number

10. Pool name or Wildcat  
BAGLEY PERMO PENN, NORTH

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH  
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

SMITH & MARRS INC.

3. Address of Operator

BOX 863 KERMIT, TEXAS 79745

4. Well Location

Unit Letter L : 2080 feet from the S line and 690 feet from the W line  
Section 34 Township 11-S Range 33-E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
4271 KB

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type \_\_\_\_\_ Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water \_\_\_\_\_

Pit Liner Thickness: \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐


OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3-14-05 TAG CIBP @ 8620'--DUMP 35' CEMENT ON TOP  
3-15-05 SET CIBP @ 8550' - DUMP 35' CEMENT ON TOP  
3-21-05 SPOT 25 SXS @ 5650'-5407' & TAG  
3-22-05 PULL 3810' OF 5 1/2" CASING  
3-22-05 SPOT 50 SXS @ 3860'-3666' & TAG  
3-22-05 SPOT 35 SXS @ 2200'-2100'  
3-23-05 PULL 442' OF 8 5/8" CASING  
3-23-05 SPOT 75 SXS @ 500'-343' & TAG  
3-23-05 SPOT 20 SXS @ 60' TO SURFACE

INSTALL DRY HOLE MARKER  
CIRCULATED 10# MUD

approved as to plugging of the Well Bore.  
ability under bond is retained until  
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE [Signature] TITLE PRESIDENT DATE 3-28-2005

Type or print name RICKEY SMITH  
No.

E-mail address:

Telephone

For State Use Only

APPROVED BY: [Signature]  
Conditions of Approval (if any):

TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE APR 08 2005