Submit 1 Copy To Appropriate District Office	State of New Me		Form C-103
<u>District I</u>	Energy, Minerals and Natu	ral Resources	October 13, 2009
1625 N French Dr., Hobbs, NM 88240 District II		20.025	API NO.
1301 W. Grand Avc., Artesia, NM 88210		DIVISION 5 India	eate Type of Lease
District III 1220 South St. Francis Dr.		cis Dr.	TATE FEE
1000 Rio Brazos Rd, Aztec, NM 87410 District IV  OCT 26 26 anta Fe, NM 87505		505 6. State	Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			
87505 HOBBSOCD SUNDRY NOTICES AND REPORTS ON WELLS		7 1 625	e Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			e Name of One Agreement Name
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		R SUCH WH LA	AUGHLIN
PROPOSALS.)  1. Type of Well: Oil Well Gas Well Other Injection well.		8. Well	Number 8
2. Name of Operator			ID Number 873
Apache Corp.		7. 001.	Table 1075
3. Address of Operator		10. Poc	I name or Wildcat
P O box Drawer D Monument NM 88265		MONU	MENT ; PADDOCK (47080)
4. Well Location			
Unit LetterF:	1760 feet from the	NORTH line and	1750 feet from the
West line			
Section 9	Township 20S	Range 37E	NMPM Lea County
Section 9 Township 20S Range 37E NMPM Lea County  11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
	11. Elevation (show whether DK,	RRD, RT, OR, etc.)	
では、 では、 は、 は、 は、 は、 は、 は、 は、 は、 は、			146-recover a constraint, debugging all debugges and discount and as a suppression of the constraint and a
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
12. Check Appropriate Box to indicate Nature of Notice, Report of Other Bata			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🔲	REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OF	PNS.□ P AND A □
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JOB	
DOWNHOLE COMMINGLE			
OTHER: Extend TA status		OTUED.	П
OTHER: Extend TA status		OTHER:	
13. Describe proposed or compl		ertinent details, and give per	tinent dates, including estimated date
13. Describe proposed or compl of starting any proposed wo	rk). SEE RULE 19.15.7.14 NMAC	ertinent details, and give per	
13. Describe proposed or compl	rk). SEE RULE 19.15.7.14 NMAC	ertinent details, and give per	
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete.	rk). SEE RULE 19.15.7.14 NMACompletion.	ertinent details, and give per For Multiple Completions:	Attach wellbore diagram of
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete.	rk). SEE RULE 19.15.7.14 NMACompletion.	ertinent details, and give per For Multiple Completions:	Attach wellbore diagram of
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete.	rk). SEE RULE 19.15.7.14 NMACompletion.	ertinent details, and give per For Multiple Completions:	Attach wellbore diagram of
13. Describe proposed or compl of starting any proposed wo	rk). SEE RULE 19.15.7.14 NMACompletion.	ertinent details, and give per For Multiple Completions:	Attach wellbore diagram of
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete.	rk). SEE RULE 19.15.7.14 NMACompletion.	ertinent details, and give per For Multiple Completions:	Attach wellbore diagram of
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete.	rk). SEE RULE 19.15.7.14 NMACompletion.	ertinent details, and give per c. For Multiple Completions: essure up to 520 psi for 32 m	Attach wellbore diagram of inutes.
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete.	rk). SEE RULE 19.15.7.14 NMACompletion.	ertinent details, and give per c. For Multiple Completions: essure up to 520 psi for 32 m	inutes. Extend / YR.
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete.	rk). SEE RULE 19.15.7.14 NMACompletion.	ertinent details, and give per c. For Multiple Completions: essure up to 520 psi for 32 m	Attach wellbore diagram of inutes.
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete.	rk). SEE RULE 19.15.7.14 NMACompletion.	certinent details, and give per c. For Multiple Completions: essure up to 520 psi for 32 m  Condition OCD H	inutes.  Attach wellbore diagram of  ye,  on of Approval: notify  lobbs office 24 hours
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete.	rk). SEE RULE 19.15.7.14 NMACompletion.	certinent details, and give per c. For Multiple Completions: essure up to 520 psi for 32 m  Condition OCD H	inutes. Extend / YR.
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete.	rk). SEE RULE 19.15.7.14 NMACompletion.	certinent details, and give per c. For Multiple Completions: essure up to 520 psi for 32 m  Condition OCD H	inutes.  Attach wellbore diagram of  ye,  on of Approval: notify  lobbs office 24 hours
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete.	rk). SEE RULE 19.15.7.14 NMACompletion.	certinent details, and give per c. For Multiple Completions: essure up to 520 psi for 32 m  Condition OCD H	inutes.  Attach wellbore diagram of  ye,  on of Approval: notify  lobbs office 24 hours
13. Describe proposed or complete of starting any proposed wo proposed completion or recomplete.	rk). SEE RULE 19.15.7.14 NMACompletion.	certinent details, and give per c. For Multiple Completions:  essure up to 520 psi for 32 m  Condition  OCD H  prior of rule	inutes.  Attach wellbore diagram of  ye,  on of Approval: notify  lobbs office 24 hours
13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction.  Intend to move in Gandy pump truck	rk). SEE RULE 19.15.7.14 NMAC ompletion.  to perform MIT on casing. Will pr	certinent details, and give per c. For Multiple Completions:  essure up to 520 psi for 32 m  Condition  OCD H  prior of rule	inutes.  Attach wellbore diagram of  ye,  on of Approval: notify  lobbs office 24 hours
13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction.  Intend to move in Gandy pump truck	rk). SEE RULE 19.15.7.14 NMAC ompletion.  to perform MIT on casing. Will pr	certinent details, and give per c. For Multiple Completions:  essure up to 520 psi for 32 m  Condition  OCD H  prior of rule	inutes.  Attach wellbore diagram of  ye,  on of Approval: notify  lobbs office 24 hours
13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction.  Intend to move in Gandy pump truck	rk). SEE RULE 19.15.7.14 NMAC ompletion.  to perform MIT on casing. Will pr	certinent details, and give per c. For Multiple Completions:  essure up to 520 psi for 32 m  Condition  OCD H  prior of rule  te:	inutes. Extend / yR.  on of Approval: notify lobbs office 24 hours nning MIT Test & Chart
13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction of the starting any proposed wo proposed completion or reconstruction.  Intend to move in Gandy pump truck  Spud Date:	rk). SEE RULE 19.15.7.14 NMAC ompletion.  to perform MIT on casing. Will pr	certinent details, and give per c. For Multiple Completions:  essure up to 520 psi for 32 m  Condition  OCD H  prior of rule  te:	inutes. Extend / yR.  on of Approval: notify lobbs office 24 hours nning MIT Test & Chart
13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction.  Intend to move in Gandy pump truck  Spud Date:	Rig Release Da	certinent details, and give per c. For Multiple Completions:  certinent details, and give per c. For Multiple Completions:  certinent details, and give per c. For Multiple Completions:  Condition OCD H  prior of rule  te:	inutes. Extend yr.  on of Approval: notify lobbs office 24 hours nning MIT Test & Chart
13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction of the starting any proposed wo proposed completion or reconstruction.  Intend to move in Gandy pump truck  Spud Date:	Rig Release Da	certinent details, and give per c. For Multiple Completions:  essure up to 520 psi for 32 m  Condition  OCD H  prior of rule  te:	inutes. Extend / yR.  on of Approval: notify lobbs office 24 hours nning MIT Test & Chart
13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction.  Intend to move in Gandy pump truck  Spud Date:  I hereby certify that the information and starting any proposed wo proposed completion or reconstruction.	Rig Release Da	certinent details, and give per  For Multiple Completions:  Condition  Condition  COD H  prior of rule  te:  st of my knowledge and belication  trument Tech	Attach wellbore diagram of inutes.  Extend yr.  on of Approval: notify lobbs office 24 hours nating MIT Test & Chart  ef.  DATE 10 - 26-11
13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction of the starting any proposed wo proposed completion or reconstruction.  Intend to move in Gandy pump truck  Spud Date:  I hereby certify that the information at the starting any proposed wo proposed completion or reconstruction.  Signature Jim Ellison Jim Ellison	Rig Release Da	certinent details, and give per c. For Multiple Completions:  certinent details, and give per c. For Multiple Completions:  certinent details, and give per c. For Multiple Completions:  Condition OCD H  prior of rule  te:	Attach wellbore diagram of inutes.  Extend yr.  on of Approval: notify lobbs office 24 hours nating MIT Test & Chart  ef.  DATE 10 - 26-11
13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction of the starting any proposed wo proposed completion or reconstruction.  Intend to move in Gandy pump truck  Spud Date:  I hereby certify that the information at the starting any proposed wo proposed completion or reconstruction.  Signature:  Type or print name:  Jim Ellison:  For State Use Only	Rig Release Da  TITLE Ins  E-mail address	certinent details, and give per T. For Multiple Completions:  Condition  Condition  OCD H  prior of rule  te:  st of my knowledge and belief  trument Tech  :_JD.Ellison@apacheccorp.	Attach wellbore diagram of inutes.  On of Approval: notify  Cobbs office 24 hours  Inning MIT Test & Chart  On DATE 10 - 20 - 1  Com_ PHONE:
13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction of the starting any proposed wo proposed completion or reconstruction.  Intend to move in Gandy pump truck  Spud Date:  I hereby certify that the information at SIGNATURE  Type or print name Jim Ellison  For State Use Only  APPROVED BY	Rig Release Da  TITLE Ins  E-mail address	certinent details, and give per T. For Multiple Completions:  Condition  Condition  OCD H  prior of rule  te:  st of my knowledge and belief  trument Tech  :_JD.Ellison@apacheccorp.	Attach wellbore diagram of inutes.  On of Approval: notify  Cobbs office 24 hours  Inning MIT Test & Chart  On DATE 10 - 20 - 1  Com_ PHONE:
13. Describe proposed or complete of starting any proposed wo proposed completion or reconstruction of the starting any proposed wo proposed completion or reconstruction.  Intend to move in Gandy pump truck  Spud Date:  I hereby certify that the information at the starting any proposed wo proposed completion or reconstruction.  Signature:  Type or print name:  Jim Ellison:  For State Use Only	Rig Release Da  TITLE Ins  E-mail address	certinent details, and give per T. For Multiple Completions:  Condition  Condition  OCD H  prior of rule  te:  st of my knowledge and belief  trument Tech  :_JD.Ellison@apacheccorp.	Attach wellbore diagram of inutes.  Extend yr.  on of Approval: notify lobbs office 24 hours nating MIT Test & Chart  ef.  DATE 10 - 26-11