

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-34778
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Monument 11 State
8. Well Number 30
9. OGRID Number
10. Pool name or Wildcat Monument, ABO, North

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:
Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
Chevron USA Inc

3. Address of Operator
15 Smith Rd, Midland, TX 79705

4. Well Location
Unit Letter P : 754 feet from the South line and 330 feet from the East line
Section 11 Township 19-S Range 36-E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL P Sect 11 Twp 19S Rag 36E Pit type Steel Depth to Groundwater 55 Distance from nearest fresh water well Over 1000'
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rag ;
754 feet from the South line and 330 feet from the East line (Steel Tank)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD 24 Hrs Prior to MI & RU.
2. Set 5 1/2 CIBP @ 7075 Spot 25sx Plug 7075-6950 (Lateral, ABO) WOC Tag.
3. Displace Hole W/MLF, 9.5 # Brine w/12.5 # Gel P/BBL.
4. Spot 25sx plug 4400-4200 (S. Andres).
5. Spot 25sx plug 2900-2700 (8 5/8 Shoe) WOC Tag.
6. Cut 5 1/2 CSG @ 2500, L/O CSG.
7. Spot 60sx plug 2550-2400 (Stub) WOC Tag.

8. Spot 60sx plug 1400-1200 (T-Salt).
9. Spot 60sx plug 500-300 (11 3/4 Shoe) WOC Tag.
10. 10sx Surf, Install Dry Hole Marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Jimmy Bagley TITLE Consultant DATE 4-6-05
Type or print name Jimmy Bagley E-mail address: Telephone No. 432 561-8600

(This space for State use)

APPROVED BY Harry W. Wink TITLE OCD FIELD REPRESENTATIVE II / STATE MANAGER DATE APR 11 2005
Conditions of approval, if any:

THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS.

OPERATOR CHEVRON USA INC.
 LEASENAME MONUMENT 11 STATE
 SECT 11 TWN 19-S RNG 36-E
 FROM 754 N5L 330 @WL
 TD: 7491 FORMATION @ TD ABO
 PBTD: FORMATION @ PBTD

	SIZE	SET @	TOC	TOC DETERMINED BY
SURFACE	11 3/4	450	SURF	CIRC
INTMED 1	8 5/8	2794	SURF	CIRC
INTMED 2				
PROD	5 1/2	7315	2500	T.S
	SIZE	TOP	BOT	TOC DETERMINED BY
LINER 1				
LINER 2				
	CUT & PULL @		TOP - BOTTOM	
INTMED 1		PERF		
INTMED 2		OPENHOLE	7135	7463
PROD				

* REQUIRED PLUGS DISTRICT *

PLUG	TYPE	BACKS	DEPTH
PLUG	PLUG	CLINT	
EXAMPLES			
PLUG #1	OH	25 SCS	9850'
PLUG #2	SHOE	50 SCS	8700'-8800'
PLUG #3	CIBP/35'		5300'
PLUG #4	CIBP	25 SCS	5300'
PLUG #5	STUB	50 SCS	4600'-4700'
PLUG #6	RETRN SQZ	200 SCS	400
PLUG #7	SURF	10 SCS	0-10'
PLUG #8	CIBP	25	7075
PLUG #9	S.ANDRES	25	4400
PLUG #10	8 5/8 S	25	2900
PLUG #11	STUB	60	2550
PLUG #12	T.SALT	60	1400
PLUG #13	11 3/4 S	60	500
PLUG #14	SURF	10	10
PLUG #15			
PLUG #16			
PLUG #17			
PLUG #18			
PLUG #19			
PLUG #20			
PLUG #21			
PLUG #22			
PLUG #23			
PLUG #24			
PLUG #25			
PLUG #26			
PLUG #27			
PLUG #28			
PLUG #29			
PLUG #30			
PLUG #31			
PLUG #32			
PLUG #33			
PLUG #34			
PLUG #35			
PLUG #36			
PLUG #37			
PLUG #38			
PLUG #39			
PLUG #40			
PLUG #41			
PLUG #42			
PLUG #43			
PLUG #44			
PLUG #45			
PLUG #46			
PLUG #47			
PLUG #48			
PLUG #49			
PLUG #50			
PLUG #51			
PLUG #52			
PLUG #53			
PLUG #54			
PLUG #55			
PLUG #56			
PLUG #57			
PLUG #58			
PLUG #59			
PLUG #60			
PLUG #61			
PLUG #62			
PLUG #63			
PLUG #64			
PLUG #65			
PLUG #66			
PLUG #67			
PLUG #68			
PLUG #69			
PLUG #70			
PLUG #71			
PLUG #72			
PLUG #73			
PLUG #74			
PLUG #75			
PLUG #76			
PLUG #77			
PLUG #78			
PLUG #79			
PLUG #80			
PLUG #81			
PLUG #82			
PLUG #83			
PLUG #84			
PLUG #85			
PLUG #86			
PLUG #87			
PLUG #88			
PLUG #89			
PLUG #90			
PLUG #91			
PLUG #92			
PLUG #93			
PLUG #94			
PLUG #95			
PLUG #96			
PLUG #97			
PLUG #98			
PLUG #99			
PLUG #100			

PLUG	TYPE	BACKS	DEPTH
PLUG	PLUG	CLINT	
EXAMPLES			
PLUG #1	OH	25 SCS	9850'
PLUG #2	SHOE	50 SCS	8700'-8800'
PLUG #3	CIBP/35'		5300'
PLUG #4	CIBP	25 SCS	5300'
PLUG #5	STUB	50 SCS	4600'-4700'
PLUG #6	RETRN SQZ	200 SCS	400
PLUG #7	SURF	10 SCS	0-10'
PLUG #8	CIBP	25	7075
PLUG #9	S.ANDRES	25	4400
PLUG #10	8 5/8 S	25	2900
PLUG #11	STUB	60	2550
PLUG #12	T.SALT	60	1400
PLUG #13	11 3/4 S	60	500
PLUG #14	SURF	10	10
PLUG #15			
PLUG #16			
PLUG #17			
PLUG #18			
PLUG #19			
PLUG #20			
PLUG #21			
PLUG #22			
PLUG #23			
PLUG #24			
PLUG #25			
PLUG #26			
PLUG #27			
PLUG #28			
PLUG #29			
PLUG #30			
PLUG #31			
PLUG #32			
PLUG #33			
PLUG #34			
PLUG #35			
PLUG #36			
PLUG #37			
PLUG #38			
PLUG #39			
PLUG #40			
PLUG #41			
PLUG #42			
PLUG #43			
PLUG #44			
PLUG #45			
PLUG #46			
PLUG #47			
PLUG #48			
PLUG #49			
PLUG #50			
PLUG #51			
PLUG #52			
PLUG #53			
PLUG #54			
PLUG #55			
PLUG #56			
PLUG #57			
PLUG #58			
PLUG #59			
PLUG #60			
PLUG #61			
PLUG #62			
PLUG #63			
PLUG #64			
PLUG #65			
PLUG #66			
PLUG #67			
PLUG #68			
PLUG #69			
PLUG #70			
PLUG #71			
PLUG #72			
PLUG #73			
PLUG #74			
PLUG #75			
PLUG #76			
PLUG #77			
PLUG #78			
PLUG #79			
PLUG #80			
PLUG #81			
PLUG #82			
PLUG #83			
PLUG #84			
PLUG #85			
PLUG #86			
PLUG #87			
PLUG #88			
PLUG #89			
PLUG #90			
PLUG #91			
PLUG #92			
PLUG #93			
PLUG #94			
PLUG #95			
PLUG #96			
PLUG #97			
PLUG #98			
PLUG #99			
PLUG #100			

