(April 2004) DEPARTMEN BUREAU OF L SUNDRY NOTICES Do not use this form for p	AND REPORTS ON WELLS	FORM APPROVED OMB NO 1004-0137 Expires March 31, 2007SOCD5 Lease Serial No LC-032233 (A)0 3 20116 If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - (Other instructions on reverse side	CEIVED 7 If Unit or CA/Agreement, Name and/or No
 Type of Well X Oil Well Gas Well Other Name of Operator Occidental Permian Ltd. Attn: Ma Address P.O. Box 4294, Houston, TX 77210-4 Location of Well (Footage, Sec., T, R, M, or Survey D 990' FSL & 1650' FEL, Letter 0, Sec)escription)	1 30-023-24003
12. CHECK APPROPRIATE	BOX(ES) TO INDICATE NATURE OF	
TYPE OF SUBMISSION	TY	PE OF ACTION
If the proposal is to deepen directionally or recompl Attach the Bond under which the work will be perf following completion of the involved operations. If	ete horizontally, give subsurface locations and mea formed or provide the Bond No on file with BLM the operation results in a multiple completion or r otices shall be filed only after all requirements. In	Production (Start/Resume) Water Shut-Off Reclamation Well Integrity Recomplete Other <u>Plug well</u> Temporarily Abandon <u>from TD to approx.</u> Water Disposal <u>800'</u> mig date of any proposed work and approximate duration thereof asured and true vertical depths of all pertiment markers and zones t/BIA Required subsequent reports shall be filed within 30 days recompletion in a new interval, a Form 3160-4 shall be filed once cluding reclamation, have been completed, and the operator has
 2) MI x RU pulling unit. ND WH × 3) RIH x tag sand on top of RBP 4) Spot 140' bottom (Grayburg/Sa 5) Spot 126' (Yates) plug. WOC × 6) Spot 115' (surface shoe) plug 	at 3658'. Circulate well with ap an Andres) plug. WOC x tag no sha < tag no shallower than 2508'. g. WOC x tag no shallower than 13 - 800' (bottom fresh water dept	proved plug mud. 11ower than 3543'.
14. I hereby certify that the foregoing is true and correct Name (<i>Printed Typed</i>)	Tıtle	
Mark Stephens		atory Compliance Analyst
Mark Stephen	Date 10/31,	
Approved by	SPACE FOR FEDERAL OR STATE OF	Date
Conditions of approval, if any, are attached. Approval of certify that the applicant holds legal of equitable title to which would entitle the appleant to enduct operations the	this notice does not warrant or hose rights in the subject lease reon	and willfully to make to any department or ageney of the United

Occidental Permian NOI to Plug and Abandon up to 800 feet from surface **Conditions of Approval** North Hobbs Grayburg San Andres 341-30 30-025-24665 Lea County, New Mexico October 13, 2011

- 1. Surface disturbance beyond the existing pad must have prior approval.
- 2. SEE attached General Reequirements
- 3. Operator to have H2S monitoring equipment on location as H2S has been reported from wells in the area.
- 4. Step #3; Spot 140' bottom (Grayburg/San Andres) plug. WOC and tag no shallower than 3543'
- 5. Step#4; Spot 126' (Yates) plug. WOC and tag no shallower than 2508'
- 6. Step#5; Spot 115' (Surface Shoe) plug. WOC and tag no shallower than 1398'
- 7. Step #6 OK
- 8. Subsequent sundry and wellbore schematic required.

EGF 101311