

Submit 1 Copy To Appropriate District Office  
District I - (575) 393-6161  
1625 N French Dr, Hobbs, NM 88240  
District II - (575) 748-1283  
811 S First St, Artesia, NM 88210  
District III - (505) 334-6178  
1000 Rio Brazos Rd, Aztec, NM 87410  
District IV - (505) 476-3460  
1220 S St Francis Dr., Santa Fe, NM, 87505

HOBBS OCD  
NOV 07 2011  
RECEIVED

State of New Mexico  
Energy, Minerals and Natural Resources  
TOILE CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
Revised August 1, 2011

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. 30-025-05368
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Vanguard Permian, LLC		6. State Oil & Gas Lease No. B7896
3. Address of Operator 1209 S. Main Lovington, NM 88260		7. Lease Name or Unit Agreement Name State O
4. Well Location Unit Letter J : 1650 feet from the South line and 2310 feet from the East line Section 31 Township 16S Range 37E NMPM Lea County		8. Well Number 12
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 258350
		10. Pool name or Wildcat Lovington Drinkard

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

\*MIRU. POH w/tbg & Rods.  
\*Rig up reverse Unit. Clean fish out of hole.  
\*Run production tbg, pump & Rods. Hang well on.  
\*Start pumping to State O Tank Battery.

Spud Date: 10/04/2011

Rig Release Date: 11/04/2011

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mike Jones TITLE Production Foreman DATE 11/4/2011  
Type or print name \_\_\_\_\_ E-mail address: \_\_\_\_\_ PHONE: \_\_\_\_\_

For State Use Only

APPROVED BY: [Signature] TITLE State Rep DATE 11-9-2011  
Conditions of Approval (if any): \_\_\_\_\_

NOV 09 2011