Submit 1 Copy To Appropriate District	State of New Mexico		Form C-103
Office <u>District 1</u> – (575) 393-6161	***		October 13, 2009
District I – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM.88240 District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178 1220 South St. Francis Dr.		WELL API NO.	
District II - (575) 748-1283			30-025-26891
811 S. First St., Artesia, NM 88210 " TIL CONSERVATION DIVISION			5. Indicate Type of Lease
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 NOV 0 201 Santa Fe, NM 87505			STATE STATE FEE FED
District IV - (505) 476-3460 NOV U Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM HOBBSOCD			,
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPI	LICATION FOR PERMIT" (FORM C-101) FO	OR SUCH	GGIVA DD 4
PROPOSALS.)			SCHARB 4
1. Type of Well: Oil Well Gas Well Other			8. Well Number: 001
2. Name of Operator			9. OGRID Number 269324
LINN OPERATING, INC.			
3. Address of Operator			10. Pool name or Wildcat
600 TRAVIS, SUITE 5100, HOUSTON, TEXAS 77002			SHARB;BONE SPRING
4. Well Location			
Unit Letter M;	660 feet from the S	line and 66	60 feet from the W line
Section 04			
Section 04	Township 19S	Range 35E	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3,866'			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF BITELTION TO			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL WORK			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRIL			
PULL OR ALTER CASING [MULTIPLE COMPL	CASING/CEMENT	TJOB 🔲
DOWNHOLE COMMINGLE]		
071177	·		
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
I INDI DDODOGEG TO MOVE A WORKOVED BIG OVEC THE COLLARD A #1 TO TRUE GOOD TO THE COLLARD A TRUE			
LINN PROPOSES TO MOVE A WORKOVER RIG ONTO THE SCHARB 4#1 TO TEST THE CSG FOR POSSIBLE LEAKS. LINN			
WILL ISOLATE THE LEAKS AND SQUEEZE THE LEAKS WITH CEMENT. THE LEAKS ARE SUSPECTED DUE TO A			
RECENT INCREASE IN WATER PRODUCTION FROM 1 BWPD TO 10 BWPD.			
,			
			·
		<u> </u>	
Spud Date:	Rig Release Da	ıte:	
•			
			.
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
Thereby serviny that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE LIVE O. COLLARON TITLE: REGULATORY SPECIALIST III. DATE NOVEMBER 2 2011			
SIGNATURE STREET OF CHILDREN TITLE: REGULATORY SPECIALIST III DATE NOVEMBER 2, 2011			
Type or print name TERRY B. CALLAHAN E-mail address: tcallahan@linnenergy.com PHONE: 281-840-4272			
For State Use Only			
APPROVED BY TITLE STATE DATE 11-9-2011			
Conditions of Approval (if any):	THE T	TIT I	7.9 DAIE //-/-(01)
~ " / /			