

## Mull, Donna, EMNRD

---

**From:** Matthew Pride [mattp@pride-energy.com]  
**Sent:** Monday, November 07, 2011 3:56 PM  
**To:** Mull, Donna, EMNRD  
**Subject:** South Four Lakes Unit #15, Lea County, NM; API#: 30-025-36882

Donna,

Here is an e-mail from David Brooks at the NMOCD, Santa Fe, to Jim Bruce (our attorney), addressing the Non Standard Unit exception question that you and I discussed a few days ago. Is this e-mail from David Brooks sufficient for us to attempt to recomple in the Mississippi formation, and then if the recomple is successful then at that time obtain an NSP approval from the NMOCD ?

Thanks Donna,

Matt

Matthew L. Pride  
Pride Energy Company  
P.O. Box 701950  
Tulsa, OK 74170  
(918) 524-9200  
(918) 524-9292 Fax

---

**From:** jamesbruc@aol.com [mailto:jamesbruc@aol.com]  
**Sent:** Monday, November 07, 2011 4:23 PM  
**To:** Matthew Pride  
**Subject:** Fwd: Question

-----Original Message-----

From: Brooks, David K., EMNRD, EMNRD <david.brooks@state.nm.us>  
To: jamesbruc <jamesbruc@aol.com>  
Sent: Mon, Nov 7, 2011 11:23 am  
Subject: RE: Question

I think they can do this. NSP approval is required prior to production.

David

---

**From:** jamesbruc@aol.com [mailto:jamesbruc@aol.com]  
**Sent:** Friday, October 28, 2011 9:40 AM  
**To:** Brooks, David K., EMNRD  
**Subject:** Question

David: I received the question below from a client (Pride Energy). The request is to re-complete but not produce until they get NSP approval (if the recompletion is successful). Please let me know. (Donna Mull asked them to run this by you ) Thanks.

Jim

We plan to recomplete from the Devonian formation up hole in the Mississippian formation in a well. The well location is 2,380 FNL & 2,230 FEL. The OCD says we will need a Non Standard Unit exception. Question: Do we have to get this before we even recomplete or can we recomplete and see whether we will be successful in the recompletion before getting the Non Standard Unit exception?