

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
June 19, 2008

HOBBBS OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
DEC 02 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	7. Lease Name or Unit Agreement Name: <u>Emice Monument South Unit</u>
2. Name of Operator <u>XTO Energy, Inc.</u>	8. Well Number <u>107</u>
3. Address of Operator <u>200 N. Lorraine, Ste. 800 Midland, TX 79701</u>	9. OGRID Number <u>005380</u>
4. Well Location Unit Letter <u>F</u> : <u>1980</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>25</u> Township <u>20S</u> Range <u>36E</u> NMPM County <u>Lea</u>	10. Pool name or Wildcat <u>Emice Monument; Grayburg-San Andres</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) <u>3548' DF</u>	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Reactivation - Acidize - RWTP ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 9-8-11 MIRU PU. RU Rev Unit. MI & rack 127 jts 2 7/8" prod. tbg. RU Hydrostatic TT. RIH w/4 1/2" bit, 6-3 1/2" DC's & 111 jts 2 7/8" prod. tbg. Tag CIBP & 3655'. DO CIBP. Circ hole clean.
9-9-11 RIH clean out OH to 4040' POOH & LD DC's & bit. RIH w/noth collar to 3910'. Dump 1600# 20/40 mesh sand. PUH out of OH.
9-12-11 RIH tag sand @3880'. Clean out sand to 3918'. Circ hole clean. POOH & LD notch collar. RIH & pump 4 sxs CI H cmt. on sand. PUH WOC. RIH & tag cmt @ 3918' RD WL.
9-13-11 RU WL. RIH & tag cmt. @ 3817'. PU & RIH w/sonic hammer tool. RU acid equip. Sonic hammer wash Grayburg OH f/3710 - 3874' w/130 bbls 9# brine @ 4.5 bpm & circ to pit. Sonic hammer acid wash Grayburg f/3710 - 3874' w/3800 gals 20% 90/10 acid @ 2.5 bpm. Flush acid w/25 bbls 9# brine. RD acid equip. PUH out of OH. RU swab, RIH w/swab cups. BFL - 1600' FS. Made 30 runs.
9-15-11 RD swab. POOH w/tbg & LD sonic hammer tool. PU & RIH w/2 7/8" prod. tbg. set @ 3731'. NU WH PU & RIH w/plng & rods. RD MO PU. RWTP.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sharon Hindman TITLE Regulatory Analyst DATE 11/30/2011

Type or print name Sharon Hindman E-mail address: sharon.hindman@ctoenergy.com PHONE 432-620-6741

For State Use Only

APPROVED BY [Signature] TITLE PETROLEUM ENGINEER DATE DEC 02 2011

Conditions of Approval (if any):