30-025-40384



HOBBS OCD

DEC 1 9 2011

RECEIVED

Devon Energy Corporation 20 North Broadway Oklahoma City, Oklahoma 73102-8260

Hydrogen Sulfide (H₂S) Contingency Plan

For

Grizzly Bear "13" Federal COM 1H

LAT. = 32.742316° N (NAD83) LONG = 103.609132°"W 660'FSL & 330 FEL, Sec-13, T-18S R-33E

Lea County NM

Devon Energy Corp. Cont Plan. Page 1

Grizzly Bear "13" Federal COM 1H

This is an open drilling site. H_2S monitoring equipment and emergency response equipment will be used within 500' of zones known to contain H_2S , including warning signs, wind indicators and H_2S monitor.





Escape

Crews shall escape upwind of escaping gas in the event of an emergency release of gas. Escape can be facilitated by traveling 127 feet East on lease road, then turn North on caliche road approximately 0.7 miles. Crews should then block entrance to the location from the lease road so as not to allow anyone traversing into a hazardous area. The blockade should be at a safe distance outside of the ROE. Evacuation should continue if necessary Northeasterly approximately to SR 529. There are no homes or buildings in the ROE.

Assumed 100 ppm ROE = 3000'

100 ppm H₂S concentration shall trigger activation of this plan.

Emergency Procedures

In the event of a release of gas containing H₂S, the first responder(s) must

- Isolate the area and prevent entry by other persons into the 100 ppm ROE.
- Evacuate any public places encompassed by the 100 ppm ROE.
- Be equipped with H₂S monitors and air packs in order to control the release.
- Use the "buddy system" to ensure no injuries occur during the response
- Take precautions to avoid personal injury during this operation.
- Contact operator and/or local officials to aid in operation. See list of phone numbers attached.
- Have received training in the
 - \circ Detection of H₂S, and
 - Measures for protection against the gas,
 - Equipment used for protection and emergency response.

Ignition of Gas Source

Should control of the well be considered lost and ignition considered, take care to protect against exposure to Sulfur Dioxide (SO₂). Intentional ignition must be coordinated with the NMOCD and local officials. Additionally the NM State Police may become involved. NM State Police shall be the Incident Command on scene of any major release. Take care to protect downwind whenever there is an ignition of the gas

Common Name	Chemical Formula	Specific Gravity	Threshold Limit	Hazardovs Limit	Lethal Concentration
Hydrogen Sulfide	H ₂ S	1.189 Air = 1	10 ppm	100 ppm/hr	600 ppm
Sulfur Dioxide	SO ₂	2.21 Air = 1	2 ppm	N/A	1000 ppm

Characteristics of H₂S and SO₂

Contacting Authorities

Devon Energy Corp. personnel must liaison with local and state agencies to ensure a proper response to a major release. Additionally, the OCD must be notified of the release as soon as possible but no later than 4 hours. Agencies will ask for information such as type and volume of release, wind direction, location of release, etc. Be prepared with all information available. The following call list of essential and potential responders has been prepared for use during a release. Devon Energy Corp. Company response must be in coordination with the State of New Mexico's 'Hazardous Materials Emergency Response Plan' (HMER)

Devon Energy Corp. Company Call List

Artesia (575)	Cellular	Office	<u>Home</u>
Foreman – Robert Bell	74 8- 7448		746-2991
Asst. Foreman – Tommy Po	olly.748-5290	748-0165	748-2846
Don Mayberry	•		
Montral Walker			
Engineer – Marcos Ortiz	(405) 317-0666	(405) 552-8152	(405) 381-4350

Agency Call List

.

1

.

Lea	Hobbs	
<u>County</u>	State Police	392-5588
<u>(575)</u>	City Police	397-9265
	Sheriff's Office	
	Ambulance	911
	Fire Department	397-9308
	LEPC (Local Emergency Planning Committee)	393-2870
	NMOCD	393-6161
	US Bureau of Land Management	393-3612
<u>Eddy</u>	Carlsbad	
County	State Police	885-3137
<u>(575)</u>	City Police	
	Sheriff's Office	
	Ambulance	
	Fire Department	885-2111
	LEPC (Local Emergency Planning Committee)	. 887-3798
	US Bureau of Land Management	887-6544
	New Mexico Emergency Response Commission (Santa Fe)	. (505)476-9600
	24 HR	
	National Emergency Response Center (Washington, DC)	. ,

Emergency Services

	Boots & Coots IWC	1-800-256-9688 or (281) 931-8884
	Cudd Pressure Control	(915) 699-0139 or (915) 563-3356
	Halliburton	
	B. J. Services	
Give	Flight For Life - Lubbock, TX	
GPS	Aerocare - Lubbock, TX	
position:	Med Flight Air Amb - Albuquerque, NM	(575) 842-4433
-	Lifeguard Air Med Svc. Albuquerque, NM .	

Prepared in conjunction with Wade Rohloff



.



