HOBBS OCD

Form 3160-5 (August 2007)

UNITED STATES

DEC 20 2019 ARTMENT OF THE INTERIOR D-HOBBS

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires July 31, 2010

5. Lease Serial No. NM 001410

39872

SUNDBY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an

6 If Indian, Allottee or Tribe Name

abandoned well. Use Form 3160-3 (APD) for such proposals.						
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agre	eement, Name and/or No
1. Type of Well Gas W	,			8. Well Name and No Elliott B-17 No. 4	0.	
Name of Operator John H. Hendrix Corporation				9 API Well No. 30-025-24657		
						Exploratory Area
P. O. Box 3040 Midland, TX 79702-3040	432-684-6631			Blinebry Oil & Gas		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey, Description)					11 Country or Parish	n, State
UL G, Sec 17, T22S, R37E (1980' FNL & 1980' FEL)					Lea County, NM	
12 CHEC	K THE APPROPRIATE BO	X(ES) TO INDI	CATE NATURE	OF NOTI	CE, REPORT OR OTI	HER DATA
TYPE OF SUBMISSION		TY	PE OF ACTION			
Notice of Intent ☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans		New (en ire Treat Construction und Abandon	Reco	luction (Start/Resume) amation omplete porarily Abandon	Water Shut-Off Well Integrity Other DHC Blinebry, Tubb, Drinkard zones
Final Abandonment Notice	Convert to Injection	Plug I	Back	Wat	er Disposal	
testing has been completed. Final determined that the site is ready fo 07/29/11 MIRU. POOH. TFF 08/01-05/11 Swedge out tight csg 08/06-16/11 Clean out fill, junk, fro 08/17/11 GIH w/ on/off tool, ba Tubb zone @ 6135′, 08/18/11 Run 4" flush jt scab li 08/19/11 GIH w/ prod tbg. Aci 08/20/11 Swab back spent acid	Abandonment Notices must r final inspection) @ 5764'. Tight spot @ 50 area and trim protruding to m 5755-6220'. Mostly stiller, and clean sand to RB 39', 62', 65', 69', 80', 85', 9 ner - GIH w/ btm pkr, 400' dize Blinebry perfs (5493-d fluids. Rcvd 35 bbls. Fl ds. Return to production. Tubb, 20% Drinkard. DH	be filed only after 003' csg pieces. and. POOH. BP @ 6272'. La 90', 6200', 05', 2 Iliner, top okr, of 5717'), new Tul uid cleaned up.	er all requirement tch on to RBP, 25', 35', 45', 54' on/off tool. Set ob perfs (6135-	released a 15 shots btm @ 505 6254') and	and POOH w/ tbg and POOH. POOH. or and top @ 4650'. Drinkard perfs (637	d tools. GIH and perforate
				_	D(1	REAU OF LAND MANAGEMENT
Signature Landy Done Hayne			Date 09/19/20			CARLSBAD FIELD OF FICE
	THIS SPACE	FOR FEDE	RAL OR ST	ATE OF	FICE USE	
Approved by Conditions of approval, if any, are attache that the applicant holds legal or equitable entitle the applicant to conduct operations	title to those rights in the subje					Date

Title 18 U S.C Section 1001 and Title 43 U S C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

fictitious or fraudulent statements or representations as to any matter within its jurisdiction