

Submit 1 Copy To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources  
HOBBS  
OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
October 13, 2009

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-38036
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator PURVIS OPERATING CO.		6. State Oil & Gas Lease No.
3. Address of Operator PO BOX 51990, MIDLAND, TX 79710-1990		7. Lease Name or Unit Agreement Name BADGER STATE
4. Well Location Unit Letter <u>P</u> : <u>660</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>East</u> line Section <u>6</u> Township <u>15S</u> Range <u>35E</u> NMPM LEA County		8. Well Number <u>1</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. OGRID Number 131559
		10. Pool name or Wildcat MORTON (WOLFCAMP)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

**NOTICE OF INTENTION TO:**  
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

**SUBSEQUENT REPORT OF:**  
REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- On 01/10/12 MIRU CU & RevUnit, tag intermediate plug & displace hole w/9# salt gel.
- Set 35 sack plug of C neat @ 3000'.
- Set 35 sack plug of C neat @ 1800'.
- Perforate intermediate TOC @ 380'.
- Pump 50 sack C w/5% CACL, 450-350', WOC & tag. TAG @ 330' or better
- Set 25 sack surface plug PERF at 60'. CIRC CMT.
- Cutoff heads, weld on plate & marker, cutoff deadmen.

The Oil Conservation Division Must be notified  
24 hours prior to the beginning of plugging operations.

Spud Date:

August 4, 2011

Rig release Date:

September 25, 2011

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Donnie E. Brown*

TITLE

*Agent*  
~~Petroleum Engineer~~

DATE Jan 05, 2012

Type or print name Donnie E. Brown

E-mail address: eng@purvisop.com

PHONE: 432-682-7346

For State Use Only

APPROVED BY:

*Mark Whitaker*

TITLE

*Compliance Officer*

DATE 1-6-2012

Conditions of Approval (if any):

JAN 09 2012

# BADGER Purvis Well Bore

