

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-2004

FILE IN TRIPLICATE

DISTRICT I
1625 N French Dr , Hobbs, NM 88240

DISTRICT II
1301 W Grand Ave, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

OH CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
HOBBS OCD
JAN 17 2012

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)		WELL API NO 30-025-28981
1 Type of Well Oil Well ☒ Gas Well ☐ Other ☐		5 Indicate Type of Lease STATE ☒ FEE ☐
2 Name of Operator Occidental Permian Ltd		6 State Oil & Gas Lease No
3 Address of Operator HCR 1 Box 90 Denver City, TX 79323		7 Lease Name or Unit Agreement Name South Hobbs (G/SA) Unit
4 Well Location Unit Letter <u>E</u> <u>2420</u> Feet From The <u>North</u> <u>213</u> Feet From The <u>West</u> Line Section <u>4</u> Township <u>19-S</u> Range <u>38-E</u> NMPM Lea County		8 Well No <u>186</u>
11. Elevation (Show whether DF, RKB, RT GR, etc) 3622' DF		9 OGRID No <u>157984</u>
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth of Ground Water _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		10 Pool name or Wildcat <u>Hobbs (G/SA)</u>

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG & ABANDONMENT ☐
PULL OR ALTER CASING ☐	Multiple Completion ☐	CASING TEST AND CEMENT JOB ☐	
OTHER: _____	☐	OTHER: <u>Clean out/OAP/Acid treat</u>	☒

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103 For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RUPU & RU.
2. RU wireline & perforate tubing @3943'. RD wireline.
3. NU BOP/ND wellhead.
4. POOH w/ESP equipment.
5. RIH w/bit. Tag @4213'. POOH w/bit. Found split in joint #117.
6. RU wireline and perforate casing @4078-85' 4 JSPF. RD wireline.
7. RU Hydrotest truck & test packer & tubing No leak. Packer set @4026'. RD Hydrotest truck.
8. RU HES & perform rock salt block acid job w/2000 gal of 15% NEFE HCl acid & 1000# gelled rock salt block in 3 stages. Flush w/50 bbl brine water. RD HES. POOH w/packer.
9. RIH w/bit. Tag @4213'. No fill.
10. RU pump truck & pump 100 gal of 6490 chemical mixed w/100 bbl of brine water. Flush w/100 bbl brine water RD pump truck.

see attached sheet for additional data

I hereby certify that the information above is true and complete to the best of my knowledge and belief I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐

SIGNATURE Mendy A. Johnson TITLE Administrative Associate DATE 01/13/2012
TYPE OR PRINT NAME Mendy A. Johnson E-mail address: mendy_johnson@oxy.com TELEPHONE NO 806-592-6280

For State Use Only

APPROVED BY [Signature] TITLE PETROLEUM ENGINEER DATE JAN 17 2012
CONDITIONS OF APPROVAL IF ANY:

JAN 23 2012

SHU 186

11. POOH w/bit.
12. RIH w/ESP equipment set on 121 jts of 2-7/8" tubing. Intake set @3999'.
13. NU wellhead/ND BOP.
14. RDPU & RU. Clean location & return well to production.

RUPU 10/20/2011

RDPU 10/29/2011

Wellbore Diagram : SHOU-186E04

