HOBBS OCD

Submit One Copy To Appropriate Districts 0 2 2 Office	012		Farm C 102
Office	State of New Mexico Energy, Minerals and Natural Resources French Dr , Hobbs, NM 88240 RECEIVED		Form C-103 Revised November 3, 2011
District I 1625 N French Dr , Hobbs, NM 88240 RECEIV	ED, Minerals and Natu	rai Resources	ELL API NO.
District II 811 S First St., Artesia, NM 88210	ISTRICT II		-025-04565 Indicate Type of Lease
District III	1220 South St. Francis Dr.		STATE X FEE
1000 Rio Brazos Rd , Aztec, NM 87410 District IV	100 Rio Brazos Rd, Aztec, NM 87410 Santa Fe, NM 87505		State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, NM	,		
87505 SUNDRY NOTICES AND REPORTS ON WELLS		Lease Name or Unit Agreement Name	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		JG BACK TO A Eu	nice Monument South Unit
1. Type of Well: X Oil Well Gas Well Other		8.	Well Number 337
2. Name of Operator		9.	OGRID Number
XTO Energy, Inc.			5880
3. Address of Operator	1		Pool name or Wildcat
	d, Texas 79701	Eu	nice Monument; Grayburg-San Andres
4. Well Location		√	
Unit Letter O: 660 feet from the South line and 1980 feet from the East line			
	nge <u>36 E</u> NMPM	County Lea	Law and select account of the law and the
Elektrica - Property States	evation (Show whether DR,	·	
12. Check Appropriate Box to Indica	ate Nature of Notice, R	eport or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			ALTERING CASING
TEMPORARILY ABANDON		<u> </u>	
	TIPLE COMPL	CASING/CEMENT JO	
OTHER: D Location is ready for OCD inspection after P&A			
N/A Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. <u>All INFORMATION H</u> AS BEEN WELDED OR			
			IAS BEEN WELDED OR
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
X The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.			
X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
N/A If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location. X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)			
X All other environmental concerns have been addressed as per OCD rules.			
X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines.			
X If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and we			
location, except for utility's distribution infrastructure. (power poles are scheduled to be removed)			
When all work has been completed, return the	nis form to the appropriate I	District office to schedul	e an inspection.
SIGNATURE: Long Husso	TITLE: M	laintenance Foreman	DATE:02/02/2012
TYPE OR PRINT NAME: Gene Hudson E-MAIL: richard_hudson@xtoenergy.com			PHONE: 575-441-1634
For State Use Only APROVED	\(\) \(\)		1
BY: Wash Wtiter TITLE Compliance Officer			DATE 02-07-2012 onditions of \
Approval (if any):	4		,