

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
HOBBS OCE
OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
June 19, 2008

RECEIVED

WELL API NO. 30-025-36046
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name: Hobbs Deep 'A'
8. Well Number 1
9. OGRID Number 157984
10. Pool name or Wildcat Bowers; Seven Rivers
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3671' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	2. Name of Operator Occidental Permian Ltd.
3. Address of Operator P.O. Box 4294, Houston, TX 77210-4294	4. Well Location Unit Letter <u>P</u> : <u>990</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>East</u> line Section <u>13</u> Township <u>18-S</u> Range <u>37-E</u> NMPM County <u>Lea</u>
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3671' GR	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☐ OTHER: Run Production Equipment (& RTP) ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

See Attached

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Mark Stephens TITLE Regulatory Compliance Analyst DATE 1/6/12
Type or print name Mark Stephens E-mail address: Mark_Stephens@oxy.com PHONE (713) 366-5158

For State Use Only

APPROVED BY [Signature] TITLE PETROLEUM ENGINEER DATE FEB 08 2012
Conditions of Approval (if any):

Hobbs Deep 'A' No. 1
API No. 30-025-36046
Sec. 13, T-18-S, R-37-E
Lea Co., NM

12/13/11 - 12/17/11:

MI x RU PU. ND WH x NU BOP. RIH w/7" packer x set at 2924'. Open bypass on packer x circulate well with 140 bbls 10# brine. Kill well with 20 bbls 13.5# mud. Release x POOH x with packer. RIH with 6-1/8" bit x tag at 3255'. Circulate mud out w/10# brine. Clean out frac sand x cement to 3353' x circulate clean. ND BOP x RIH w/104 jts. 2-7/8" production tubing. NU WH x RIH w/rods and 1.25" x 24' 2-stage pump. Space out pump x hang well on. Load x test to 800 psi. RD X MO x clean location.