Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FEB 0 9 2012 OIL CONSERVATION DIVISION FILE IN TRIPLICATE WELL API NO DISTRICT | 1625 N French Dr , Hobbs, NM 88240 RECEIVED 1220 South St. Francis Dr. 30-025-07485 Santa Fe, NM 87505 5 Indicate Type of Lease DISTRICT II FEE STATE X 1301 W Grand Ave, Artesia, NM 88210 6 State Oil & Gas Lease No DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS 7 Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A State Land Section 30 DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals) 8 Well No 1 Type of Well Gas Well Oil Well X 9 OGRID No 16696 2 Name of Operator Oxy USA, Ltd. 10 Pool name or Wildcat Bowers 7 Rivers 3 Address of Operator HCR 1 Box 90 Denver City, TX 79323 4 Well Location Feet From The Line Unit Letter N West Feet From The South 1914 660 NMPM County Range Township 18-S 38-E Lea Section 11 Elevation (Show whether DF, RKB, RT GR, etc.) 3652' GL Pit or Below-grade Tank Application or Closure Distance from nearest fresh water well ______ Distance from nearest surface water Pit Type Depth of Ground Water Pit Liner Thickness Below-Grade Tank: Volume bbls; Construction Material Check Appropriate Box to Indicate Nature of Notice, Report. or Other Data 12. NOTICE OF INTENTION TO: Rule 19.15.25.14 PLUG AND ABANDON PERFORM REMEDIAL WORK Set CIBP, RBP or Packer within 100 feet of uppermost perfs or open hole Pressure test to 500 psi for 30 minutes with CHANGE PLANS TEMPORARILY ABANDON a pressure drop of not greater than 10% over a PULL OR ALTER CASING Multiple Completion 30 minute period OTHER Condition of Approval. Notify OCD Hobbs and give pertinent dates, including estimated date of starting any 13 Describe Proposed or Completed Operations (Clearly state all/ Condition of Approval. Notify OCD Hobbs Test & Chart gram of proposed completion or recompletion proposed work) SEE RULE 1103. For Multiple Completion 1 Kill well. 2. POOH and lay down rods and tubing. Clean out well to 3171'. Circulate clean. RIH w/CIBP and set @3110'. Cap w35' of cement. Test casing and chart for the NMOCD. 5 Install TA well head. The Oil Conservation Division **MUST BE NOTIFIED 24 Hours** Condition of Approval: maify Prior to the beginning of operations I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit of below-grade tank has been/will be or an (attached) a prior of running MIT Test & Chart constructed or closed according to NMOCD guidelines , a general permit plan Administrative Associate SIGNATURE DATE 02/08/2012 TYPE OR PRINT NAME Mendy A. Johnson H-mail address: mendy_johnson@oxy.com TELEPHONE NO 806-592-6280 For State Use Only STATE NATE 2-9-2012 APPROVED BY TITLE CONDITIONS OF APPROVAL