

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 5-27-2004

FILE IN TRIPLICATE

DISTRICT I
1625 N French Dr, Hobbs, NM 88240

DISTRICT II
1301 W Grand Ave, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION
HOBBS OCD 1220 South St. Francis Dr.
Santa Fe, NM 87505

FEB 09 2012

RECEIVED

WELL API NO 30-025-37350
5 Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6 State Oil & Gas Lease No
7 Lease Name or Unit Agreement Name B. Hardin
8 Well No 2
9 OGRID No 192463
10 Pool name or Wildcat Wildcat: Wolfcamp - Hobbs Abo W/C

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)	
1 Type of Well Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	2 Name of Operator Oxy USA WTP Limited Partnership
3 Address of Operator HCR 1 Box 90 Denver City, TX 79323	4 Well Location Unit Letter E 2015 Feet From The North 385 Feet From The West Line Section 19 Township 18-S Range 38-E NMPM Lea County
11 Elevation (Show whether DF, RKB, RTGR, etc) 3657' GL	
Pit or Below-grade Tank Application <input type="checkbox"/> or Closure <input type="checkbox"/> Pit Type _____ Depth of Ground Water _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____	

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ Multiple Completion ☐
OTHER: _____

Rule 19.15.25.14

Set CIBP, RBP or Packer within 100 feet of uppermost perfs or open hole. Pressure test to 500 psi for 30 minutes with a pressure drop of not greater than 10% over a 30 minute period.

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1 Kill well
- 2 POOH & lay down rods & tubing.
- 3 Clean out well to 6657'.
4. RIH w/CIBP set @6607' and cap with 35' cement. Set 2nd CIBP @4000' and cap with 35' cement. Set 3rd CIBP @3400' and cap with 35' cement.
5. Test casing and chart for the NMOCD.
6. Install TA wellhead.

The Oil Conservation Division

MUST BE NOTIFIED 24 Hours

Condition of Approval : Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart

Condition of Approval: notify

I hereby certify that the information above is true and complete to the best of my knowledge and belief, and that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD approved plan ☐

SIGNATURE Mendy A. Johnson TITLE Administrative Associate DATE 02/08/2012
TYPE OR PRINT NAME Mendy A. Johnson E-mail address mendy_johnson@oxy.com TELEPHONE NO 806-592-6280

For State Use Only

APPROVED BY [Signature] TITLE STAFF WGR DATE 2-9-2012
CONDITIONS OF APPROVAL IF ANY