Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
<u>District 1</u> – (575) 393-6161 1625 N. French Dr , Hobbs, NM 88240	strict 1 – (575) 393-6161 Energy, Minerals and Natural Resources		Revised August 1, 2011 WELL API NO.
<u>District II</u> – (575) 748-1283	District II - (575) 748-1283 OH, CONCEDIA TION DIVISION		30-025-08976
<u>District III</u> – (505) 334-6178	011 5. 1 list 5t , Altesia, 1111 60210		5. Indicate Type of Lease  STATE ☐ FEE   ✓
1000 Rio Brazos Rd, Aztec, NM 87410 District IV – (505) 476-3460			6. State Oil & Gas Lease No.
1220 S. St Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			South Eunice Unit
1110100111101			8. Well Number 3
1. Type of Well: Oil Well   Gas Well  Other  Control  Co			9. OGRID Number 02799
Breck Operating Corp.		EB 1 3 2012	
3. Address of Operator	4	FED No. Ch. Dodge Armen	10. Pool name or Wildcat
P.O. Box 911, Breckenridge, TX 7642	+	RECEIVED	Eunice, 7 Rvrs Queen, So.
Unit Letter B: 330 feet from the North line and 1650 feet from the East line			
Section 21 Township 22S Range 36E NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
	·		A Description of the second se
10 01 1			
12. Check App	propriate Box to Indicate N	Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: , SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			<del></del> -
	HANGE PLANS   IULTIPLE COMPL	CASING/CEMEN	RILLING OPNS. P AND A
DOWNHOLE COMMINGLE	IOLITI LE COMIT E	OAGING/OLIVIEI	U 30D
OTHER: OTHER: OTHER: Including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
Estimated starting date 5/1/2012			
<u>CURRENT WELL STATUS</u> <u>PROPOSED PLUGGING PROCEDURE</u>			
1. 8 5/8" csg @ 287', cmt circulated 1. Circ w/ mud 2. 5 1/2" crc @ 2820' TOC @ 170' (cala)			2-3072' (20 sx)
			2-30/2 (20 sx) 0'-1520'. (Perf & sqz w/ 45 sx)
4. CIBP @ 3522' w/ 35' cmt on top. 4. WOC & tag			
5. 100' plug 337'-237' (Perf & sqz w/ 35 sx)			'-237' (Perf & sqz w/ 35 sx)
6. WOC & tag  The Oil Conservation Division Must be notified 7. Surface plug 60'-0' (Perf & sqz 25 sx)			
24 hours prior to the beginning of plugging operations.  8. Install dry hole marker.			
	-········	'9. Clean & Resto	ore Location
0 15			
Spud Date:	Rig Release D	rate:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE TITLE Vice President / Production Mgr. DATE February 7, 2012			
Type or print name <u>Daniel D. Wilson</u> E-mail address: <u>dwilson@breckop.com</u> PHONE: <u>(254) 559-3355</u>			
For State Use Only			
APPROVED BY: Complete TITLE STAFF MATE DATE Z-15-2012			
Conditions of Approval (if any)			

