	UNITED STATES DEPARTMENT OF THE INTER BUREAU OF LAND MANAGEME ( NOTICES AND REPORTS	ENT	RBS HOBBS	5 Lease Sena 012 <sup>NM-147</sup>		99 Ab - 10
	this form for proposals to drill vell. Use Form 3160-3 (APD) fo		7		, Allottee or Tribe Name	
SUBMIT IN TR	RIPLICATE- Other instructions		~	7. If Unit or	CA/Agreement, Name and/	or No.
I. Type of Well ✓ Oil Well	Gas Well Other	/	-	8. Well Nar	ne and No.	
Name of Operator Strata Prod	uction Company			New Mo	exico A Federal 002	
a. Address		Shude area code) 30-025-25751			/	
P.O. Box 1030, Roswell, NM 8	522-1127		d Pool, or Exploratory Area	/		
Location of Well (Footage, Sec. 1980' FNL & 1980 FEL, S4-7		-	or Parish, State			
1900 FILL & 1900 FEL, 54-1		Lea Co	unty, NM			
. 12. CHECK A	APPROPRIATE BOX(ES) TO INDICA	TE NATUR	E OF NOTICE RE		OTHER DATA	<u></u>
TYPE OF SUBMISSION						
Notice of Intent	Acidize Deepe	en	Production (Star	/Resume)	Water Shut-Off	
		ire Treat	Reclamation		Well Integrity	
Subsequent Report		Construction and Abandon				
Final Abandonment Notice	Convert to Injection Plug E		Water Disposal	-		
	iy for final inspection ) any would like to request a paint color va 5 Per ATT. Cor			·	al From A.	D
14 I hereby certify that the for Name (Printed/Typed)		Title Vi	ce President		a <u>an di sana</u>	
Frank S. Morga				/03/2012		
	M	Date				
Frank S. Morga	THIS SPACE FOR FEDER		TATE OFFICE I	JSE		
Frank S. Morga	THIS SPACE FOR FEDER	AL OR S	TATE OFFICE I		rate 2/15/12	
Frank S. Morga Signature Approved by Conditions of approval, if any, are certify that the applicant bolds-lease which would entitle the applicant	attached Approval of this notice does not w al or equitable title to those rights in the subje	ALORS	itle LPET	D		

,

. U. S. Geological Surve

## HOBBS DISTRICT

Cleary Petroleum Corp. No. 2 New Mexico Federal "A" SWWANEWA Sec. 4-21S-32E Lea County, N. M.

Above Data Required on Well Sign

## CONDITIONS OF APPROVAL

- 1. Drilling operations authorized are subject to compliance with the attached General Requirements for Drilling Operations on Federal Oil and Gas Leases, dated January 1, 1977.
- 2. Notify this office (telephone (505) 393-3612) when the well is to be spudded and in sufficient time for a representative to witness all cementing operations. Attached are names and telephone numbers of Geological Survey and Bureau of Land Management personnel who are available for consultation during construction, drilling, completion, and rehabilitation activities.
- 3. Immediate notice is required of all blowouts, fires, spills, and accidents involving life-threatening injuries or loss of life.
- 4. Secure prior approval of the District Engineer for variance from the approved drilling program and before commencing plugging operations, plugback work, casing repair work, corrective cementing operations, or suspending drilling operations indefinitely.
- 5. Blowout prevention equipment is to be installed, tested, and in working order before drilling below the surface casing and shall be maintained ready for use until drilling operations are completed.
- 6. Operator will provide the dirt contractor with a copy of the enclosed Bureau of Land Management "Standard Requirements for all Drilling in Relation to Oil and Gas Activities in the Roswell Distrct" prior to commencing construction of road, pad, or other associated developments.
- 7. Casing protectors will be run on drill pipe while drilling through the 9-5/8" casing. Protectors will be of sufficient number and of sufficient outside diameter to protect the casing.
- 8. After setting the <u>9-5/8</u>" casing string and before drilling into the <u>Pennsylvanian</u> formation, the blowout preventers and related control equipment shall be pressure tested to rated working pressures by an independent service company. Any equipment failing to test satisfactorily shall be repaired or replaced. This office should be notified in sufficient time for a representative to witness the tests and shall be furnished a copy of the pressure test report.
- 9. Mud system monitoring equipment, with derrick floow indicators and visual and audio alarms, shall be installed and operating before drilling into the Pennsylvanian formation and used until production casing is run and cemented. Monitoring equipment shall consist of the following:
  - (1) A recording pit level indicator to determine pit volume gains and losses.
  - (2) A mud volume measuring device for accurately determining mud volume necessary to fill the hole on trips.
  - (3) A flow sensor on the flow-line to warn of any abnormal mud returns from the well.

- 10. In the event the oil or gas test results in a dry hole, the drill pad and access road will be ripped in accordance with "BLM Roswell Districts' Ripping Recommendations for Caliche or Compacted Drill Pads and Access Roads". (Reseeding of the affected areas may be requited at the discretion of the BLM authorized officer).
- 11. All above ground structures, not subject to applicable conservation and safety requirements, shall be painted to blend with the natural surroundings. The paint used should be a nonglare, nonreflective, nonchalking color that simulates Fed. Stand. No. 595, color 30318.
- 12. All ripped surfaces are to be protected from vehicular travel by constructing a dead-end ditch and earthen barricade at the entrance to these ripped areas. The barricade is to be constructed using spoil material from the ditch and should be of sufficient magnitude to discourage vehicle entry.