Submit 3 Copies To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 873000000000000000000000000000000000000	Form C-103
District I	May 27, 2004
1625 N. French Dr., Hobbs, NM 87367	WELL API NO.
1301 W Grand Ave., Artesia, NM 88210	30-025-31724
	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 8741 Santa Fe, NM 87505 District IV	STATE 🗷 FEE 🗌
1000 Rio Brazos Rd., Aztec, NM 87418 Santa Fe, NM 87505 District LV 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name: ARROWHEAD GRAYBURG UNIT
1. Type of Well: Oil Well X Gas Well Other	8. Well Number
2. Name of Operator	9. OGRID Number
XTO ENERGY, INC.	005380
3. Address of Operator	10. Pool name or Wildcat
200 N. LORAINE, SUITE 800, MIDLAND, TEXAS 79701	ARROWHEAD; GRAYBURG
4. Well Location	THEORETZ CANDON
Unit LetterB :760feet from theNORTH line and	1890 feet from the EAST line
Onit Letter	feet from the EAST line
Section 11 Township 22S Range 36E NMPM County LEA	
11. Elevation (Show whether DR, RKB, RT, GR, etc. 3629' - GR	c.)
Pit or Below-grade Tank Application or Closure 🗵	
Pit type STEEL Depth to Groundwater Distance from nearest fresh water well * Distance from nearest surface water *	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material *NONE WITHIN 1,000'.	
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	NG OPNS. ☐ PLUG AND V 🕱 ABANDONMENT
PULL OR ALTER CASING MULTIPLE CASING TEST AND CEMENT JOB Approx	ed for plugging of well bore only.
OTHER: OTHER: OF CAND	Y Under Rivid 16 Fetained pending receipt
13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
02/19/12: SET 5-1/2" CIBP @ 3,600'; PRES. TEST 5-1/2" CSG. TO 500# - HEID OK; CIRC. WELL W/ PXA FLUID; MIX X PUMP A 25 SX. CMT. PLUG @ 3,600'; WCC. 02/20/12: TAG TOP OF CMT. PLUG @ 3,429'; MIX X PUMP A 25 SX. CMT. PLUG @ 2,700'-2,500'(CALC.); MIX X PUMP A 25 SX. CMT. PLUG @ 1,530'; WCC X TAG TOP OF CMT. PLUG @ 1,134'; MIX X CIRC. TO SURF. A 35 SX. CMT. PLUG @ 350'-3'; DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CASINGS X	
INSTALL DRY HOLE MARKER. WELL PLUCCED	AND ABANDONED 02/20/12.
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines X, a general permit or an (attached) alternative OCD-approved plan	
SIGNATURE TITLE AG	
	leyler@milagro-res.com Telephone No. (432) 687-3033
For State Use Only	
APPROVED BY TITLE STAFF	DATE 2-22-20/2
Conditions of Approval, if any:	