

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Department of Minerals and Natural Resources
OCCUPANCY CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505
RECEIVED

Form C-103
June 19, 2008

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-04658
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator XTO Energy, Inc.		6. State Oil & Gas Lease No.
3. Address of Operator 200 N. Loraine, Ste. 800 Midland, TX 79701		7. Lease Name or Unit Agreement Name: Eunice Monument South Unit
4. Well Location Unit Letter G : 1980 feet from the North line and 1980 feet from the East line Section 16 Township 21S Range 36E NMPM County Lea		8. Well Number 383
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3590' GL		9. OGRID Number 005380
		10. Pool name or Wildcat Eunice Monument; Grayburg-San Andres

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: **Reactivation** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

9/16/11 MIRU PU. ND WH NU BOP.
9/19/11 Tag CIBP @ 3728'. DO CIBP. RIH to 3950'. PU & RIH W/2 7/8" notch collar & 2 7/8" tbg
Dump 400# 20/40 Mesh sand
9/20/11 RIH tag sand @ 3936'. POOH w/tbg & notch collar. RU WL. RIH & dump 3 sxs Cl C cmt.
on sand. POOH & RD WL.
9/21/11 PU & RIH w/notch collar & 2 7/8" tbg. Tag cmt/sand @ 3930' PUH dump 200# 20/40 sand &
WOC. Tag sand @ 3921'. POOH & LD notch collar. RU Rotary WL RIH dump 1 sx Cl C cmt.
On sand. RIH w/notch collar & 104 jts 2 7/8 tbg.
9/22/11 RIH tag cmt. @ 3919'. New PBTD @ 3920'. PUH RU swab.
9/26/11 POOH & LD notch collar. RIH w/7" CIBP. Set CIBP @ 3700'. Press TCA to 500 psig for
30 min w/no loss. Circ TCA w/170 lbs FW. POOH & LD 2 7/8" tbg. SWI & SDON
9/27/11 Con't POOH & LD tbg. NU WH. RU pump trk L&T TCA to 500 psig for 30 min on chart
recorder w/no loss. RD pump trk. RDMO PU.

Spud Date:

Rig Release Date:

Shut-In

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sharon Hindman TITLE Regulatory Analyst DATE 10/06/2011

Type or print name Sharon Hindman E-mail address: sharon_hindman@xtoenergy.com PHONE 432-620-6741

For State Use Only

APPROVED BY [Signature] TITLE STAFF DATE 3-1-2012

Conditions of Approval (if any):

MAR 01 2012