Submit 1 Copy To Appropriate District Office	State of New Mexico			Form C-103
District I Energy, Minerals and Natural Resources		WELL API NO.	October 13, 2009	
1625 N French Dr., Hobbs, NM 88240 District II 1301 W Grand Ave, Artesia, NM 88210 1625 N French Dr., Hobbs, NM 88240 CONSERVATION DIVISION			30-025-25212 ✓	
District III 1000 C = -41 C4 E = 1 D =			5. Indicate Type	
1000 Rio Brazos Rd., Aztec, NM 87410 MAR 1 5 2012 Santa Fe NM 87505			STATE [FEE Z
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Ga	s Lease No.
SUNDRY NOTI RES MADE REPORTS ON WELLS			7. Lease Name or	Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			CENTRAL DRINKARD UNIT 8. Well Number 409	
1. Type of Well: Oil Well Gas Well Other INJECTOR			/	
2. Name of Operator CHEVRON U.S.A. INC.			9. OGRID Number 4323	
3. Address of Operator			10. Pool name or Wildcat	
15 SMITH ROAD, MIDLAND, TEXAS 79705			DRINKARD	
4. Well Location				
Unit Letter C: 977 feet from the NORTH line and 2236 feet from the WEST line				
Section 28 Township 21S Range 37E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
	1. Elevation (Snow whether DK,	, KKD, KI, GK, elc.)		
The state of the s				# # # # # # # # # # # # # # # # # # #
12. Check App	propriate Box to Indicate N	ature of Notice, R	Report or Other	Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORL				ALTERING CASING \(\begin{array}{c} \
		COMMENCE DRILL		P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN		JOB 🗌		
DOWNHOLE COMMINGLE				
OTHER:	•	OTHER: SQZ DF	RINKARD GAS PE	RFS
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
2-04-12: MIRU. REL PKRS. TIH TO SET PKR @ 25' +/ 2-06-12: TAG FILL @ 6616. DUMP 1000 LBS SAND DN PROD CSG.				
2-07-12: TIH W/WS & TAG TOP OF SAND @ 6566. DUMP 2 SX . TAG TOP OF SAND @ 6558. 2-08-12: TIH W/RBP & SET @				
6477. SET PKR @ 6314. 2-09-12: ACIDIZE SQUEEZED PERFS 6356-6420 W/1500 GALS 15 NEFE. TIH & RETR RBP. TIH W/5				
½" TBG. SET CICR @ 6306. 2-13-12: MIX & PUMP 41 BBLS CMT. SQZ TO 2500#. REV OUT W/BW. PUMP 30 SX @ 11.9 PPG W/2% CACL2, 30 PPS KOL-SEAL, 100 SX @ 14.8 PPG W/4/10% C-15. 2-14-12: TIH W/BIT TO TOP OF CMT @ 6265. DRILL				
OUT CMT, CICR. STOP DRILG @ 6336. PULL UP TO 6300'. 2-15-12: TAG CMT & DRILL 10' CIRC CUTTINGS UP.				
2-16-12: DRILL OUT TO 6500. TEST TO 350#. OK. PRESS UP TO 500# FOR 30 MINS. LOST 100# IN 1 MIN. HELD 400# FOR 30				
MINS. DRILL OUT CMT & SAND TO 6557. 2-17-12: TAG @ 6616. C/O OH TO 6628. 2-18-12: TIH W/WS. TAG @ 6546.				
DILL DN TO 6628. TAG FILL @ 6608. C/O TO 6628. 2-20-12: TAG FILL @ 6612. 16' FILL. 2-21-12: TIH W/PKR & SET @ 6472. 2-22-12: SET PKR @ 6472. EOT @ 657. ACIDIZE OPEN HOLE W/1500 GALS 15% HCL. REL PKR. 2-23-12: WELL ON				
VAC. REM 2 7/8" TBG FOR 2 3/8" TBG. TIH W/PKR TO SET @ 25' +/ 2-24-12: CIRC W/145 BBLS PKR FLUID. <u>SET PKR @</u>				
6463. 2-25-12: TOP OF CSG W/1.5 B		OR NMOCD. PRESS	3 TO 540 PSI FOR	30 MINS. (ORIGINAL
CHART & COPY OF CHART ATTAC	HED) KIG DOWN.			
<u> </u>				
Spud Date:	Rig Release Da	ite:		
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
2 miles of the state and and the state and complete to the obsect of my knowledge and oblice.				
SIGNATURE TITLE REGULATORY SPECIALIST DATE 03-09-2012				
Type or print name DENISE PINKER For State Use Only	TON E-mail address: <u>leak</u>	cejd@chevron.com	РНС	ONE: 432-687-7375
APPROVED BY: Wash (if any):	tale TITLE Con	·Plisuce Office	DA'	TE 03-16-2012

MAR 1 9 2012

